Eksploatacija ranjivosti, detekcija, i Incident Response izveštaj

Ime studenta: Anastasija Savić i Katarina Vučić

Datum: 30.11.2024.

Pregled Ranljivosti

1.1 Informacije o ranljivosti

ID ranljivosti (CVE): CVE 2014-3704

Pogođen servis: Drupal Core (verzije 7.x do 7.32)

CVSS ocena: 7.5 (visoko)

Opis ranljivosti: Ranjivost se odnosi na *SQL Injection* u Drupalovom jezgru verzije 7.x do 7.32. Problem se javlja zbog neodgovarajuće konstrukcije primenjenih upita u funkciji *expandArguments* u API-ju za rad sa bazom podataka. Napadač može da iskoristi ovu ranjivost koristeći specijalne zahteve i na taj način da omogući direktan upis bazi podataka. Ovo može da dovede do pristupa ili manipulacije podacima bez adekvatnih privilegija.

1.2 Opis eksploita

Izvor eksploita:

https://www.rapid7.com/db/modules/exploit/unix/webapp/drupal_drupalgeddon2/

Metod eksploatacije:

Napadač kreira specifičan unos sa login formu koji uključuje SQL komande. Npr. umjesto korisničkog imena može da unese nešto poput name[0;insert... kako bi direktno injektovao SQL komande u upit korišćen za autentifikaciju korisnika. SQL injekcija omogućava napadaču da izvrši komande koje modifikuju bazu podataka. Npr. napadač može da doda novi korisnički nalog sa pravima administratora (pomoću niza INSERT upita). Na taj način će koristiti akcije za koje mu ne bi trebale biti dostupne.

Proces Eksploatacije

2.1 Podešavanje eksploita

Ranjiv cilj:

Ciljna mašina koristi ranjivu verziju Drupal-a, koja omogućava eksploataciju *SQL Injection* ranjivosti poznate kao *Drupalgeddon2*.

Verzija servisa: Drupal Core 7.x do 7.32

Port: 80

Alati za eksploataciju:

Korišćen je Metasploit alat za detekciju i eksploataciju ranjivosti.

2.2 Koraci eksploatacije

Na *Slici 1* ispod vidimo komandu *search drupal* koja pretražuje dostupne eksploite za drupal ranjivost. Kasnije, koristeći *use* komandu, biramo koji ćemo exploit koristiti.

Slika 1

2.3 Rezultat eksploatacije

Prikažite rezultate eksploatacije:

Slika 2 prikazuje rezultat eksploatacije, koristeći komandu run.

```
msf6 exploit(unix/webapp/drupal_drupalgeddon2) > run

[*] Started reverse TCP handler on 10.0.2.15:4444

[*] Running automatic check ("set AutoCheck false" to disable)

[-] Exploit aborted due to failure: unknown: Cannot reliably check exploitability. "set ForceExploit true" to override c heck result.

[*] Exploit completed, but no session was created.
```

Slika 2

Nakon uspešno izvršenog eksploita moguće je pristupiti root-u pomoću komande *python -c 'import pty; pty.spawn("/bin/bash")'*, što i prikazuje *Slika 3*.

```
root@metasploitable3-ub1404:~# exit
msf6 exploit(unix/webapp/drupal_drupalgeddon2) > python -c 'import pty; pty.spawn("/bin/bash")'
[*] exec: python -c 'import pty; pty.spawn("/bin/bash")'
root@metasploitable3-ub1404:~# |
```

Slika 3

Detekcija Korišćenjem Wazuh SIEM-a

Za svaku eksploatisanu ranljivost:

3.1 Wazuh SIEM eravila

Pravila korišćena za detekciju:

(Navedite specifična Wazuh pravila koja su se aktivirala ili prilagodila za detekciju eksploita)

ID pravila:

(Uključite ID pravila i kratak opis)

3.2 Konfiguracija SIEM-a

Podešavanje Wazuh agenta:

(Opis konfiguracije agenta na ranjivoj mašini i kako je povezan sa Wazuh Managerom)

Agent se nalazi na istoj mašini kao i metasploitable3. Ta mašina je Ubuntu 14. U terminalu run-nujemo komande koje dobijemo nakon što deploy-ujemo agenta sa Wazuh servera. Komande su prilagođene mašini na kojoj će biti agent, ip adresi i nazivu manager-a. Nakon toga samo startujemo wazuh agenta - komanda sudo service wazuh-agent start. Takođe, možemo koristiti komande sudo service wazuh-agent restart i sudo service wazuh-agent stop za ponovno pokretanje i zaustavljanje wazuh agenta.

Prikupljanje logova:

(Navedite koje logove pratite da biste otkrili pokušaje eksploatacije)

Pokušaji eksploatacije se mogu vidjeti na *Slici 4*. Logovi nam prikazuju informacije o pokušaju ekspolatacije (koja eksploatacija je u pitanju, kada je pokušaj izveden, sa kog agenta i mašine itd. (pogledati *Sliku 4*). Takođe, isto važi i za pristupanje root-u.

3.3 Proces detekcije

Opišite proces detekcije:

Screenshot-ovi se nalaze ispod (Slike 4 i 5).

Incident Response sa The Hive-om

4.1 Podešavanje integracije


Opis integracije:

Wazuh i TheHive su povezani prateći tutorijal sa linka


https://wazuh.com/blog/using-wazuh-and-thehive-for-threat-protection-and-incident-response

Integracija pravila:


Nakon kreiranog alerta u Wazuh-u, pojavio se alert unutar TheHive-a. Na slikama ispod (*Slika 4, Slika 5, Slika 6, Slika 7*) nalaze se screenshot-ovi Wazuh i TheHive alata unutar alert sekcija.




Slika 4



Slika 5



Slika 6



Slika 7

4.2 Kreiranje slučaja u The Hive-u

Detalji o slučaju:

(Dajte screenshot-ove koji prikazuju kreirani slučaj u The Hive-u nakon što se Wazuh pravilo aktiviralo)