


CTU搬运场景

- 1.单层料架转运到多层料架
- 2.多层料架转运到单层料架
- 3.多层料架转运到输送线
- 4.输送线转运到多层料架

AGV搬运场景


- 1.普通库位搬运到CTU单/多层料架点
2. CTU单/多层料架点搬运到普通库位
3. CTU单/多层料架点换面任务



1.单层料架转运到多层料架

交互流程

请求示例




```
{
  "url": "http://10.157.10.10:8182/rcms/services/rest/hikRpcService/genAgvSchedulingTask",
  "request": {
    "agvCode": null,
    "taskCode": "2022032217254826673909e8dba86cf",
    "taskTyp": "CTU01",
    "ctnrTyp": "CTU",
    "ctnrCode": "100041",
    "wbCode": null,
    "positionCodePath": [
      {
        "positionCode": "CS-07-001-01",
        "type": "05"
      },
      {
        "positionCode": "CS-01-002-05",
        "type": "05"
      }
    ]
  },
  "podCode": "",
  "podDir": "",
  "podTyp": null,
  "materialLot": null,
  "priority": null,
  "data": "WMS_SHELF_MOVE_TASK",
  "reqCode": "25e9b9f922a44ebb8ad3df4a5955e74c",
  "reqTime": "2022-03-22 17:25:48",
  "clientCode": "MES-1-1",
  "tokenCode": null
},
{
  "response": {
    "code": "0",
    "message": "成功",
    "reqCode": "25e9b9f922a44ebb8ad3df4a5955e74c",
    "data": "2022032217254826673909e8dba86cf"
  }
}
```

2.多层料架转运到单层料架

交互流程


请求示例



```
{
  "url": "http://10.157.10.10:8182/rcms/services/rest/hikRpcService/genAgvSchedulingTask",
  "request": {
    "agvCode": null,
    "taskCode": "2022032217254826673909e8dba86cf",
    "taskTyp": "CTU02",
    "ctnrTyp": "CTU",
    "ctnrCode": "100041",
    "wbCode": null,
    "positionCodePath": [
      {
        "positionCode": "CS-01-002-05",
        "type": "05"
      },
      {
        "positionCode": "CS-07-001-01",
        "type": "05"
      }
    ],
    "podCode": "",
    "podDir": "",
    "podTyp": null,
    "materialLot": null,
    "priority": null,
    "data": "WMS_SHELF_MOVE_TASK",
    "reqCode": "25e9b9f922a44ebb8ad3df4a5955e74c",
    "reqTime": "2022-03-22 17:25:48",
    "clientCode": "MES-1-1",
    "tokenCode": null
  },
  "response": {
    "code": "0",
    "message": "成功",
    "reqCode": "25e9b9f922a44ebb8ad3df4a5955e74c",
    "data": "2022032217254826673909e8dba86cf"
  }
}
```

3.多层料架转运到输送线

交互流程




请求示例

```
{
  "url": "http://10.157.10.10:8182/rcms/services/rest/hikRpcService/genAgvSchedulingTask",
  "request": {
    "agvCode": null,
    "taskCode": "2022032217254826673909e8dba86cf",
    "taskTyp": "CTU03",
    "ctnrTyp": "CTU",
    "ctnrCode": "100041",
    "wbCode": "S01",
    "positionCodePath": [
      {
        "positionCode": "CS-01-002-05",
        "type": "05"
      },
      {
        "positionCode": "1-1",
        "type": "05"
      }
    ],
    "podCode": "",
    "podDir": "",
    "podTyp": null,
    "materialLot": null,
    "priority": null,
    "data": "WMS_SHELF_MOVE_TASK",
    "reqCode": "25e9b9f922a44ebb8ad3df4a5955e74c",
    "reqTime": "2022-03-22 17:25:48",
    "clientCode": "MES-1-1",
    "tokenCode": null
  },
  "response": {
    "code": "0",
    "message": "成功",
    "reqCode": "25e9b9f922a44ebb8ad3df4a5955e74c",
    "data": "2022032217254826673909e8dba86cf"
  }
}
```

4.输送线转运到多层料架

交互流程

请求示例




```
{
  "url": "http://10.157.10.10:8182/rcms/services/rest/hikRpcService/genAgvSchedulingTask",
  "request": {
    "agvCode": null,
    "taskCode": "2022032217254826673909e8dba86cf",
    "taskTyp": "CTU04",
    "ctnrTyp": "CTU",
    "ctnrCode": "100041",
    "wbCode": "S01",
    "positionCodePath": [
      {
        "positionCode": "1-2",
        "type": "05"
      },
      {
        "positionCode": "CS-01-002-05",
        "type": "05"
      }
    ],
    "podCode": "",
    "podDir": "",
    "podTyp": null,
    "materialLot": null,
    "priority": null,
    "data": "WMS_SHELF_MOVE_TASK",
    "reqCode": "25e9b9f922a44ebb8ad3df4a5955e74c",
    "reqTime": "2022-03-22 17:25:48",
    "clientCode": "MES-1-1",
    "tokenCode": null
  },
  "response": {
    "code": "0",
    "message": "成功",
    "reqCode": "25e9b9f922a44ebb8ad3df4a5955e74c",
    "data": "2022032217254826673909e8dba86cf"
  }
}
```

1.普通库位搬运到CTU单/多层料架点 --AGV普通任务

交互流程


请求示例



```
{
  "url": "http://10.157.10.10:8182/rcms/services/rest/hikRpcService/genAgvSchedulingTask",
  "request": {
    "agvCode": null,
    "taskCode": "2022032217254826673909e8dba86cf",
    "taskTyp": "AGV02",
    "ctnrTyp": "",
    "ctnrCode": "",
    "wbCode": null,
    "positionCodePath": [
      {
        "positionCode": "LOC-05",
        "type": "00"
      },
      {
        "positionCode": "CS-01",
        "type": "00"
      }
    ],
    "podCode": "410046",
    "podDir": "",
    "podTyp": null,
    "materialLot": null,
    "priority": null,
    "data": "WMS_SHELF_MOVE_TASK",
    "reqCode": "25e9b9f922a44ebb8ad3df4a5955e74c",
    "reqTime": "2022-03-22 17:25:48",
    "clientCode": "MES-1-1",
    "tokenCode": null
  },
  "response": {
    "code": "0",
    "message": "成功",
    "reqCode": "25e9b9f922a44ebb8ad3df4a5955e74c",
    "data": "2022032217254826673909e8dba86cf"
  }
}
```

2. CTU单/多层料架点搬运到普通库位 --AGV普通任务

交互流程




请求示例

```
{
  "url": "http://10.157.10.10:8182/rcms/services/rest/hikRpcService/genAgvSchedulingTask",
  "request": {
    "agvCode": null,
    "taskCode": "2022032217254826673909e8dba86cf",
    "taskTyp": "AGV03",
    "ctnrTyp": "",
    "ctnrCode": "",
    "wbCode": null,
    "positionCodePath": [
      {
        "positionCode": "410046",
        "type": "03"
      },
      {
        "positionCode": "LOC-02",
        "type": "00"
      }
    ],
    "podCode": "410046",
    "podDir": "",
    "podTyp": null,
    "materialLot": null,
    "priority": null,
    "data": "WMS_SHELF_MOVE_TASK",
    "reqCode": "25e9b9f922a44ebb8ad3df4a5955e74c",
    "reqTime": "2022-03-22 17:25:48",
    "clientCode": "MES-1-1",
    "tokenCode": null
  },
  "response": {
    "code": "0",
    "message": "成功",
    "reqCode": "25e9b9f922a44ebb8ad3df4a5955e74c",
    "data": "2022032217254826673909e8dba86cf"
  }
}
```

3. CTU单/多层料架点换面任务 --AGV换面任务

交互流程

请求示例



```
{
  "url": "http://10.157.10.10:8182/rcms/services/rest/hikRpcService/genAgvSchedulingTask",
  "request": {
    "agvCode": null,
    "taskCode": "2022032217254826673909e8dba86cf",
    "taskTyp": "AGV01",
    "ctnrTyp": "",
    "ctnrCode": "",
    "wbCode": null,
    "positionCodePath": [
      {
        "positionCode": "410046",
        "type": "03"
      }
    ],
    "podCode": "410046",
    "podDir": "",
    "podTyp": null,
    "materialLot": null,
    "priority": null,
    "data": "WMS_SHELF_MOVE_TASK",
    "reqCode": "25e9b9f922a44ebb8ad3df4a5955e74c",
    "reqTime": "2022-03-22 17:25:48",
    "clientCode": "MES-1-1",
    "tokenCode": null
  },
  "response": {
    "code": "0",
    "message": "成功",
    "reqCode": "25e9b9f922a44ebb8ad3df4a5955e74c",
    "data": "2022032217254826673909e8dba86cf"
  }
}
```