Cynbit Technologies

Quality Assurance (QA) Audit Report

Candidate Name	Kapil Gulbani
Target Role	QA Testing Intern
Target URL	https://cynbit.in
Testing Date	October 2026

Executive Summary

This report presents a Quality Assurance audit, functional testing and usability analysis of the official Cynbit Technologies web platform (cynbit.in). The scope covered input validation, cross-page redirection checks, mobile viewport responsiveness and frontend console performance metrics. Six issues were logged: **3 High**, **2 Medium** and **1 Low** severity. All are currently Open.

Test Environment and Setup

Browser	Google Chrome (latest version) with DevTools
Testing Scope	Contact Us, Careers, Core Team pages and mobile responsive viewports
Methodology	Exploratory Testing, Boundary Value Analysis, Negative Testing, UI/UX Auditing
Mobile Viewport	Chrome DevTools Device Toolbar, Responsive mode (400 x 642)

Bug Audit and Tracking Log

Bug ID	Module / Page	Description	Severity	Priority	Status	Evidence
BUG-001	Contact Form (/contact)	Full Name field lacks character-type validation (accepts numeric values like Kapil123).	**Medium**	P2	Open	Fig. 1
BUG-002	Contact Form (/contact)	Email field accepts kapil@gmail (no .com) on the client side; submit then fails with a generic error that names no field.	**High**	P1	Open	Fig. 2
BUG-003	Careers (/careers)	"View Details" buttons show high click latency and intermittent unresponsiveness.	**High**	P1	Open	Fig. 3
BUG-004	Careers (/careers)	"DROP A PORTFOLIO" CTA redirects to generic Contact page instead of a portfolio upload.	**Medium**	P2	Open	Fig. 4
BUG-005	Mobile View Layout	Fixed bottom navigation bar overlaps and hides interactive buttons (e.g. "VIEW DETAILS").	**High**	P1	Open	Fig. 5
BUG-006	Global / Console	DevTools warnings: unused preloaded CSS and missing explicit image dimensions.	**Low**	P3	Open	Fig. 6, 7

Detailed Bug Findings and Evidence

1. BUG-001: Missing Character Validation in Full Name Field

Severity: Medium | **Priority:** P2

Description: The Full Name input accepts alphanumeric strings and numbers without showing any validation error.

Steps to Reproduce:

1. Navigate to https://cynbit.in/contact.
2. Locate the **Full Name** input field.
3. Enter numeric or mixed characters (e.g. *Kapil123*).

Expected Result: The system should restrict numeric input or show a validation error ("Alphabets only").
Actual Result: The field accepts numbers without any restriction.




Figure 1: Contact form accepting "Kapil123" in the Full Name field with no validation error.

2. BUG-002: Incomplete Email Format Validation and Unclear Error Message

Severity: High | **Priority:** P1

Description: The email input accepts an incomplete address that lacks a top-level domain (TLD) extension. The browser lets the form be submitted, and the page then shows a generic error that does not tell the user which field caused the problem.

Steps to Reproduce:

1. Navigate to https://cynbit.in/contact.
2. Enter an incomplete email string (e.g. *kapil@gmail* without .com) and fill in the message.
3. Click **SEND INQUIRY**.

Expected Result: The email field should be flagged as invalid on the client side because the domain extension is missing, with a clear field-level message.
Actual Result: No client-side error appears and the form is submitted. The page then shows "SOMETHING WENT WRONG. PLEASE TRY AGAIN OR EMAIL US DIRECTLY.", which does not say what is wrong.

Note: The generic message does not identify the failing field, so users cannot tell whether the email, the message or the server is at fault. The same screenshot also shows the numeric Full Name value (BUG-001) being accepted.




Figure 2: Contact form with "kapil@gmail" accepted in the Email field; submission ends with a generic error message.

3. BUG-003: "View Details" Button Latency / Unresponsiveness

Severity: High | **Priority:** P1

Description: The "VIEW DETAILS" buttons on internship cards experience high click latency and intermittent unresponsiveness.

Steps to Reproduce:

1. Open https://cynbit.in/careers.
2. Scroll to the **Internship Openings** section.
3. Click the "VIEW DETAILS" buttons on different cards and observe the response time.

Expected Result: Each button should respond immediately and open the role details.
Actual Result: Buttons respond slowly or intermittently do not respond.

Note: This screenshot shows the affected buttons, but latency cannot be captured in a still image. A screen recording or a Network / Performance tab capture would strengthen this evidence.




Figure 3: Careers page, Internship Openings cards with "VIEW DETAILS" buttons (the status bar shows the target link on hover).

4. BUG-004: Misleading CTA Redirection

Severity: Medium | **Priority:** P2

Description: Clicking "DROP A PORTFOLIO" on the Careers page routes the user to the generic Contact Us page instead of a dedicated portfolio upload interface.

Steps to Reproduce:

1. Visit https://cynbit.in/careers.
2. Scroll to the section *"Don't See Your Role?"*.
3. Click **"DROP A PORTFOLIO"**.

Expected Result: A targeted resume / portfolio upload interface should open.
Actual Result: The user is redirected to /contact.




Figure 4: "Don't See Your Role?" section showing the "DROP A PORTFOLIO" CTA on /careers.

5. BUG-005: Mobile Bottom Navigation Overlap

Severity: High | **Priority:** P1

Description: On mobile viewports, the fixed bottom navigation bar overlaps and cuts off interactive elements such as the "VIEW DETAILS" button on internship cards.

Steps to Reproduce:

1. Open https://cynbit.in/careers and toggle mobile view (F12 > Device Toolbar).
2. Scroll through the internship cards and observe the bottom layout.

Expected Result: Responsive containers should adjust cleanly, with no floating bar obstructing interactive controls.
Actual Result: The bottom navbar overlaps card contents and buttons (the QA Testing Intern card's button is cut off).




Figure 5: Mobile view (400 x 642): the bottom navigation bar covers the "VIEW DETAILS" button of the QA Testing Intern card.

6. BUG-006: Console Warnings and Missing Image Dimensions

Severity: Low | **Priority:** P3

Description: Chrome DevTools reports warnings for a CSS file that is preloaded but not used within a few seconds of load, plus an issue for lazy-loaded images without explicit dimensions. A deprecated-parameters warning from feature_collector.js is also logged.

Steps to Reproduce:

1. Open https://cynbit.in/careers with DevTools open (F12).
2. Go to the **Console** and **Issues** tabs and reload the page.

Expected Result: The console should be free of warnings; preloaded resources should be used, and images should declare width and height.
Actual Result: Repeated "resource was preloaded but not used" warnings for a _next/static/css file, and "Lazy-loaded images should have explicit dimensions" in Issues.




Figure 6: Console warnings (preloaded CSS not used) and Issues tab showing the lazy-loaded image dimensions issue (cropped from the mobile-view screenshot).




Figure 7: Console showing a deprecated-parameters warning (feature_collector.js:23) on the Careers page.

Additional Test Coverage

The Core Team page (/team) was also reviewed as part of the testing scope. Its closing section with the "START A CONVERSATION" and "VIEW OPENINGS" calls to action rendered correctly and no defects were logged for this page.




Figure 8: Core Team page (/team), closing section with CTAs. No defects observed.

Recommendations for Improvement

1. **Strict input sanitization:** apply front-end regex checks for names (`^[A-Za-z\s]+$`) and for email TLD structure.
2. **Responsive CSS refactoring:** adjust viewport padding and stacking order (z-index) so the bottom navigation bar does not overlap interactive CTAs on mobile layouts.
3. **Dedicated application portals:** implement an inline file upload dialog for portfolio submissions instead of redirecting to the generic Contact page.
4. **Performance hygiene:** remove or correctly apply unused preloaded CSS, set explicit width and height on lazy-loaded images, and investigate click-handler latency on the Careers cards.

Appendix: Screenshot Evidence Index

Figure	File	Page	Linked Bug
Fig. 1	Screenshot_2026-10-29_171139.png	/contact	BUG-001
Fig. 2	Screenshot_2026-10-29_175119.png	/contact (after submit)	BUG-002
Fig. 3	Screenshot_2026-10-29_171815.png	/careers (desktop)	BUG-003
Fig. 4	Screenshot_2026-10-29_172251.png	/careers (desktop)	BUG-004
Fig. 5	Screenshot_2026-10-29_173515.png	/careers (mobile 400 x 642)	BUG-005
Fig. 6	Screenshot_2026-10-29_173515.png (cropped)	/careers (mobile + DevTools)	BUG-006
Fig. 7	Screenshot_2026-10-29_173002.png	/careers (DevTools console)	BUG-006
Fig. 8	Screenshot_2026-10-29_172544.png	/team	No bug (coverage)