IDENTIFYING MALWARE ATTACKS USING WIRESHARK

Overview:

Qakbot is an information stealer also known as Qbot. This family of malware has been active for years, and Qakbot generates distinct traffic patterns. This Wireshark tutorial reviews a recent packet capture (pcap) from a Qakbot infection. Understanding these traffic patterns can be critical for security professionals when detecting and investigating Qakbot infections.

Note: This tutorial assumes you have a basic knowledge of network traffic and Wireshark. We use a customized column display shown in this tutorial. You should also have experience with Wireshark display filters as described in this additional tutorial.

Please also note that the pcap used for this tutorial contains malware. You should review this pcap in a non-Windows environment. If you are limited to a Windows computer, we suggest reviewing the pcap within a virtual machine (VM) running any of the popular recent Linux distros.

This tutorial will cover the following:

- Qakbot distribution methods
- Initial zip archive from link in an malspam
- Windows executable for Qakbot
- Post-infection HTTPS activity
- Other post-infection traffic




Figure 1. The pcap for this tutorial.

Qakbot Distribution Methods:

Qakbot is most often distributed through malicious spam (malspam), but it also has been distributed through exploit kits as recently as November 2019. In some cases, Qakbot is a follow-up infection caused by different malware like Emotet as reported in this example from March 2019.

Recent malspam-based distribution campaigns for Qakbot follow a chain of events shown in Figure 2.




Figure 2. Flow chart from recent Qakbot distribution campaigns.

Initial Zip Archive from Link in Malspam

Recent malspam distributing Qakbot uses fake email chains that spoof legitimate email addresses. One such example is shown in Figure 3.




Figure 3. Recent malspam example pushing Qakbot.

URLs from these emails end with a short series of numbers followed by *.zip*. See Table 1 for a few examples of URLs from Qakbot malspam recently reported on URLhaus and Twitter.

First reported	URL for initial zip archive
2019-12-27	hxxps://prajoon.000webhostapp[.]com/wp-content/uploads/2019/12/last/033/033.zip
2019-12-27	hxxps://psi-uae[.]com/wp-content/uploads/2019/12/last/870853.zip
2019-12-27	hxxps://re365[.]com/wp-content/uploads/2019/12/last/85944289/85944289.zip
2019-12-27	hxxps://liputanforex.web[.]id/wp-content/uploads/2019/12/last/794/794.zip

2020-01-06	hxxp://eps.icothanglong.edu[.]vn/forward/13078.zip
2020-01-22	hxxp://hitechrobo[.]com/wp-content/uploads/2020/01/ahead/84296848/84296848.zip
2020-01-22	hxxp://faithoasis.000webhostapp.com/wp-content/uploads/2020/01/ahead/550889.zip
2020-01-27	hxxps://madisonclubbar[.]com/fast/invoice049740.zip
2020-01-29	hxxp://zhinengbao[.]wang/wp-content/uploads/2020/01/lane/00571.zip
2020-01-29	hxxp://bhatner[.]com/wp-content/uploads/2020/01/ahead/9312.zip
2020-02-03	hxxp://santedeplus[.]info/wp-content/uploads/2020/02/ending/1582820/1582820.zip

Table 1. URLs for the initial zip archive to kick off a Qakbot infection chain.

In our pcap, you can find the HTTP request for a zip archive using *http.request.uri contains .zip* in the Wireshark filter as shown in Figure 4.




Figure 4. Finding the URL for the initial zip archive.

Follow the TCP stream to confirm this is a zip archive as shown in Figure 5 and Figure 6, then try to export the zip archive from the pcap as shown in Figure 7.





Figure 5. Following the TCP stream for the HTTP request from our filter results.



6. Indicators this URL returned a zip archive

Figure




Figure 7. Exporting objects from HTTP traffic in the pcap.

In most cases, the menu for $File \rightarrow Export\ Objects \rightarrow HTTP$ should export a zip archive sent over HTTP. Unfortunately, as shown in Figure 8, we cannot export this file named 9312.zip because it is separated into hundreds of smaller parts within the export HTTP objects list.




Figure 8. 9312.zip is broken up into hundreds of objects within the list, so we cannot export it this way.

Fortunately, we can export data from a TCP stream window and edit the binary in a hex editor to remove any hxxP response headers. Use the following steps to extract the zip archive from this pcap:

- 1. Follow TCP stream for the HTTP request for 9312.zip.
- 2. Show only the response traffic in the TCP stream Window.
- 3. Change "Show and save data as" from ASCII to Raw.
- 4. Save the data as a binary (I chose to save it as: 9312.zip.bin)
- 5. Open the binary in a hex editor and remove the HTTP request headers before the first two bytes of the zip archive (which show as PK in ASCII).
- 6. Save the file as a zip archive (I chose to save it as 9312.zip)
- 7. Check the file to make sure it's a zip archive.

See Figures 9 through 14 for a visual guide of this process.



Figure 9. Step 2 – When viewing the TCP stream, switch from viewing the entire conversation to viewing only data returned from the server.



Figure 10. Step 3 – Show and save data as Raw instead of ASCII.




Figure 11. Step 4 – Save this raw data from the TCP stream as a binary.




Figure 12. Step 5 – Open your saved binary in a hex editor and remove any HTTP response data before the first two bytes of the zip archive (that show as PK in ASCII).




Figure 13. Step 6 – Save your edited binary as a zip archive.




Figure 14. Step 7 – Confirm the edited file is a zip archive, then extract the VBS file and check the file hashes.

Figure 14 shows how to use a terminal window from a Debian-based Linux distro to check the files. From our pcap, the zip archive should be the same as this file submitted to VirusTotal. Our extracted VBS file should be the same as this file also submitted to VirusTotal.

A public sandbox analysis of our extracted VBS file indicates it generates the next Qakbot-related URL in our infection chain: a URL that returned a Windows executable for Qakbot.

Windows Executable for Qakbot

These extracted VBS files generate URLs that return Windows executables for Qakbot. Since December 2019, URLs for Qakbot executables have ended with 44444.png or 444444.png. See Table 2 for some recent examples of these Qakbot URLs we found using our AutoFocus Threat Intelligence service.

First Seen	URL for Qakbot executable
2019-12-27	hxxp://centre-de-conduite-roannais[.]com/wp-content/uploads/2019/12/last/444444.png
2020-01-06	hxxp://newsinside[.]info/wp-content/uploads/2020/01/forward/44444.png
2020-01-15	hxxp://iike.xolva[.]com/wp-content/themes/keenshot/fast/444444.png
2020-01-17	hxxp://deccolab[.]com/fast/444444.png
2020-01-21	hxxp://myrestaurant.coupoly[.]com/wp-content/uploads/2020/01/along/444444.png
2020-01-22	hxxp://alphaenergyeng[.]com/wp-content/uploads/2020/01/ahead/444444.png
2020-01-23	hxxp://claramohammedschoolstl[.]org/wp-content/uploads/2020/01/upwards/444444.png
2020-01-23	hxxp://creationzerodechet[.]com/choice/444444.png
2020-01-26	hxxp://productsphotostudio[.]com/wp-content/uploads/2020/01/lane/444444.png
2020-01-27	hxxp://sophistproduction[.]com/wp-content/uploads/2020/01/choice/444444.png
2020-01-30	hxxp://uofnpress[.]ch/wp-content/uploads/2020/01/side/444444.png
2020-02-03	hxxp://csrkanjiza[.]rs/wp-content/uploads/2020/02/ending/444444.png
	·

Table 2. URLs for Qakbot executables.

In our pcap, find the HTTP GET request for our Qakbot executable using *hxxp.request.uri contains.png* in the Wireshark filter as shown in Figure 15.




Figure 15. Finding the URL for our Qakbot executable.

Export this object from the pcap using the *File* \rightarrow *Export Objects* \rightarrow *HTTP* menu path as shown in Figure 16 and check the results as shown in Figure 17.




Figure 16. Exporting our Qakbot executable from the pcap.

Figure 17. Checking the exported file in a Debian-based Linux terminal window.

From our pcap, the Qakbot executable should be this file submitted to VirusTotal. A public sandbox analysis of this file generated several Qakbot indicators (identified as Qbot).

Post-infection HTTPS Activity

Use your basic filter (covered in this previous WIreshark tutorial) for a quick view of web traffic in our pcap. Scroll down to activity after the HTTP GET request to alphaenergyeng[.]com that returned our Qakbot executable. You should see several indicators of HTTPS or SSL/TLS traffic to 68.1.115[.]106 with no associated domain as noted in Figure 18.

	202	20-01-29-Qb	ot-infection-traffic.pcap	◆ - B :
<u>File Edit View Go Ca</u>	pture Analyze Statist	ics Telep	hon <u>y W</u> ireless <u>T</u> ools <u>H</u> elp	
	X 6 6 6 3		QQQ	
(http.request or ssl.har	ndshake.type == 1) and	d !(ssdp)	Expression.	+ basic basic+ basic+DNS
Time	Dst	Dst port	Host	Info
2020-01-29 15:42	2 5.61.27.159	80	alphaenergyeng.com	GET /wp-content/uploa
2020-01-29 15:48	3 204.79.197.200	443	www.bing.com	Client Hello
2020-01-29 15:48	3 204.79.197.222	443	fp.msedge.net	Client Hello
	3 13.107.42.254	443	1-ring.msedge.net	Client Hello
	3 104.114.164.71	443	ow1.res.office365.com	Client Hello
	3 <u>13.107.246.10</u>	443	pti.store.microsoft.com	Client Hello
	9 68.1.115.106	443		Client Hello
	9 68.1.115.106	443		Client Hello
Dakhot	9 68.1.115.106	443		Client Hello
	9 68.1.115.106	443		Client Hello
2020-01 29 15 5	68.1.115.106	443		Client Hello
2020-01-19 15:50		443		Client Hello
2020-01-29 15:50		443		Client Hello
2020-01-29 1:50		443		Client Hello
2020-01-29 15.50		443	fe2cr.update.microsoft.c	Client Hello
2020-01-29 15:	65.52.108.90	443	fe3cr.delivery.mp.micros	
2020-01-29 15:53		443		Client Hello
2020-01-29 15:5:		443		Client Hello
2020-01-29 15:52		443		Client Hello
2020-01-29 15:52		443		Client Hello
2020-01-29 15:54	4 68.1.115.106	443		Client Hello

Figure 18. HTTPS or SSL/TLS traffic caused by Qakbot.

This traffic has unusual certificate issuer data commonly noted during Qakbot infections. We reviewed unusual certificate issuer data in our previous WIreshark tutorial about Ursnif, so this should be easy to find.

Let's review our Qakbot certificate issuer data using the following Wireshark filter:

Ip.addr eg 68.1.115.186 and ssl.handshake.type eg 11

For Wireshark 3.0 or newer, use *tls.handshake.type* instead of *ssl.handshake.type*. Select the first frame in your results and expand the frame details window until you find the certificate issuer data as shown in Figure 19.




Figure 19. Reviewing certificate issuer data from Qakbot traffic.

Patterns for the locality name, organization name, and common name are highly-unusual, not normally found in certificates from legitimate HTTPS, SSL, or TLS traffic. Our example of this issuer data is listed below:

- id-at-countryName=**ES**
- id-at-stateOrProvinceName=IA
- id-at-localityName=Uorh Ofwa
- id-at-organizationName=Coejdut Mavmtko Qxyemk Dxsjie LLC.
- id-at-commonName=gaevietovp.mobi

Other Post-infection Traffic

Our pcap contains other activity associated with a Qakbot infection. Each activity is not inherently malicious on its own, but taken together with our previous findings, we can assume a full Qakbot infection.

Another indicator of a Qakbot infection is HTTPS traffic to cdn.speedof[.]me. The domain speedof[.]me is used by a legitimate Internet speed test service. Although this is not malicious traffic, we frequently see traffic to cdn.speedof[.]me during Qakbot infections. Figure 20 shows this activity from our pcap.




Figure 20. The domain cdn.speedof[.]me within the Qakbot traffic.

Qakbot also opens windows from all browsers on an infected Windows host. At approximately 13 minutes and 5 seconds into this sandbox analysis, the video playback shows Qakbot opening Chrome, then Firefox, then Internet Explorer on a Windows 7 host. This analysis shows Qakbot generated traffic to the following URLs:

- hxxp://store.nvprivateoffice[.]com/redir_chrome.html
- hxxp://store.nvprivateoffice[.]com/redir_ff.html
- hxxp://store.nvprivateoffice[.]com/redir_ie.html

The domain nvprivateoffice[.]com has been registered through GoDaddy since 2012, and store.nvprivateoffice[.]com shows a default web page for nginx on a Fedora server.

Our pcap for this tutorial is from a Qakbot infection on a Windows 10 host without Chrome or Firefox installed. Our pcap only shows web traffic for Internet Explorer and the new Chromium-based Microsoft Edge. Both times,

the URL generated by Qakbot was hxxp://store.nvprivateoffice[.]com/redir_ie.html.

To find this traffic, use the following Wireshark filter as shown in Figure 21:

http.request.full_uri contains store.nvprivateoffice

		<u>A</u> nalyze <u>S</u> tatisti	cs Telep	hony <u>W</u> ireless	Tools Help			(↑ □ □ ×
		a		Q	Q Q II			
p.request.ful	_uri contains	store.nvprivateof	fice.com	× ×	Expression	+ basic	basic+	basic+DNS
	Dst		Dst port	Host		Infe)	
020-01-29	15:56 89.	105.198.119	80	store.nvpr	ivateoffice	.com GE	T /redi	r_ie.html
920-01-29	15:56 89.	105.198.119	80	store.nvpr	ivateoffice	.com GE	T /favi	con.ico HT
920-01-29	15:56 89.	105.198.119	80	store.nvpr	ivateoffice	.com GE	T /redi	r_ie.html
020-01-29	15:56 89.	105.198.119	80	store.nvpr	ivateoffice	.com GE	T /favi	con.ico HT
								· ·
	p.request.ful 920-01-29 920-01-29 920-01-29	p.request.full_uri contains : Dst 020-01-29 15:56 89. 020-01-29 15:56 89. 020-01-29 15:56 89.	Dst 020-01-29 15:56 89.105.198.119 020-01-29 15:56 89.105.198.119 020-01-29 15:56 89.105.198.119 020-01-29 15:56 89.105.198.119	p.request.full_uri contains store.nvprivateoffice.com	p.request.full_uri contains store.nvprivateoffice.com Dst Dst port Host 220-01-29 15:56 89.105.198.119 80 store.nvpr 220-01-29 15:56 89.105.198.119 80 store.nvpr 220-01-29 15:56 89.105.198.119 80 store.nvpr 220-01-29 15:56 89.105.198.119 80 store.nvpr	Dst Dst port Host store.nvprivateoffice 220-01-29 15:56 89.105.198.119 80 store.nvprivateoffice 220-01-29 15:56 89.105.198.119 80 store.nvprivateoffice 320-01-29 15:56 89.105.198.119 80 store.nvprivateoffice	Dst	Dst

Figure 21. Finding Qakbot traffic that opens web browsers on an infected Windows host.

Follow the TCP stream for each of the two HTTP GET requests ending in redir_ie.html. The first request has a User-Agent in the HTTP headers for Internet Explorer as shown in Figure 22. The second request for the same URL has a User-Agent in the HTTP headers for the new Chromium-based Microsoft Edge as noted in Figure 23.




Figure 22. Qakbot traffic to store.nvprivateoffice[.]com using Internet Explorer 11.




Figure 23. Qakbot traffic to store.nvprivateoffice[.]com using the new Chromium-based Microsoft Edge.

Finally, our pcap from the Qakbot-infected host also has email-related TCP traffic to various ports for various email protocols like SMTP, IMAP, and POP3. To get an idea of this non-web-related traffic, use the following Wireshark filter as shown in Figure 25:

tcp.flags eq 0x0002 and !(tcp.port eq 80) and !(tcp.port eq 443)




Figure 25. Getting an idea of the non-web-related traffic from this Qakbot infection.

Figure 25 shows TCP connections and attempted TCP connections to various ports like 25, 110,143, 465, 587, 993, and 995 commonly used by different email protocols. The first two lines in the results show traffic to TCP port 65400, but reviewing the associated TCP streams indicates this also email-related traffic.

Use the following Wireshark filter to get a better idea of email-related traffic from the infected host as shown in Figure 26:

smtp or imap or pop




Figure 26. Finding email-related traffic caused by Qakbot in this pcap.

Follow some of the TCP streams to get a better idea for this type of email traffic. We do not normally see such unencrypted email traffic originating from a Windows client to public IP addresses. Along with other indicators, this *smtp or imap or pop* filter may reveal Qakbot activity.