


COPV irreversible-damage localization on published BAM sensor geometry (180 kHz)

(A) per-PZT damage involvement [R]
(true 5x5 ring x circumference)



(B) RAPID damage image on TRUE unrolled cylinder [R]
peak arc=0mm axial=1293mm

