


Restoration design: the crown HEIGHT (moment arm) drives peri-implant bone stress, not the crown material

(A) crown HEIGHT dominates ($\times 1.9$ over $0 \rightarrow 10$ mm)



(B) crown MATERIAL is secondary ($< 2\%$ over $21\times$)

