VMMarketplaceInvalidInput_ACG

Last updated by | David Goebel | May 19, 2022 at 11:02 AM PDT



Contents

- Scenario
- In ASC
- Mitigation Options
- Root Cause:RCA
- Related Articles
- Need additional help or have feedback?

Scenario

Customer is trying to deploy a VM from a shared image gallery image and receives the following error:

OR


Error Code: Conflict
Message:The resource with id '/subscriptions/<<SUBSID>>/resourceGroups/<<RGNAME>>/providers/Microsoft.Comp

This can happen when the customer creates an image in SIG from a Marketplace image that requires Purchase Plan information.


NOTE: This is a <u>generic deployment error</u> \square that can occur outside of SIG as well, such as when a customer is using a regular managed image to deploy a VM. This TSG is <u>specifically</u> covering the scenario where the customer is experiencing the issue when using an image housed inside a Shared Image Gallery (SIG).

In ASC

Under the CRP operations we can see the error for the deployment:



You can click on the QOS Jarvis link to view the CRP ApiQosEvent logs. Scroll over to the **requestEntity** column to view the template that was submitted to CRP. We can scroll down to the "imageReference" property to confirm this is an image in a shared image gallery:



Mitigation Options

- use json template and specify **purchase plan** information (This is different from the SIG Image Definition Publisher, Offer, SKU)
 - "purchasePlan": { "product": "[parameters('productName')]", "name": "[parameters('planName')]", "publisher": "[parameters('planPublisherName')]"}

```
variables": {},
"resources": [
        "type": "Microsoft.Compute/galleries/images",
"name": "[concat(parameters('galleryName'), '/', parameters('imageDefinitionName'))]",
        "apiVersion": "2019-07-01",
        "location": "[parameters('location')]",
         "properties": {
    "osType": "[parameters('osType')]",
             "osState": "[parameters('osState')]",
             "identifier": {
                  "publisher": "[parameters('publisher')]",
                  "offer": "[parameters('offer')]",
                  "sku": "[parameters('sku')]'
              "recommended": {
                  "vCPUs": {
                      "min": "[parameters('minRecommendedvCPUs')]",
                       "max": "[parameters('maxRecommendedvCPUs')]"
                      "min": "[parameters('minRecommendedMemory')]",
                       "max": "[parameters('maxRecommendedMemory')]"
             "hyperVGeneration": "[parameters('hyperVGeneration')]",
              "purchasePlan": {
                  "product": "[parameters('productName')]",
                 "name": "[parameters('planName')]",
"publisher": "[parameters('planPublisherName')]"
         "tags": {}
```

- re-create shared image gallery image definition specifying <u>purchase plan information</u> (update not supported)

Root Cause: RCA

Plan incorrectly specified or missing in deployment

• First Party images do not require plan information, but Third Party images do

Related Articles

How to Find Plan Information from a Failed VM Deployment

Need additional help or have feedback?

3/24/23, 2:49 PIVI	v www.arketpiaceinvalidinput_ACG - Overview	
To enage the Azure Compute Gallery SMEs	To provide feedback on this page	To provide kudos on this page
Please reach out to the Azure Compute Gallery SMEs AVA channel via Teams.	Use the Azure Compute Gallery Feedback form to submit detailed feedback on improvements or new content ideas for Azure Compute Gallery.	Use the Azure Compute Gallery Kudos form to submit kudos on the page. Kudos will help us improve our wiki content overall!
Make sure to use the Ava process for faster assistance.	Please note the link to the page is required when submitting feedback on existing pages! If it is a new content idea, please put N/A in the Wiki Page Link.	Please note the link to the page is required when submitting kudos!