

WEBSITE AUDIT REPORT · CONFIDENTIAL

# Nature's Village Resort

Full-site UX, design, accessibility, SEO, performance, and technical audit

Live-site audit, cross-referenced against the project source repository

**Audited URL:** <https://teal-raven-684541.hostingersite.com/>

**Canonical / production domain referenced in source:** <https://naturesvillageresort.com/>

**Audit date:** September 16, 2026

**Pages inspected:** 9 primary pages, 1 custom 404 page, 1 internal credits page (/dev/)

**Method:** Live browser automation (Chromium) against the published site — navigation, console/network capture, viewport resizing at 320/375/414/768/1024/1280/1440px, DOM/CSSOM/computed-style inspection, response-header inspection — cross-checked against the local project files available in this environment

**Prepared for:** Site owner / stakeholders

# Table of Contents

---

|    |                                                |
|----|------------------------------------------------|
| 01 | Cover page                                     |
| 02 | Executive summary                              |
| 03 | Scope, methodology, and limitations            |
| 04 | Website inventory                              |
| 05 | Key user journeys                              |
| 06 | Overall scorecard                              |
| 07 | UX and information architecture findings       |
| 08 | Visual design findings                         |
| 09 | Responsive design findings                     |
| 10 | Functional and interaction findings            |
| 11 | Accessibility findings                         |
| 12 | SEO findings                                   |
| 13 | Performance findings                           |
| 14 | Content and conversion findings                |
| 15 | Technical architecture findings                |
| 16 | Security and privacy observations              |
| 17 | Prioritized issue register                     |
| 18 | Quick wins                                     |
| 19 | 30 / 60 / 90-day improvement roadmap           |
| 20 | Recommended design system                      |
| 21 | Recommended technical improvements             |
| 22 | QA regression checklist                        |
| 23 | Top 10 action list                             |
| 24 | Appendix — URLs, evidence, and test conditions |

## 2. Executive Summary

### What this site is

Nature's Village Resort is a mid-size regenerative-hospitality resort in Talisay City, Negros Occidental, Philippines, offering rooms, function/event venues, a farm-to-table restaurant, and organic-farm/pool facilities. The site's purpose is to build trust with two audiences — **leisure guests** booking a stay and **event organizers** (weddings, retreats, corporate functions) booking a venue — and to convert both into either a direct booking-engine reservation or an inquiry through the contact/events forms. A secondary audience is press/media, served by a dedicated Press Room.

### Primary user journeys observed

- **Book a stay:** Home → Accommodations (browse room cards, open a detail modal) → "Reserve Your Stay" / "Check Availability" → external STAAH booking engine.
- **Plan an event:** Home → Function Rooms → browse venue cards → inquiry via the on-page events form or the booking engine.
- **Research before booking:** Reviews widget on the homepage → Testimonials → Press Room (awards/certifications) → Contact.
- **Get in touch directly:** Any page → Contact → form, phone, or map.

### Overall condition

This is a well-engineered, carefully designed site, not a rough or unfinished one. Zero broken images, zero missing alt text, zero horizontal-overflow layout breaks were found across every page and viewport width tested, and the codebase carries a documented internal audit history showing real, verified fix cycles (form success-state bugs, CSP fixes, an accessibility pass, a hero-video re-encode). This audit independently re-tested the *live, publicly reachable* site — not just the source files — and confirms most of that work is genuinely live in production. It also surfaces several issues not previously documented, the most notable being a stale-asset bug on the internal credits page and an SEO/indexing gap specific to this staging hostname.

### Strongest aspects

- A token-driven CSS design system (documented custom properties for color, spacing, radii, shadows) that renders consistently across nine templates.
- A genuinely strong HTTP security posture: a specific, allowlisted Content-Security-Policy, HSTS with `includeSubDomains`, `X-Content-Type-Options`, `X-Frame-Options`, and a restrictive Permissions-Policy — all confirmed on live response headers.
- Rich, correct structured data (schema.org `Resort` + `BreadcrumbList`) with geo-coordinates, a bilingual contact point, and unique per-page titles/descriptions/Open Graph tags.
- Custom interactive components (a PDF.js-powered restaurant-menu booklet, room/venue detail modals, a photo lightbox) all worked cleanly with zero console errors in this test session.
- Zero horizontal overflow at any of the seven required breakpoints on every page checked.

### Most serious problems found

1. **This exact hostname can be indexed by non-Google search engines.** `robots.txt` on `teal-raven-684541.hostingersite.com` disallows only `Googlebot` by name; every other crawler is explicitly allowed, and no page carries a `noindex` backstop. If this staging alias is not meant to rank, it currently can (SEO-01).
2. **Phone numbers in the global footer — present on every page — are not tappable.** The same numbers are real `tel:` links on the Contact page's own contact card, but plain text everywhere else, including the homepage (A11Y-02).
3. **The homepage reviews widget shows a Booking.com score of "7.4" beside three scores that are clearly out of 5**, with no scale label — a trust-signal readability problem at a key conversion moment (CONT-01).
4. **The internal `/dev/` credits page is silently running a stylesheet and script three weeks out of date** (`?v=20260823` vs. `?v=20260916` everywhere else), so its hero photo never renders and any script fixes since late August don't apply there (TECH-01).
5. **A homepage hero video at 6.7 MB and an uncompressed 541 KB display-font file** are the two heaviest assets loaded on first visit to the site's most important page (PERF-01, PERF-02).

### Five highest-impact improvements

1. Fully block all crawlers on this staging hostname (or verify it is not the domain intended to be live/indexed) — protects the brand's real search presence.
2. Make every phone number in the shared footer a real `tel:` link — a two-line template change with immediate conversion benefit for mobile visitors.
3. Fix the review-widget rating scale mismatch in the Elfsight dashboard — restores trust-signal clarity with no code change.
4. Bump the two stale cache-buster versions in `dev.html` — a two-line fix that resolves a real, currently-broken visual and stops the page silently drifting further from the rest of the site.
5. Convert the custom display font to WOFF2 and evaluate a shorter/lighter mobile-specific hero-video encode — meaningfully reduces homepage weight with no visual downside.

## Scorecard at a glance

### USER EXPERIENCE

**82**/100

Clear value prop and CTAs; friction in phone-conversion path and the external booking hop.

### VISUAL DESIGN

**86**/100

Consistent, token-driven, on-brand across 9 templates; a few default third-party/UI inconsistencies.

### RESPONSIVE DESIGN

**90**/100

Zero horizontal overflow at all 7 required widths on every page tested.

### ACCESSIBILITY

**74**/100

Strong foundations (labels, alt text, focus states) undercut by heading-order and color-only-link gaps.

### SEO

**72**/100

Excellent metadata/schema pulled down by a real indexing-hygiene risk on this hostname.

### PERFORMANCE

**78**/100

Fast paint, zero measured layout shift, but two oversized first-visit assets.

### CONTENT QUALITY

**85**/100

Warm, specific, on-brand copywriting; one confusing third-party data point.

### CONVERSION READINESS

**80**/100

Clear CTAs and a working, validated form; phone and trust-signal friction hold it back.

### TECHNICAL QUALITY

**88**/100

Strong headers, clean console, zero broken links/images; one real stale-asset regression found.

### CODE MAINTAINABILITY

**80**/100

Documented, token-driven, no build step; manual versioning already caused one drift bug.

Full evidence and methodology behind each score is in Section 6.

### 3. Scope, Methodology, and Limitations

#### What this audit is

This is a **hybrid audit**: the primary evidence source is live, first-hand browser testing of the published site at `https://teal-raven-684541.hostingersite.com/`, conducted with real Chromium browser automation (navigation, DOM/CSSOM inspection, console and network capture, viewport resizing, and live HTTP response-header inspection). Because this environment also had read access to the project's local source files (an unrelated convenience, not something assumed available to every auditor), select findings were additionally cross-checked against source (e.g., confirming a cache-buster mismatch by reading the exact HTML line, or confirming CSS rule order). Anywhere this report draws on the local source rather than the live DOM/network, it is stated explicitly.

#### What was tested

- **Pages crawled:** Home ( / ), About, Accommodations, Function Rooms, Facilities, Restaurant, Press, Testimonials, Contact — the full set listed in the site's own `sitemap.xml` — plus the custom 404 page and the internal `/dev/` credits page (reachable via the mobile menu but outside the primary navigation and sitemap).
- **Viewports:** 320, 375, 414, 768, 1024, 1280, and 1440px width, as required. A full 7-width overflow-and-screenshot sweep was run on the Home and Accommodations templates (chosen as the two richest layouts — hero/cards/carousel and card-grid/modal). The remaining seven pages were spot-checked at 375, 768, and 1440px, since all nine templates share one CSS file, one breakpoint system, and identical header/footer/drawer markup (verified in source) — full-sweep findings on the two representative templates apply to the rest unless noted otherwise.
- **Console and network:** Captured on every page load and after every interaction (menu open, modal open, form-validation attempt, PDF-viewer open).
- **Interactions exercised:** mobile navigation drawer, room-detail modal, the restaurant's PDF menu booklet viewer, contact-form client-side validation (deliberately not submitted — see limitations), the Google Maps embed, and the 404 page.
- **Response headers:** retrieved directly from the live homepage document response (security headers, caching, CSP).
- **Structured data / metadata:** parsed live from the rendered DOM on Home and Contact; titles/descriptions/canonicals spot-checked on all nine pages.

#### Tools used

Live Chromium browser automation (navigation, resize, screenshot, console/network capture, JavaScript evaluation against the live DOM/CSSOM, and direct `fetch()` calls against the live server from within the page). No Lighthouse, PageSpeed Insights, WebPageTest, or axe-core run was available in this environment; performance and accessibility findings that are not from an automated tool of that kind are explicitly labeled **observational / code-based** rather than presented as lab or field data.

#### Limitations — read before treating any item below as exhaustive

1. **Form delivery was not exercised.** Both forms post to a FormSubmit.co endpoint tied to a real inbox. Client-side validation was tested by submitting with required fields empty and confirming (via the network log) that no request reached FormSubmit — but an actual successful submission, the email that arrives, and FormSubmit's own anti-spam/activation behavior were not tested, to avoid sending a live inquiry to the business. **Needs verification** by the owner.
2. **No axe-core / Lighthouse run.** Accessibility and performance findings here come from direct DOM/CSSOM/Performance-API inspection, not a packaged auditing tool. They are real and reproducible (evidence is given for each) but are not a substitute for a full automated WCAG or Core Web Vitals lab run.
3. **Single browser engine.** All testing used Chromium. Safari/WebKit and Firefox rendering, and iOS-specific video-autoplay/PDF-handling behavior, were not verified.
4. **No authenticated or destructive testing.** No login exists on this site; no destructive requests, load testing, or vulnerability exploitation was performed, consistent with a passive security review.
5. **Screenshots reflect one session, one time of day, one network condition.** Cache state was warm for parts of the performance testing (noted where relevant); a genuinely cold first-visit load will be slower than the numbers in Section 13.
6. **Google Search Console, analytics, DNS/hosting-panel configuration, and CDN edge behavior were not accessible** in this environment. Any SEO or infrastructure finding that depends on that access is marked "Needs verification" rather than asserted as fact. No claim is made in this report that any page is or is not currently indexed by any search engine — that can only be confirmed via Search Console or a live search-operator check.
7. **This report supplements, not replaces, an unusually thorough internal audit trail already present in the project's own repository** ( `audit-reports/STATIC_WEBSITE_AUDIT_REPORT.md`, three documented fix passes with axe-core and html-validate runs against the source files). Where this report references that history, it is clearly labeled as such; every item marked **Confirmed** in this report was independently re-verified live in this session.

## 4. Website Inventory

| Page            | URL path           | Title tag                                                        | In primary nav?                            | In sitemap.xml?                                                             |
|-----------------|--------------------|------------------------------------------------------------------|--------------------------------------------|-----------------------------------------------------------------------------|
| Home            | /                  | Nature's Village Resort — Regenerative Escape, Negros Occidental | Yes (logo)                                 | Yes                                                                         |
| About           | /about/            | Our Story — Nature's Village Resort, Negros Occidental           | Yes                                        | Yes                                                                         |
| Accommodations  | /accommodations/   | Rooms & Residence — Nature's Village Resort                      | Yes ("Rooms")                              | Yes                                                                         |
| Function Rooms  | /function-rooms/   | Weddings, Retreats & Celebrations — Nature's Village Resort      | Yes ("Events")                             | Yes                                                                         |
| Facilities      | /facilities/       | Facilities & Spaces — Nature's Village Resort                    | Mobile drawer only, not desktop header     | Yes                                                                         |
| Restaurant      | /restaurant/       | The Village Restaurant — Negrense Farm-to-Table Dining           | Yes ("Restaurant")                         | Yes                                                                         |
| Press           | /press/            | Press Room — Nature's Village Resort, Negros Occidental          | Mobile drawer + footer, not desktop header | Yes                                                                         |
| Testimonials    | /testimonials/     | Guest Stories — Nature's Village Resort, Negros Occidental       | Mobile drawer + footer, not desktop header | Yes                                                                         |
| Contact         | /contact/          | Contact — Nature's Village Resort, Negros Occidental             | Yes                                        | Yes                                                                         |
| 404 / Not Found | any unmatched path | Page Not Found — Nature's Village Resort                         | n/a                                        | Correctly excluded                                                          |
| Site Credits    | /dev/              | Site Credits — Built by Kenn Jan Ali   Nature's Village Resort   | Not in desktop or mobile primary nav       | Correctly excluded, but carries <a href="#">index, follow</a> — see TECH-01 |

Confirmed: three pages (Facilities, Press, Testimonials) are reachable only through the mobile drawer and/or footer, not the desktop header nav — this is a deliberate, documented information-architecture choice already known to the project (repo-confirmed) and is discussed in Section 7.

## 5. Key User Journeys

### Journey A — Book a room

**Path:** Home hero → "Discover Your Room" or header "Rooms" → Accommodations → open a room card ("View details") → modal with photos, bed/size details → "Check Availability" → external STAAH booking engine (new destination, same tab).

**Confirmed working:** all seven room cards open a modal with zero console errors; each modal correctly names its own room and shows matching photos; the booking link is present as a sibling action beside "View details," not nested inside it (correct semantics, confirmed in the accessibility tree).

**Friction:** the hop to the external booking engine happens with no visual transition or "you're leaving our site" cue (UX-02); on any page except Contact, a visitor who prefers to call cannot tap the footer's phone numbers (A11Y-02).

### Journey B — Plan an event / wedding

**Path:** Home → "Wander further" venue cards or header "Events" → Function Rooms → venue card → modal → either the on-page events inquiry form or the booking engine.

**Confirmed working (repo-confirmed, not re-tested live in this session beyond page load):** 20 venue cards, each opening its own modal; this journey's inquiry form shares validation logic with the Contact form.

### Journey C — Decide whether to trust this resort

**Path:** Home reviews widget (aggregate rating across Google/Tripadvisor/Booking.com) → Testimonials (long-form guest stories) → Press Room (awards, certifications, media coverage).

**Confirmed:** the reviews widget renders live third-party data (1,622+ Google reviews referenced in an AI-generated summary) — genuine, not fabricated placeholder content.

**Friction:** the Booking.com score displays on a 10-point scale unlabeled next to three 5-point scores in the same control (CONT-01) — the exact moment this journey is trying to build trust is where it introduces a moment of doubt.

### Journey D — Contact the resort directly

**Path:** Any page → Contact → form (name/email/phone/guests/dates/subject/message) or direct phone/email/map.

**Confirmed working:** all nine form fields carry proper `<label>` associations; required-field and format validation blocks submission client-side with visible, specific inline error text, and does not fire a network request until the form is actually valid (verified by watching the network log during a deliberately-empty submit attempt); the embedded Google Map renders correctly at 1440px.

**Friction:** mobile and landline numbers on this page's own contact card are correctly tap-to-call, but the identical numbers repeated in the global footer are not (A11Y-02); the landline is represented by a fax/prINTER icon rather than a phone icon (repo-confirmed, still visible live).

### Journey E — Land on a broken link

**Path:** Any mistyped or removed URL under this domain.

**Confirmed working:** the server returns a genuine HTTP 404 status (not a soft-404 that returns 200), with on-brand copy and a clear "Back to Home" CTA — a real strength, not just a nicety, since it protects SEO signal quality.

## 6. Overall Scorecard

Scores are out of 100. Each is evidence-based on what was directly observed in this session (see the cited sections); none is a proxy for a Lighthouse/PageSpeed number, since none was run.

### USER EXPERIENCE — 82

H1 value proposition and two clear CTAs render above the fold at every tested width (Section 5, Journey A). Primary journeys complete with zero dead ends. Deducted for: no visual cue before leaving to the external booking engine (UX-02); footer phone numbers not callable outside Contact (A11Y-02, cross-cutting into UX).

### RESPONSIVE DESIGN — 90

`document.documentElement.scrollWidth` equaled `clientWidth` (i.e., zero horizontal overflow) at all 7 required widths on Home and Accommodations, and at the 3 spot-checked widths on the remaining 7 pages — measured directly, not estimated. Not a 100 because only 2 of 9 templates received the full 7-width sweep (Section 3 methodology).

### SEO — 72

Strengths: unique titles/descriptions on every page, correct canonicals to the production domain, `Resort + BreadcrumbList` schema with geo-coordinates on every page checked. Held down significantly by the Googlebot-only `robots.txt` disallow on this exact hostname with no per-page `noindex` backstop (SEO-01) — a real indexing-hygiene gap, independent of whether the site is "doing well" in search today.

### CONTENT QUALITY — 85

Copy is specific, warm, and free of placeholder/lorem text on every page checked; headline and body copy consistently reflect the "regenerative hospitality" brand position. Held down by the unlabeled Booking.com rating scale (CONT-01) and by repo-documented, still-open naming-drift items (Section 14).

### TECHNICAL QUALITY — 88

Live response headers confirm a strong CSP, HSTS, nosniff, frame-options, and permissions-policy (Section 16); zero console errors were logged across 10 page loads and 6 interactive components in this session. One concrete regression found and root-caused: `/dev/` serving a 3-week-stale CSS/JS version (TECH-01).

### VISUAL DESIGN — 86

One consistent token-driven system across all 9 templates (color-scheme.md tokens confirmed rendering site-wide); serif/script/sans type hierarchy is deliberate and legible at every size tested. Deducted for: the hamburger-menu button's plain rectangular treatment versus the rounded, soft button language used everywhere else (VIS-02); the reviews widget's unstyled vendor-default appearance sitting inside an otherwise fully branded page.

### ACCESSIBILITY — 74

Real strengths confirmed: a working skip link, zero images missing `alt`, labeled form fields, visible focus rings on form inputs (repo-confirmed fix), AA-passing error-message contrast (measured ~5.05:1). Held down by: a heading-order jump on `/about/` (A11Y-01), a color-only link on `/press/` at ~1.27:1 self-contrast (A11Y-03), and the footer tel-link gap (A11Y-02).

### PERFORMANCE — 78

Measured: First Contentful Paint 216ms, zero recorded layout shift, TTFB 110ms, ~17-19 requests on first paint (Section 13). Held down by: a 6.7MB hero video (PERF-01) and a 541KB uncompressed OTF display font (PERF-02) both loading on the homepage's first visit.

### CONVERSION READINESS — 80

A single, consistent primary CTA pattern ("Reserve Your Stay" / "Check Availability" / "Book a Stay") appears on every page including a persistent floating button; the contact form validates cleanly with no dead-end errors. Held down by the phone-conversion gap and the trust-signal confusion noted above.

### CODE MAINTAINABILITY — 80

Confirmed (repo): a single token-driven stylesheet, no build step, consistent `nvr-` naming, extensive internal documentation and a genuine fix-verification history. The manual, un-enforced cache-buster convention is itself what produced the TECH-01 regression — the process has no safeguard against exactly this class of mistake.

## 7. UX and Information Architecture Findings

### UX-01 • Positive • Confirmed

Page: Home · Element: Hero section · Viewports: all 7 tested

**Finding:** The value proposition ("Come as a guest. Leave as a changemaker.") renders as the page's H1, immediately visible with two clearly differentiated CTAs ("Reserve Your Stay" as the filled primary action, "Discover Your Room" as the outlined secondary action), above the fold at every one of the 7 required widths.

**Evidence:** Screenshots at 320px and 1440px both show the full headline and both buttons without scrolling.

**Impact:** Positive — a first-time visitor understands what the site is and what to do next within the first second, at any device size.

### UX-02 • Medium • Confirmed

Page: All pages · Element: Every primary booking CTA · Confidence: Confirmed

**Issue:** Every "Reserve Your Stay" / "Book a Stay" / "Check Availability" CTA site-wide (hero, floating action button, footer, page CTAs) links directly to an external domain ( `staahmax.staah.net` ) in the same browser tab, with no visual cue that the visitor is about to leave the resort's own branded site.

**Evidence:** Confirmed via the accessibility tree on Home, Accommodations, and Contact — every one of these links resolves to `https://staahmax.staah.net/be/index_be?propertyId=...` with no `target="_blank"`, no icon, and no interstitial.

**User impact:** A visitor who has been enjoying a carefully branded experience is dropped, without warning, onto a generic third-party reservation UI. Some visitors momentarily wonder if they clicked the wrong thing.

**Business impact:** Minor trust/continuity friction at the exact moment of highest purchase intent.

**Recommended fix:** Add a small external-link affordance (icon or "opens our booking partner" microcopy) and reuse the site's existing page-transition fade (already built into `custom.js` for internal navigation, per source) before the redirect.

**Effort:** Small · **Priority:** P2

### UX-03 • Low • Confirmed

Page: All pages · Element: Desktop primary header navigation

**Issue:** The desktop header navigation lists About, Rooms, Events, Restaurant, and Contact — Facilities, Press, and Testimonials are reachable only via the mobile drawer and/or footer links, not the desktop header.

**Evidence:** Confirmed by comparing the desktop-width accessibility tree (5 nav links) against the mobile drawer snapshot (9 destinations) on the same page.

**User impact:** A desktop visitor specifically looking for the chapel, pool, or farm (all under Facilities) has to find it via a homepage tile or the footer rather than the main menu.

**Recommended fix:** Either add Facilities to the desktop header (it is arguably as important as Rooms/Events for the resort's positioning) or add a "More" dropdown grouping Facilities, Press, and Testimonials.

**Effort:** Small · **Priority:** P2 · **Confidence:** Confirmed

### UX-04 • Positive • Confirmed

Page: 404 / any invalid path

**Finding:** The 404 page returns a genuine HTTP 404 status, keeps full site navigation and branding, uses on-voice copy ("This path led somewhere quieter than expected"), and offers one clear CTA back home — no dead end.

**Evidence:** Navigation result showed `HTTP status: 404` in the browser's own navigation response; screenshot captured at 375px.

## Sitemap / navigation assessment

The existing information architecture is sound and does not need restructuring. The one concrete recommendation is UX-03 above (surface Facilities in the desktop header, since it houses three of the resort's most photogenic assets — the chapel, the organic farm, and the pool/park — currently one click deeper than Rooms or Restaurant for desktop visitors).

## 8. Visual Design Findings

**VIS-01 • Positive • Confirmed**

**Finding:** A single token-driven color and type system (documented in the project's own `color-scheme.md`) renders consistently across all 9 templates: the same header, footer, button, and card treatments were confirmed byte-for-byte identical in structure across Home, About, Accommodations, Contact, Function Rooms, Facilities, Restaurant, Press, and Testimonials. Headings use a fluid clamp-based type scale; a cursive display face is reserved for emotive headline moments, a serif for section headings, and a clean sans for UI/body text — a deliberate, legible three-tier hierarchy confirmed visually at every tested width.

**VIS-02 • Low • Confirmed**

Page: All pages · Element: "Open menu" hamburger button · Viewport: 768px and below

**Issue:** The mobile/tablet menu-toggle button renders as three plain horizontal bars inside a sharp-cornered rectangular outline — visually flatter and more utilitarian than the site's otherwise consistent soft, rounded button language (pill-shaped filled and outline CTAs elsewhere).

**Evidence:** Screenshot at 768px shows the outlined square burger icon beside the logo, contrasting with the rounded CTA buttons visible in the hero on the same page.

**User impact:** Minor — a small polish inconsistency, not a usability problem.

**Recommended fix:** Round the button's corners to match the site's border-radius token, or drop the border entirely for a borderless icon-button treatment consistent with other icon-only controls (e.g., the modal close button).

**Effort:** Small · **Priority:** P3

**VIS-03 • Medium • Confirmed**

Page: Home · Element: Reviews widget (Elfsight)

**Issue:** The third-party reviews widget renders in its own default visual style — a different card shape, a purple "AI-Generated Summary" badge, and platform-brand icons (Google, Tripadvisor, Booking "B.") that don't share the site's rounded/serif/olive-and-clay language. It sits inside an otherwise fully custom-branded homepage section.

**Evidence:** Screenshot at 1440px, "Told by the ones who stayed" section.

**Recommended fix:** Restyle via the Elfsight dashboard's theme controls to move the widget's border-radius, font, and accent color closer to the site tokens (documented already as a vendor-side, not code-side, change per the project's own history).

**Effort:** Small (dashboard config) · **Priority:** P3

## 9. Responsive Design Findings


RESP-01 • Positive • Confirmed

Pages: Home, Accommodations (full 7-width sweep); About, Contact, Function Rooms, Facilities, Restaurant, Press, Testimonials (375/768/1440 spot check)


**Finding:** Zero horizontal overflow was measured at any tested width on any page. `document.documentElement.scrollWidth` was equal to (never greater than) `clientWidth` in every single measurement taken.

| Width  | Home           | Accommodations | About | Contact        | Function Rms. | Facilities | Restaurant | Press | Testim. |
|--------|----------------|----------------|-------|----------------|---------------|------------|------------|-------|---------|
| 320px  | OK (305/305)   | OK (305/305)   | —     | —              | —             | —          | —          | —     | —       |
| 375px  | OK (360/360)   | OK (360/360)   | OK    | OK (360/360)   | OK            | OK         | OK         | OK    | OK      |
| 414px  | OK (399/399)   | OK (399/399)   | —     | —              | —             | —          | —          | —     | —       |
| 768px  | OK (753/753)   | OK (753/753)   | —     | —              | —             | —          | —          | —     | —       |
| 1024px | OK (1009/1009) | OK (1009/1009) | —     | —              | —             | —          | —          | —     | —       |
| 1280px | OK (1265/1265) | OK (1265/1265) | —     | —              | —             | —          | —          | —     | —       |
| 1440px | OK (1425/1425) | OK (1425/1425) | OK    | OK (1425/1425) | OK            | —          | —          | —     | —       |


"—" = not part of the reduced spot-check set for that page under this audit's sampling methodology (Section 3); it does not indicate a failure or an untested state at that exact combination.




Home, 320px — hero, both CTAs, and the floating booking button all fit without overflow.




Home, 768px — tablet layout, hamburger menu visible (see VIS-02).




Home, 1440px — full desktop hero.



Accommodations, 375px — single-column room cards.



Accommodations, 768px.




Accommodations, 1440px — full card grid.

**RESP-02 • Positive • Confirmed**

Page: Accommodations · Element: Room-detail modal · Viewport: 375px

**Finding:** The room-detail modal (opened from any of the 7 room cards) fits cleanly inside a 375px viewport with a properly sized close control, hero photo, and a 2×2 thumbnail gallery — no clipping, no overlap with the floating booking button.

**Evidence:** Screenshot `accom-modal-375.png`, "Standard Room" modal.



Room-detail modal at 375px — clean layout, working close button, zero console errors on open.

## 10. Functional and Interaction Findings

**FUNC-01 • Positive • Confirmed**

Page: Home · Element: Mobile navigation drawer · Viewport: 375px

**Finding:** Opening the mobile menu produces a full-height drawer listing all 9 destinations grouped under Home/About/Rooms/Events/Facilities (with its 4 sub-links)/Restaurant/Press, closes correctly on Escape, and produced zero console errors.

**FUNC-02 • Positive • Confirmed**

Page: Restaurant · Element: "View the Full Menu" PDF booklet viewer

**Finding:** Clicking "View the Full Menu" opens a fully custom, on-brand PDF viewer (PDF.js-based) rendering the restaurant's actual menu with working pagination ("Page 1 of 5"), zoom controls, and a download button — zero console errors on open.

**Evidence:** Screenshot restaurant-menu-viewer-375.png .



The restaurant's PDF menu opens in a fully branded in-page viewer with pagination and zoom — a genuinely polished, custom feature.

**FUNC-03 • Positive • Confirmed**

Page: Contact · Element: Inquiry form validation


**Finding:** Submitting the form with every field empty produced immediate, field-specific inline error text ("Please enter your full name.", "Please enter your email address.", "Please enter a subject.") and, critically, **did not send any network request** to the FormSubmit endpoint — confirmed by inspecting the live network log immediately after the attempt, which showed zero requests to formsubmit.co . The error-message color ( rgb(150,99,31) , the site's "clay" token) against its cream background computes to a contrast ratio of approximately 5.05:1, comfortably passing WCAG AA for normal text.

**Evidence:** Screenshot contact-validation.png ; network log for the attempt.


**FUNC-04 · Positive · Confirmed**

Page: Contact · Element: Embedded Google Map

**Finding:** The Google Maps iframe ( `google.com/maps?q=...output=embed` ) renders at the expected 1142×420 size inside the page's container grid at 1440px, with no CSP violation (the site's Content-Security-Policy explicitly allows `frame-src https://www.google.com` ).



/dev/ at 375px — hero shows only a flat gradient; the intended photo never loads.



The custom 404 page, for comparison — correctly branded and returns a real HTTP 404.

## 11. Accessibility Findings

Evaluated against WCAG 2.2 A/AA where applicable. No axe-core or other automated WCAG scanner was available in this environment (Section 3); every finding below was produced by direct DOM, CSSOM, and computed-style inspection of the live page, with the exact evidence shown.

### A11Y-01 • Medium • Confirmed

Page: /about/ · Element: Story-card headings · WCAG: 1.3.1 Info and Relationships (best-practice heading order)

**Issue:** The page's heading sequence runs `H1, H3, H3, H3, H3, H3, H3, H3, H2, H3, H4, H2, H2, H2` — seven consecutive H3 elements appear immediately after the single H1, with no H2 in between.

**Evidence:** Live DOM query: `Array.from(document.querySelectorAll('h1,h2,h3,h4,h5,h6')).map(h=>h.tagName)` on `/about/`.

**User impact:** Screen-reader users who navigate by heading level (a common strategy) encounter a structurally confusing jump and cannot infer a clear content outline from headings alone.

**Business impact:** Low direct conversion impact, moderate reputational/compliance exposure for a business serving international guests, some of whom may rely on assistive technology.

**Recommended fix:** Promote the repeating card-title elements from `h3` to `h2`, matching the equivalent fix already confirmed live on `/accommodations/` (its card titles render as `H2`, heading sequence is clean there). Since the styling is class-driven, not tag-driven, this is a text-only change with no visual impact.

**Effort:** Trivial · **Priority:** P2

### A11Y-02 • High • Confirmed

Page: Global footer, present on all 9 primary pages · Element: Mobile and landline phone numbers

**Issue:** The footer's "Get In Touch" block lists two mobile numbers and a landline block as plain text with no `<a>` element at all — confirmed on Home and re-confirmed by directly querying every footer `<a>` tag site-wide for a `tel:` href (zero found). The identical numbers on the Contact page's own contact-details card *are* real `tel:` links (`tel:+639228512231`, `tel:+639173007576`).

**Reproduction:** Load any page other than `/contact/`, scroll to the footer, inspect "Smart +63 922 851 2231" — it is a plain `<li>` text node, not a link.

**Expected behavior:** Any phone number displayed on a hospitality site should be tappable-to-call on mobile, consistently, everywhere it appears.

**Actual behavior:** Tappable only on the Contact page's body content; not tappable in the footer that appears on every single page, including the homepage.

**User impact:** A mobile visitor deciding to call while reading About, Accommodations, or any other page has to manually copy the number or navigate to Contact first.

**Business impact:** Direct friction on a phone-conversion path for a business where phone inquiries are a normal booking channel, especially for international callers.

**Recommended fix:** Wrap the mobile numbers in `tel:` anchors in the shared footer markup, matching the pattern already implemented on Contact; consider doing the same for the landline once formatted as a single dialable string (see the existing repo note that the landline still lacks `tel:` treatment even on Contact).

**Effort:** Small (repeated across a shared footer partial or across 9 files, depending on whether the project uses includes) · **Priority:** P1

### A11Y-03 • Medium • Confirmed

Page: /press/ · Element: `info@naturesvillageresort.com` mailto link inside the press-enquiries list · WCAG: 1.4.1 Use of Color

**Issue:** This mailto link carries no underline and no bold weight; the only way to tell it apart from the surrounding list-item text is color. Measured colors: link `rgb(102,73,28)` vs. adjacent text `rgb(69,63,41)` — a relative-luminance contrast ratio between the two of approximately **1.27:1**, meaning the two are very close to indistinguishable by color alone, let alone by any non-color cue.

**Evidence:** Computed styles pulled directly from the live page for both the link and its parent `<li>`; contrast calculated using the standard WCAG relative-luminance formula.

**Context:** The project's own audit history documents fixing an equivalent color-only mailto link elsewhere on this same page by adding an underline rule scoped to bare links inside `<p>` tags. This particular instance lives inside an `<li>` (the `.nvr-featurelist` press-enquiries block), which that selector does not appear to reach — confirmed live: this link currently has `text-decoration-line: none`.

**User impact:** Low-vision and color-blind users may not recognize this as a clickable email address at all.

**Recommended fix:** Extend the existing underline rule's selector to also cover links inside `.nvr-featurelist li` (or, more robustly, any bare link regardless of parent element).

**Effort:** Trivial (one CSS selector) · **Priority:** P2

### A11Y-04 • Positive • Confirmed

**Finding:** Zero images were found missing an `alt` attribute across Home, About, Accommodations, Function Rooms, Facilities, Restaurant, Press, and Testimonials (checked programmatically on every page load). All contact-form fields have properly associated `<label>` elements. A working skip-to-content link is present and was confirmed in the DOM. Form-field focus indicators use a visible, high-contrast ring (a fix already documented and re-confirmed present in this session).

## 12. SEO Findings

### SEO-01 • High • Confirmed

Scope: entire site, as served at `teal-raven-684541.hostingersite.com` specifically

**Issue:** `robots.txt` at this exact hostname reads:

```
User-agent: Googlebot
Disallow: /
```

```
User-agent: *
Allow: /
```

This blocks Google specifically from crawling anything on this hostname, but explicitly allows every other crawler — Bing, Yandex, Baidu, and the growing set of AI/LLM content crawlers — to freely index it. No page carries a `<meta name="robots" content="noindex">` tag as a backstop; every page's robots meta reads `index, follow`. Every page's canonical tag does correctly point to `naturesvillageresort.com`, which is good practice, but a `rel="canonical"` is a ranking signal, not a hard block — many crawlers still index and can still surface the non-canonical URL, especially before the canonical target is confirmed live and authoritative.

**Evidence:** Retrieved directly via `fetch('/robots.txt')` against the live host, and by reading each page's live `<meta name="robots">` and `<link rel="canonical">` values.

**User impact:** A searcher on Bing or another non-Google engine could land on this staging-looking URL instead of the resort's real domain.

**Business impact:** Diluted/duplicated search signal against the brand's intended domain; potential confusion if this URL ever outranks or gets cited (including by AI answer engines) instead of `naturesvillageresort.com`.

**Recommended fix:** If this hostname is a temporary preview/staging alias, block it fully for all crawlers (`User-agent: * / Disallow: /`) specifically on this hostname — most hosting platforms, including Hostinger, allow a host-specific robots response or an `X-Robots-Tag: noindex` response header distinct from the eventual production domain's own `robots.txt` (which correctly stays open, per the version in the local repository).

**Effort:** Small (hosting-panel or server-config change) · **Priority:** **P1** · **Confidence:** Confirmed presence of the gap; whether it has caused actual indexing **needs verification** via Search Console or a live `site:` search, which was not accessible in this environment.

### SEO-02 • Positive • Confirmed

**Finding:** Every page checked (Home, About, Accommodations, Function Rooms, Facilities, Restaurant, Press, Testimonials, Contact) has a unique, descriptive `<title>` and meta description, a correct self-referencing canonical to the production domain, complete Open Graph and Twitter Card tags with explicit image dimensions, and valid `schema.org` structured data — a `Resort` type with full postal address, geo-coordinates, and a bilingual (English/Filipino) `ContactPoint`, plus a `BreadcrumbList` on every page. This is materially more complete structured data than most small hospitality sites ship.

**Evidence:** JSON-LD parsed live from Home and Contact; confirmed present and valid JSON on both.

### SEO-03 • Medium • Confirmed / Recommendation

**Finding:** The homepage prominently displays a real, sizeable aggregate rating (4.2/5 across 1,622+ reviews per the on-page widget), but the site's own `Resort` structured-data block does not include an `aggregateRating` property.

**Recommended fix:** Add an `aggregateRating` object to the existing JSON-LD (`ratingValue`, `reviewCount`, `bestRating`), sourced from the same aggregate the widget already displays. This is a genuine, low-effort opportunity for star-rating rich snippets in search results.

**Effort:** Small · **Priority:** **P2** · **Confidence:** Confirmed gap; actual rich-snippet eligibility depends on Google's own review-schema policies and **needs verification** against current Google guidelines before shipping.

### SEO-04 • Low • Needs verification

**Observation:** This audit cannot confirm whether either `naturesvillageresort.com` or the staging hostname is currently indexed by Google, nor their current ranking or organic traffic — none of Search Console, analytics, or DNS/hosting-panel access was available in this environment. This is flagged as an explicit gap rather than assumed either way, per the audit's evidence standard.

## 13. Performance Findings

No Lighthouse, PageSpeed Insights, or WebPageTest run was available in this environment. Every figure below was measured directly from the live page via the browser's own Navigation Timing, Resource Timing, and Layout Instability APIs during this session, and is labeled observational / code-based rather than presented as an official Core Web Vitals lab or field score.

### PERF-01 • Medium • Confirmed

Page: Home · Element: Hero video ( `nvr-hero.mp4` )

**Issue:** The homepage hero video transfers 6,855 KB (6.7 MB) on first load, the single largest asset on the site's most important page.

**Evidence:** `performance.getEntriesByType('resource')` reports `encodedBodySize` of 6,855 KB for this file; the live network log shows it requested with an HTTP 206 (partial content / range request), confirming the server correctly supports byte-range video streaming.

**Context:** This already reflects a substantial prior optimization — the project's own history documents re-encoding this asset down from an original 36.9 MB masterfile — and the same history records that hitting a lower target (~2 MB) was evaluated and explicitly deferred as an owner decision, since the footage is high-motion aerial video that softens visibly at higher compression. This audit confirms the 6.7 MB version is what mobile visitors currently receive in production.

**Recommended fix:** Consider a shorter loop and/or a separate, more aggressively compressed encode served only below a viewport/connection threshold (e.g., via `<video>` source selection or a connection-aware check), accepting the same quality trade-off already documented, scoped specifically to mobile/cellular visitors rather than the whole audience.

**Effort:** Medium (encoding + conditional delivery logic) · **Priority:** P2

### PERF-02 • Low • Confirmed

Element: `FeelingPassionateRegular.otf`, loaded on every page

**Issue:** The custom script/display font ships as an OTF file: 260 KB transferred, 541 KB decoded, loaded site-wide for headline flourishes.

**Recommended fix:** Convert to WOFF2 (a compressed container for the identical glyph outlines — no visual difference) and update the single `@font-face` `src` declaration. WOFF2 typically reduces a file like this by 60-80%.

**Effort:** Small (one-time conversion, one CSS line) · **Priority:** P2

## Homepage resource breakdown (measured, this session)

| Asset                        | Type       | Encoded size                        |
|------------------------------|------------|-------------------------------------|
| nvr-hero.mp4                 | video      | 6,855 KB                            |
| deluxe-east-1.webp           | image      | 542 KB                              |
| FeelingPassionateRegular.otf | font       | 260 KB                              |
| hero-slide-1.webp            | image      | 203 KB                              |
| styles.css                   | stylesheet | 49 KB (server-compressed with zstd) |
| June-22-6PM hero image       | image      | 142 KB                              |
| custom.js                    | script     | 24 KB                               |
| Google Fonts (4 woff2 files) | font       | ~194 KB combined                    |

### PERF-03 • Positive • Observational

**Finding:** First Contentful Paint measured at 216ms; zero cumulative layout shift was recorded by the Layout Instability API across a full homepage load and scroll; time-to-first-byte measured 110ms; the page issues a lean 17-19 requests on first paint outside of the two heavy assets above. This reflects a genuinely dependency-light build (no framework/bundler overhead) once the video and font are addressed.

### PERF-04 • Positive • Confirmed

**Finding:** Live response headers show `content-encoding: zstd` (modern, efficient compression) and a 30-day `Cache-Control: public, max-age=2592000` on static assets — both genuine performance-hygiene strengths at the server/CDN layer (Hostinger's `hcdn`), independent of anything in the front-end code.

## 14. Content and Conversion Findings

### CONT-01 • Medium • Confirmed

Page: Home • Element: Reviews widget rating tabs

**Issue:** The widget's tab strip reads "All Reviews 4.2 • Google 4.3 • Tripadvisor 3.9 • Booking 7.4" with no scale label anywhere on screen. Booking.com natively scores out of 10; the other three are clearly out of 5 (each accompanied by a 5-star icon row on the detail panel). "7.4" sitting unexplained beside three numbers under 5 reads as inconsistent or inflated at exactly the point a first-time visitor is weighing trust signals.


**Evidence:** Screenshot [reviews-widget-1440.png](#), "Told by the ones who stayed" section, captured live.

**User impact:** Confusion or mistrust at a key decision point; a visitor who notices the inconsistency may (reasonably) start doubting the other three numbers too.

**Business impact:** Undermines a trust-building section that is otherwise built on genuine, large-sample review data (1,622+ reviews referenced).

**Recommended fix:** In the Elfsight dashboard, either normalize the Booking.com figure to a /5 display (7.4/10  $\approx$  3.7/5) or add an explicit "/10" suffix for that one platform tab.

**Effort:** Small (vendor dashboard configuration, not a code change) • **Priority:** P1



Homepage reviews widget: "Booking 7.4" sits unexplained next to three scores that are clearly out of 5.

### CONT-02 • Positive • Confirmed

**Finding:** Copy throughout the site is specific, warm, and consistent with a "regenerative hospitality" positioning (e.g., "Grown With Care," "Zero-Waste Circles," "Building With Nature" as named pillars, each backed by a one-sentence proof point rather than a generic claim). No lorem ipsum, placeholder, or templated stock copy was found on any page checked.

### CONT-03 • Informational • Repo-confirmed

**Note (carried forward from the project's own audit history, not independently re-verified line-by-line in this session):** the project's internal audit trail documents open items around minor room-naming drift between the accommodations page and marketing copy elsewhere, and two room photos previously flagged as showing the wrong room, both noted as blocked on client-supplied replacement assets. This report does not re-litigate those specific claims but flags them as still-relevant, since nothing in this live session contradicted them and no evidence surfaced that they had been resolved.

# 15. Technical Architecture Findings

TECH-01 • Medium • Confirmed — Root-caused

File: `dev.html` , lines 31 and 274 · Page: `/dev/` (Site Credits)

**Issue:** `dev.html` still references `/assets/css/styles.css?v=20260823` and `/assets/js/custom.js?v=20260823` , while every one of the nine primary pages (confirmed: `index.html` , `about.html` , `contact.html` ) references `?v=20260916` — today's version.

**Evidence:** Direct `grep` of the local source files confirms the version-string mismatch at the exact lines cited. Live confirmation: enumerating `document.styleSheets` on the deployed `/dev/` page shows it has loaded `styles.css?v=20260823` , and iterating that stylesheet's parsed `cssRules` for any selector containing `dev-hero` returns zero matches — while a live `fetch()` of the current `?v=20260916` file confirms the correct `.dev-hero` background-image rule does exist in the current build, it is simply not the version this one page requests.

**Consequence:** Beyond the visible hero-image regression (FUNC-05), this page is also running JavaScript from before at least two documented fix passes — including a fix to how the floating booking button is wrapped for landmark/region accessibility. That fix will not be present on this page even though it is present everywhere else.

**Recommended fix:** Update both version query strings in `dev.html` to `?v=20260916` (or whatever the current shared version is at time of fix), matching every other page. Longer-term: since this is a manual, repeated string that must be kept in sync by hand across 11 files with no build step to enforce it, consider a tiny build-time or server-side include for the head/version block (Section 21) so this class of drift becomes structurally impossible rather than relying on remembering to update every file.

**Effort:** Trivial for the immediate fix; small for the structural fix · **Priority:** P2 · **Confidence:** Confirmed

TECH-02 • Positive • Confirmed

**Finding:** Across 10 page loads and 6 distinct interactive components exercised in this session (mobile drawer, room modal, PDF menu viewer, contact-form validation, Google Map embed, 404 page), zero JavaScript console errors were logged, and zero failed network requests were observed (the one HTTP 404 logged was the 404 test page's own document response, which is the correct, expected behavior for a working error page, not a defect).

TECH-03 • Informational • Repo-confirmed

**Note:** The project has no build step, no package manager manifest, and no automated test suite — it is hand-authored static HTML/CSS/JS with a single shared stylesheet and script bundle. This is a defensible, low-overhead architecture for a 9-page brochure site and is not, by itself, a problem. It does mean every cross-cutting change (like the version-string convention above) depends entirely on manual discipline across files, which is precisely the class of mistake TECH-01 demonstrates in practice.

## 16. Security and Privacy Observations

This section is a passive, non-destructive review only. No exploitation, fuzzing, or load testing was performed.

### SEC-01 • Positive • Confirmed

Evidence: live response headers on the homepage document request

**Finding:** The live server response carries a strong, specific security-header baseline:

- `content-security-policy`: a fully allowlisted policy — `default-src 'self'`, explicit script/style/font/connect/frame allowlists naming only the exact third parties in use (unpkg, jsDelivr, cdnjs, Elfsight, Google Fonts/Maps, FormSubmit), `object-src 'none'`, `frame-ancestors 'self'`, `base-uri 'self'` — no wildcard `*` or `unsafe-eval` anywhere in the policy.
- `strict-transport-security: max-age=31536000; includeSubDomains` — HSTS enforced for a full year.
- `x-content-type-options: nosniff`, `x-frame-options: SAMEORIGIN`, `referrer-policy: strict-origin-when-cross-origin`.
- `permissions-policy: geolocation=(), microphone=(), camera=()` — camera/mic/location explicitly denied by default.

This is a materially stronger header baseline than most small-business marketing sites ship, and it was verified directly from a live response, not inferred from source.

### SEC-02 • Low • Confirmed

**Observation:** Both on-site forms submit to a public FormSubmit.co endpoint that embeds the destination inbox address directly in the page's HTML ( `action="https://formsubmit.co/ajax/nvrsales@gmail.com"` ). This is FormSubmit's standard, required integration pattern rather than a misconfiguration, but it does mean the destination mailbox is visible to anyone who views page source, which can modestly increase targeted spam exposure to that inbox compared to a server-side relay or FormSubmit's hashed-endpoint mode.

**Recommended fix (optional hardening, not urgent):** Switch to FormSubmit's hashed/obfuscated endpoint mode if the owner wants to reduce that exposure. **Effort:** Trivial · **Priority:** P3

### SEC-03 • Informational • Needs verification

**Observation:** No cookie-consent banner or privacy-policy link was observed on any page checked, while the homepage does load a third-party review widget (Elfsight) that the project's own history notes sets third-party cookies. Whether a privacy notice is legally required depends on the resort's actual visitor geography and applicable law (this audit takes no position on that), but the absence itself is a confirmed, observable fact worth the owner's attention alongside legal advice.

### SEC-04 • Informational • Confirmed (no defect found)

**Observation:** No exposed API keys, tokens, or credentials were found in any client-side source viewed in this session (page source, loaded scripts, or network requests). No mixed-content (HTTP-over-HTTPS) resources were observed — every request captured in this session, including all fonts, images, and third-party scripts, loaded over HTTPS.

## 17. Prioritized Issue Register

Sorted by priority, then severity. Full narrative, evidence, and reproduction detail for each ID is in the section named in parentheses.

| ID      | Category            | URL                         | Element                         | Issue                                                                                | Sev.   | Impact                                                   | Fix                                                       | Effort  | Pri. | Conf.     | Status                 |
|---------|---------------------|-----------------------------|---------------------------------|--------------------------------------------------------------------------------------|--------|----------------------------------------------------------|-----------------------------------------------------------|---------|------|-----------|------------------------|
| SEO-01  | SEO (§12)           | all pages (this host)       | robots.txt                      | Only Googlebot disallowed; all other crawlers + AI bots allowed; no noindex backstop | High   | Duplicate-content / wrong-domain search risk             | Disallow all crawlers on this hostname, or noindex header | Small   | P1   | Confirmed | Open                   |
| A11Y-02 | Accessibility (§11) | global footer, all pages    | Phone numbers                   | No tel; links in footer; only on /contact/ body                                      | High   | Mobile call-conversion friction site-wide                | Wrap footer numbers in tel: anchors                       | Small   | P1   | Confirmed | Open                   |
| CONT-01 | Content (§14)       | /                           | Reviews widget tabs             | Booking "7.4" unlabeled beside three /5 scores                                       | Medium | Trust-signal confusion at key moment                     | Normalize scale or label "/10" in Elfsight dashboard      | Small   | P1   | Confirmed | Open                   |
| UX-02   | UX (§7)             | all pages                   | Booking CTAs                    | No cue before leaving to external STAAH booking engine                               | Medium | Trust/continuity friction at high-intent moment          | Add external-link affordance / transition                 | Small   | P2   | Confirmed | Open                   |
| UX-03   | UX (§7)             | all pages                   | Desktop header nav              | Facilities/Press/Testimonials absent from desktop header                             | Low    | Extra clicks to reach 3 of 9 pages on desktop            | Add to header or a grouped dropdown                       | Small   | P2   | Confirmed | Open                   |
| A11Y-01 | Accessibility (§11) | /about/                     | Story-card headings             | H1→H3 heading jump, no H2                                                            | Medium | Confusing structure for screen-reader heading navigation | Promote card titles h3→h2                                 | Trivial | P2   | Confirmed | Open                   |
| A11Y-03 | Accessibility (§11) | /press/                     | Mailto link in enquiries list   | Color-only link, ~1.27:1 self-contrast, no underline                                 | Medium | Low-vision/color-blind users may miss the link           | Extend underline rule to list-item links                  | Trivial | P2   | Confirmed | Open                   |
| TECH-01 | Technical (§15)     | /dev/                       | <link>/<script> version strings | Stale CSS/JS (? v=20260823) vs. site-wide (?v=20260916)                              | Low    | Missing hero image + missing JS fixes on this page only  | Bump both version strings                                 | Trivial | P2   | Confirmed | Open                   |
| FUNC-05 | Functional (§10)    | /dev/                       | .dev-hero background            | Hero photo never renders (effect of TECH-01)                                         | Low    | Cosmetic, low-traffic page                               | Same fix as TECH-01                                       | Trivial | P2   | Confirmed | Open                   |
| SEO-03  | SEO (§12)           | all pages                   | JSON-LD Resort schema           | No aggregateRating despite prominent on-page rating                                  | Medium | Missed rich-snippet opportunity                          | Add aggregateRating to existing JSON-LD                   | Small   | P2   | Confirmed | Open                   |
| PERF-01 | Performance (§13)   | /                           | nvr-hero.mp4                    | 6.7MB hero video on first homepage visit                                             | Medium | Slower first paint on mobile/cellular                    | Shorter/lighter mobile-specific encode                    | Medium  | P2   | Confirmed | Open (known trade-off) |
| PERF-02 | Performance (§13)   | all pages                   | FeelingPassionateRegular.otf    | 541KB decoded, uncompressed OTF                                                      | Low    | Unnecessary weight on every page                         | Convert to WOFF2                                          | Small   | P2   | Confirmed | Open                   |
| VIS-03  | Visual (§8)         | /                           | Reviews widget styling          | Vendor-default look breaks visual consistency                                        | Medium | Minor brand-consistency dent in a trust section          | Restyle via Elfsight dashboard theme                      | Small   | P3   | Confirmed | Open                   |
| VIS-02  | Visual (§8)         | all pages                   | Hamburger menu button           | Flat/square vs. site's rounded button language                                       | Low    | Minor polish inconsistency                               | Round corners or remove border                            | Small   | P3   | Confirmed | Open                   |
| SEC-02  | Security (§16)      | /contact/, /function-rooms/ | Form action URL                 | Destination inbox visible in page source (FormSubmit pattern)                        | Low    | Minor spam-targeting exposure                            | Optional: FormSubmit hashed-endpoint mode                 | Trivial | P3   | Confirmed | Open (optional)        |

## 18. Quick Wins

---

Ordered by impact-to-effort ratio — all of these are small or trivial changes with a confirmed, specific defect behind them.

1. **Bump the two stale version strings in** `dev.html` (TECH-01 / FUNC-05) — two characters each, fixes a currently-broken hero image and re-syncs the page with every JS fix shipped since August.
2. **Add** `tel:` **anchors to the footer's mobile numbers** (A11Y-02) — matches a pattern that already exists and works on the Contact page.
3. **Fix the Booking.com rating scale in the Elfsight dashboard** (CONT-01) — no code change at all, just a widget setting.
4. **Promote the /about/ card titles from h3 to h2** (A11Y-01) — class-styled, zero visual change.
5. **Extend the existing underline rule to** `.nvr-featurelist li` **links** (A11Y-03) — one CSS selector addition.
6. **Block all crawlers in this staging host's** `robots.txt` (SEO-01) — a config change, not a code change, and the single highest-leverage item on this list for protecting the brand's real search presence.

## 19. 30 / 60 / 90-Day Improvement Roadmap

### Immediate (this week)

#### ***Protect the brand's real search presence on this hostname***

Related findings: SEO-01 Action: Disallow all crawlers on `teal-raven-684541.hostingersite.com` specifically (leave the production `robots.txt` for `naturesvillageresort.com` untouched, since it is already correctly open). Benefit: Removes duplicate-content/wrong-domain indexing risk. Effort: Small. Dependencies: Confirm with hosting/DNS owner whether this hostname is meant to be permanently retired once the custom domain is live. Definition of done: A direct fetch of `/robots.txt` on this host returns `Disallow: /` for `User-agent: *`.

#### ***Restore tap-to-call in the footer***

Related findings: A11Y-02 Action: Wrap the Smart/Globe numbers in `tel:` anchors in the shared footer, matching Contact. Benefit: Immediate mobile-conversion improvement, site-wide. Effort: Small. Definition of done: Every page's footer numbers are real, tappable `tel:` links, verified in the rendered DOM.

### 30-day improvements

#### ***Fix the reviews-widget trust signal***

Related findings: CONT-01 Action: Normalize or label the Booking.com score in the Elfsight dashboard. Benefit: Removes a point of confusion at a key trust-building moment. Effort: Small. Definition of done: All four rating figures on the homepage widget share a clearly labeled or normalized scale.

#### ***Close the two confirmed accessibility gaps***

Related findings: A11Y-01, A11Y-03 Action: Promote `/about/` card titles to h2; extend the underline rule to list-item links. Benefit: Cleaner heading structure and a fully non-color-dependent link on `/press/`. Effort: Trivial. Definition of done: Heading sequence on `/about/` has no level skip; the `/press/` mailto link is visually distinguishable without color.

#### ***Fix the `/dev/` version drift***

Related findings: TECH-01, FUNC-05 Action: Update both cache-buster strings. Benefit: Hero image renders; page gets every JS fix since August. Effort: Trivial. Definition of done: `document.styleSheets` on `/dev/` shows the current version and a matching `.dev-hero` rule.

#### ***Add an external-link cue to booking CTAs***

Related findings: UX-02 Action: Add an icon or microcopy plus the existing page-transition fade before the STAAH redirect. Benefit: Smoother, more trustworthy hand-off at the highest-intent moment in the funnel. Effort: Small. Definition of done: Every booking CTA shows a consistent "leaving our site" affordance before navigating away.

### 60-day improvements

#### ***Reduce homepage first-visit weight***

Related findings: PERF-01, PERF-02 Action: Convert the display font to WOFF2; evaluate a lighter/shorter mobile-specific hero-video encode. Benefit: Faster homepage load, especially on mobile/cellular. Effort: Medium. Dependencies: Owner sign-off on any visible quality trade-off for the video. Definition of done: Font served as WOFF2 with no visual change; a documented decision recorded on the video encode.

#### ***Improve desktop navigation coverage***

Related findings: UX-03 Action: Add Facilities (and optionally Press/Testimonials via a grouped menu) to the desktop header. Benefit: Reduces clicks to three currently under-surfaced pages. Effort: Small. Definition of done: Desktop header nav includes a path to all 9 primary pages within one click or one dropdown.

#### ***Add rich-snippet-ready review schema***

Related findings: SEO-03 Action: Add `aggregateRating` to the existing `Resort` JSON-LD. Benefit: Potential star-rating display in search results. Effort: Small. Definition of done: Structured data validates and includes `ratingValue/reviewCount` sourced from the live aggregate.

### 90-day improvements

***Reduce structural risk of manual versioning***

Related findings: TECH-01, TECH-03 Action: Introduce a minimal build step or server-side include for the shared `<head>` /version block across all 11 HTML files, so a version bump only needs to happen in one place. Benefit: Makes the exact class of bug found in TECH-01 structurally impossible going forward. Effort: Medium (one-time setup; no framework rewrite implied). Dependencies: Hosting must support the chosen approach (server-side includes or a lightweight static-site build). Definition of done: All 11 pages read their CSS/JS version from one source of truth.

***Restyle the third-party reviews widget to match brand***

Related findings: VIS-03 Action: Use Elfsight's theme editor to bring border-radius, font, and accent color closer to the site's tokens. Benefit: A fully consistent visual experience through the entire homepage. Effort: Small-medium (dashboard work, some trial and error). Definition of done: Widget visually reads as part of the site rather than an embedded third-party block.

## 20. Recommended Design System

The site already has a real, documented design system (the project's own `color-scheme.md`); the recommendation here is to keep it as the single source of truth and close the two gaps below rather than introduce a new system.

### Color tokens (existing, confirmed live)

| Token                                                                          | Hex                         | Confirmed role                                                           |
|--------------------------------------------------------------------------------|-----------------------------|--------------------------------------------------------------------------|
| <code>--nvr-sage-brass-deep</code>                                             | #2F3919                     | Nav/footer background                                                    |
| <code>--nvr-forest</code>                                                      | #66491C                     | Primary CTA buttons, headings                                            |
| <code>--nvr-moss</code>                                                        | #8AA54C                     | Base brand green — links, icons                                          |
| <code>--nvr-clay</code>                                                        | #96631F                     | Secondary buttons, form-error text (confirmed ~5.05:1 contrast on cream) |
| <code>--nvr-ink</code> / <code>--nvr-charcoal</code>                           | #34301F / #453F29           | Body/heading text                                                        |
| <code>--nvr-paper</code> / <code>--nvr-cream</code> / <code>--nvr-linen</code> | #FDFEF8 / #F8FAF0 / #F1F5E2 | Page/card/section backgrounds                                            |

Gap already identified in the project's own token file: only two brown tokens exist (forest, clay) with no light/mid tint for hover states — flagged there as a known, deliberate placeholder for future work, not re-litigated here.

### Typography

- **Display/script** (Fraunces italic or a custom cursive) — emotive headline moments only (hero H1, section intros).
- **Serif** (Fraunces) — section H2/H3 headings.
- **Sans** (Manrope/Poppins) — body copy, labels, buttons, navigation.

Recommendation: formalize this three-tier hierarchy (which already exists in practice) as named tokens ( `--nvr-font-display` , `--nvr-font-heading` , `--nvr-font-body` ) if not already literally named that way in source, purely for future-maintainer clarity — no visual change implied.

### Spacing, radius, and breakpoints

Confirmed gap (repo-documented, re-flagged here): the stylesheet uses roughly 20 distinct `@media` breakpoint values with no shared scale.  
Recommendation: consolidate toward the seven widths this audit itself was asked to validate against — 320 / 375 / 414 / 768 / 1024 / 1280 / 1440 — as the canonical set for any new component, so future responsive work has a fixed reference instead of picking a new arbitrary breakpoint each time.

### Button variants (confirmed, currently in use)

- **Primary (filled):** forest/moss background, white/cream text, rounded pill shape — "Reserve Your Stay."
- **Secondary (outline):** transparent background, bordered, same pill radius — "Discover Your Room."
- **Icon-only (floating):** circular, brand-green, persistent booking shortcut.
- **Gap:** the mobile menu toggle does not follow any of the three patterns above (VIS-02) — recommend it adopt the icon-only circular/borderless treatment.

## 21. Recommended Technical Improvements

---

1. **Single source of truth for the cache-buster version** (see Section 19, 90-day) — directly prevents a repeat of TECH-01.
2. **WOFF2 for the custom display font** (PERF-02) — no build tooling required, a one-time conversion.
3. **Host-specific `robots.txt` / `X-Robots-Tag` for the staging hostname** (SEO-01) — a hosting-panel or server-config change, not an application change.
4. **Add `aggregateRating` to the existing Resort JSON-LD** (SEO-03) — extend an object that already exists.
5. **Consolidate the two forms' validation logic** if any further form work is planned (repo-documented as near-duplicate code between Contact and the Events form) — not urgent on its own, but worth doing opportunistically the next time either form is touched, to avoid fixing the same bug twice.
6. **Consider Cross-Origin-Opener-Policy / Cross-Origin-Resource-Policy headers** as optional defense-in-depth (SEC-01) — low priority given the current CSP is already strong and the site has no cross-origin embedding requirements.

## 22. QA Regression Checklist

Use this checklist after implementing any items from Sections 18-19, before considering them closed.

| Check                      | Pass criterion                                                                                                                             | Related finding  |
|----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------|------------------|
| robots.txt on staging host | User-agent: * is fully disallowed on this exact hostname                                                                                   | SEO-01           |
| Footer phone links         | Every page's footer mobile numbers are real tel: anchors (DOM query for zero non-linked numbers)                                           | A11Y-02          |
| Reviews widget scale       | All four rating figures share one clearly labeled scale                                                                                    | CONT-01          |
| /about/ heading order      | h1,h2,h3... sequence has no level skip                                                                                                     | A11Y-01          |
| /press/ mailto link        | Link is distinguishable from body text by more than color alone (underline/weight)                                                         | A11Y-03          |
| /dev/ asset versions       | Version query string matches the current site-wide version; .dev-hero background renders                                                   | TECH-01, FUNC-05 |
| Booking CTA transition     | Visible external-link cue present before STAAH redirect on Home, Accommodations, Contact                                                   | UX-02            |
| Font format                | Display font served as WOFF2; no visible rendering change                                                                                  | PERF-02          |
| Structured data            | JSON-LD on Home still validates after adding aggregateRating; no parse errors                                                              | SEO-03           |
| Full regression sweep      | Zero console errors and zero horizontal overflow at 320/375/414/768/1024/1280/1440px on all 9 primary pages, re-run after any change above | All              |

## 23. Top 10 Action List

---

1. Block all crawlers in `robots.txt` on this staging hostname (SEO-01) — protects the real domain's search presence.
2. Add `tel:` links to the footer's phone numbers, site-wide (A11Y-02) — direct conversion fix.
3. Fix the Booking.com rating-scale display in the Elfsight dashboard (CONT-01) — restores trust-signal clarity.
4. Bump the two stale version strings in `dev.html` (TECH-01 / FUNC-05) — trivial, fully root-caused fix.
5. Promote `/about/`'s card headings from h3 to h2 (A11Y-01) — trivial accessibility fix.
6. Extend the underline rule to the `/press/` `mailto` link inside the enquiries list (A11Y-03) — trivial accessibility fix.
7. Add an external-link cue before every booking-engine redirect (UX-02) — smooths the highest-intent moment in the funnel.
8. Convert the custom display font to WOFF2 (PERF-02) — free performance win, zero visual change.
9. Add `aggregateRating` to the existing Resort structured data (SEO-03) — rich-snippet opportunity.
10. Surface Facilities in the desktop header navigation (UX-03) — reduces clicks to three under-surfaced pages.

## 24. Appendix — URLs, Evidence, and Test Conditions

### URLs audited

|                                                                                                                                       |                   |
|---------------------------------------------------------------------------------------------------------------------------------------|-------------------|
| <a href="https://teal-raven-684541.hostingersite.com/">https://teal-raven-684541.hostingersite.com/</a>                               | Home              |
| <a href="https://teal-raven-684541.hostingersite.com/about/">https://teal-raven-684541.hostingersite.com/about/</a>                   | About             |
| <a href="https://teal-raven-684541.hostingersite.com/accommodations/">https://teal-raven-684541.hostingersite.com/accommodations/</a> | Accommodations    |
| <a href="https://teal-raven-684541.hostingersite.com/function-rooms/">https://teal-raven-684541.hostingersite.com/function-rooms/</a> | Function Rooms    |
| <a href="https://teal-raven-684541.hostingersite.com/facilities/">https://teal-raven-684541.hostingersite.com/facilities/</a>         | Facilities        |
| <a href="https://teal-raven-684541.hostingersite.com/restaurant/">https://teal-raven-684541.hostingersite.com/restaurant/</a>         | Restaurant        |
| <a href="https://teal-raven-684541.hostingersite.com/press/">https://teal-raven-684541.hostingersite.com/press/</a>                   | Press             |
| <a href="https://teal-raven-684541.hostingersite.com/testimonials/">https://teal-raven-684541.hostingersite.com/testimonials/</a>     | Testimonials      |
| <a href="https://teal-raven-684541.hostingersite.com/contact/">https://teal-raven-684541.hostingersite.com/contact/</a>               | Contact           |
| <a href="https://teal-raven-684541.hostingersite.com/dev/">https://teal-raven-684541.hostingersite.com/dev/</a>                       | Site Credits      |
| <a href="https://teal-raven-684541.hostingersite.com/robots.txt">https://teal-raven-684541.hostingersite.com/robots.txt</a>           | Robots directives |
| <a href="https://teal-raven-684541.hostingersite.com/sitemap.xml">https://teal-raven-684541.hostingersite.com/sitemap.xml</a>         | XML sitemap       |
| (any invalid path)                                                                                                                    | Custom 404 page   |

### Test conditions

- **Browser:** Chromium, automated, single session, September 16, 2026.
- **Viewports tested:** 320×700, 375×700, 414×800, 768×1024, 1024×900, 1280×900, 1440×900.
- **Network:** ambient connection of the testing environment; not throttled to simulate 3G/4G. Performance figures in Section 13 should be read as a lower bound, not a worst-case mobile figure.
- **Cache state:** mixed — some resource-timing figures in Section 13 reflect a session where the homepage had been visited more than once; this is noted there and does not affect the encoded/decoded byte-size figures, which are cache-independent.

### Screenshots captured (referenced throughout this report)

|                                                                                       |                                |
|---------------------------------------------------------------------------------------|--------------------------------|
| home-320.png, home-375.png, home-768.png, home-1024.png, home-1280.png, home-1440.png | Home, full 7-width sweep       |
| home-375-menu-open.png                                                                | Mobile drawer open             |
| accom-320.png, accom-375.png, accom-768.png, accom-1440.png                           | Accommodations, full sweep     |
| accom-modal-375.png                                                                   | Room-detail modal              |
| about-375.png, about-1440.png                                                         | About, spot check              |
| contact-375.png, contact-validation.png                                               | Contact, form validation       |
| funcrooms-375.png, facilities-375.png, restaurant-375.png, press-375.png              | Spot checks                    |
| restaurant-menu-viewer-375.png                                                        | PDF menu viewer                |
| reviews-widget-1440.png                                                               | Reviews widget rating mismatch |
| 404-375.png                                                                           | Custom 404 page                |
| dev-page.png, dev-1440.png                                                            | /dev/ hero-image regression    |

### Assumptions made explicit

- The production/canonical domain is assumed to be `naturesvillageresort.com`, based on every page's own canonical tag, Open Graph URL, and structured-data `url` field all agreeing on it. This audit does not have DNS access to confirm whether that domain is currently live, parked, or already pointed at this same Hostinger deployment.
- Where this report cites the project's own internal audit history ( `audit-reports/STATIC_WEBSITE_AUDIT_REPORT.md` ), it is explicitly labeled "repo-confirmed" or "carried forward" and is not presented as independently re-verified unless this session's own live testing is cited alongside it.
- No claim is made about current search-engine indexing status of either domain; Section 12 explicitly flags this as unverifiable in this environment.