
11 Nov 2026


Ground cover without green islands

Partial vegetation cover keeps soil visible instead of forming sharp, flat green ovals.

BEFORE



AFTER



GROUND DETAIL / same original pixels, enlarged





The cover blend now uses its physical area fraction; the existing soil and vegetation textures remain.

Tree visibility was inspected at 40, 80, 140 and 250 m using one generated tree; trees remain visible beyond 100 m.


Playable repair build; performance work remains unfinished.
Earlier focused tests averaged 110-166 FPS; first-view stalls and the 100 FPS floor remain unresolved.

Original game captures; matched world, camera, daylight and terrain preset.


Cliff lighting without the comb pattern

The inspected canyon walls keep their original geometry and collision surface; lighting normals are filtered in both directions.


BEFORE




AFTER



WALL DETAIL / same original pixels, enlarged





A native channel-edge case reduced an 11.35 cm raw mesh mismatch to 0.015 mm after the renderer's edge fitting.

Collision contact matched the fitted surface. These are representative inspected locations; the world-wide 100 FPS floor is not certified.

Playable repair build; performance work remains unfinished.
Earlier focused tests averaged 110-166 FPS; first-view stalls and the 100 FPS floor remain unresolved.

Original game captures; matched world, camera, daylight and terrain preset.