

Forest placement repair

Inland rainforest | same location and camera | playable checkpoint, remaining work noted below



Before: straight gaps between compressed planting blocks



Now: mixed species across the correct planting footprint


Placement. Shared near/far tree identities, locally suitable per-tree species, and corrected planting footprints remove the straight rows. All 551 forest fields were present at first reveal and unchanged 20 seconds later.

Loading. Same-site entry fell from 48.3s to 21.5s after terrain setup. Reused physical support and resolved pond candidates eliminate repeated terrain queries. World reading and worker startup are additional; this is still too slow.

Checks. Actual CPU/GPU rendered positions agree within 0.05 pixels; the 600m/s route had no ground-coverage gaps. Camera-turn and shadow visibility checks pass. The recurring one-second vegetation rebuild fell from 12 occurrences to zero in a 12-second turn.

Performance. 1080p, maximum terrain, Medium vegetation, 6km view: about 118-122 FPS average; worst frames 19-28ms. Another Codex was running. No reliable overall FPS gain or 100-FPS floor is claimed. Movement/GC spikes remain.

Distant forest review



1,500m above ground, 20km view. The owner moved during this scenic review; this image is a visual example, not a stationary comparison. Beyond about 6km, forest uses canopy-colored terrain without tree silhouettes. Improving that distant representation, faster entry and remaining frame spikes are deferred.