



W07 affected yield by die

Wafer W07 · Lot L2407 · Tool ETCH-08 · Chamber A · Recipe REC-17 · Process Etch
4 observations · 1 missing · Value 0 to 98.1



W07 signed affected – reference

Wafer W07 · Lot L2407 · Tool ETCH-08 · Chamber A · Recipe REC-17 · Process Etch
4 observations · 1 missing · Delta -5 to +2



Etch chamber RCA