


Line Chart




Action	Owner	Due	Status
Verify etch chamber	Process Eng.	Sep 30	Open
Review inline sampling	Quality	Oct 02	In progress

Risk Callout

Project Card


Process Flow



Etch chamber RCA

W07 affected yield by die

Wafer W07 · Lot L2407 · Tool ETCH-08 · Chamber A · Recipe REC-17 · Process Etch
4 observations · 1 missing · Value 0 to 98.1



W07 signed affected – reference

Wafer W07 · Lot L2407 · Tool ETCH-08 · Chamber A · Recipe REC-17 · Process Etch
4 observations · 1 missing · Delta -5 to +2

