Flood situation report

Area: No-flood check: Trishuli corridor, 25 Jul 2026 | Event date: 25 July 2026 | Latest radar image: 4 August 2026


1. Where it flooded

Satellite images show 112 ha (1.12 km²) flooded or buried by debris. F010 F011

Of this, 5.2 ha is open water and 107 ha is debris or scour. F012 F014

The radar could not see 10,889 ha because of terrain shadow, so conditions there are unknown. F016

The places with the most buildings likely destroyed: Madanpur, Galchhi, Nuwakot, Batar Bajar. F048



Radar change map, before and after the event.

2. What was hit

Buildings: 102 likely destroyed and 45 possibly damaged, out of 188,933 mapped. F025 F021 F022

Roads: 2.5 km of road lies under mapped debris or water; the road sections that touch it total 6.5 km, out of 7,412.1 km mapped. F039 F033 F037

Bridges: 0 likely destroyed and 0 possibly damaged, out of 353 mapped. F031 F027 F028

3. Who is cut off

None of the 397 settlements analysed appear cut off by road. F050 F049

OpenStreetMap lists 25 health facilities in the area (hospitals, health posts and clinics); its labels are not verified. F2351 F2352

Repair priority

No results in this run.

Method

Sentinel-1 radar images from before and after the event are compared to map new water and debris. Pre-event OpenStreetMap roads, bridges and buildings are overlaid, and a road network model finds settlements that can no longer reach a health facility.

Educational prototype, not an operational tool. Numbers come from satellite analysis and have not been checked on the ground.

Grey codes such as F012 point to entries in facts.json.

Contains modified Copernicus Sentinel data 2026.
Produced using Copernicus WorldDEM-30 © DLR e.V. 2010–2014 and © Airbus Defence and Space GmbH 2014–2018 provided under COPERNICUS by the European Union and ESA; all rights reserved.
© OpenStreetMap contributors.