ojoshy club member





Postings: 154

Living in city: Leverkusen My favorite computer: CBM8032

Brief test report - SGC Tools 1.8 Demo

Environment:

C128D with 16kB VDC RAM


columns on C1901 Monitor

Testdisk image copied with ZoomFloppy onto a disk

C128 booted from Testdisk without problems

Test:

Basic Menu window opened without problem









Test C (no screenshot) Sound played correctly

Test D 80x50 interlaced text displayed correctly




Test E monochome Grafik displayed correctly (16kb VDC)



Test F was a bit surprising. The first two runs did show the picture with some black scan lines. Then I tried CONTROL + RUN/STOP and after this the picture was loaded and shown correctly (screen shots below)

With black scanlines sporadically in the picture



Without black scanlines (after several tries with control + run/stop)



A last test will follow with a C128 with 64kB VDC RAM, stay tuned.