

Site #4344: AVONDALE #1B, Jefferson, Louisiana

23.6 MW

Entergy Louisiana




Fiber Infrastructure

Fiber Carrier	AT&T, Cox Communications, Lumen, Zayo, EarthLink
Distance to Backbone	~2–5 mi
Fiber Lateral Required	~2–4 mi
Number of Upstream Routes	3–4
Upstream Capacity	1–4 Tbps
Nearest Carrier Facility	New Orleans CBD (~12 mi east)


Nearest Substation: ~ 2 Miles

Power Infrastructure Capacity




Site #4344: AVONDALE #1B, Jefferson, Louisiana

SITE CHANGE DETECTION & BASELINE MONITORING



ACCESS ROUTE & SITE CONDITION ASSESSMENT		
Assessment Item	Status	Risk Level
Access Road Condition	Fair	●
Road Obstructions	Moderate	●
Post-Storm Accessibility	Partially Accessible	●
Gate Access Visibility	Clear	●
Parking / Staging Area	Available	●
Overall Access Status: LIMITED ACCESS		


VEGETATION & ENCHROACHMENT MONITORING		
Monitoring Category	Observation	Risk Level
Vegetation Growth (25 ft)	Clear (0%)	●
Vegetation Growth (50 ft)	High (40.4%)	●
Vegetation Growth (100 ft)	High (46.3%)	●
Fence Line Encroachment	None	●
Access Road Overgrowth	Critical	●
Tree Canopy Expansion	High	●
Fire Fuel Accumulation	High	●
Vegetation Risk Level: High		




- SITE CHANGE HIGHLIGHTS
- No significant changes to the primary site infrastructure were observed between the baseline and current imagery.
 - No visible missing or damaged antenna-related assets were identified from the available imagery.
 - Additional unidentified objects were observed within the site compound compared to the baseline imagery.
 - Vegetation encroachment is present within the 50-ft assessment area and may require routine maintenance.

Overall Monitoring Result: Limited Access with High Vegetation Risk

Evidence on the Ground



Nearest Parking: ~ 0.5 Miles



Veg. Encroachment



Gate Accessibility