

VERDICT: MATCH (85% MATCH CONFIDENCE)

AI assessment verified: Claimed damage on Hood strongly aligns with detected damage patterns (85% confidence match).
Proceed to automated settlement.

Policyholder Information	Vehicle Details
Name: Alex Johnson Email: user@secureclaim.com Claim Type: Collision Damage	Model: 2023 Honda Civic Sedan Registration: KA-01-MJ-8821 Claimed Part: Hood

Claim Discrepancy & Cross-Check Matrix

Parameter	Claimed by Policyholder	Detected by AI Vision	Status
Damaged Component	Hood	Front Right Door, Front Bumper	Discrepancy
Damage Severity	Moderate	Severe, Minor	Differing
Description Summary	Brushed against a parking garage pillar while parallel parking, causing a dent and scratch...	2 damage region(s) identified with segmentation masks	85% Alignment


Itemized Damage & Repair Cost Breakdown

#	Part	Damage Type	Severity	AI Confidence	Est. Cost Range
1	Front Bumper	Dent	Severe	94%	\$28,000 – \$55,000
2	Front Right Door	Dent	Minor	84%	\$4,500 – \$8,500
TOTAL					All Identified Damage
					\$32,500 – \$63,500

Photographic Evidence & AI Segmentation Overlay

Uploaded Photo (Original)

AI Damage Segmentation Mask



DIGITALLY VERIFIED

Certified by SecureClaim AI Neural Vision Engine v2.4

Cryptographic Checksum: SHA256-OK

Settlement Recommendation: Match

This assessment is generated automatically according to Underwriting

RuleSet 2026.4.