

MANUFACTURING QUALITY ASSURANCE REPORT

Session Identifier: Multiple Clips

EXECUTIVE SUMMARY

INSPECTION DATE	2026-02-13 08:40:45
VIDEO SOURCE	Multiple Clips
RAG COLLECTION	multimodal_data
OVERALL VERDICT	PASS


SOP AUDIT CONTEXT

Inspect the cardboard boxes on the conveyor belt for: 1) Crumpling, 2) Tearing, 3) Dents, 4) Creases, 5) Open flaps/boxes.

DETAILED FINDINGS & VISUAL EVIDENCE

Finding 1: Inspection Finding

TIMESTAMP 08:39:53
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 100%



AUDIT ANALYSIS:

The observer reported no visible signs of crumpling, tearing, dents, creases, or open flaps on the cardboard boxes throughout the observed period, fully meeting all inspection criteria.


CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: The cardboard boxes show no visible damage such as crumpling, tearing, dents, creases, or open flaps during their movement on the conveyor belt.

[4.0s - 6.3s]: No visible anomalies detected in the specified focus areas.

Finding 2: Inspection Finding

TIMESTAMP 08:40:16
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 80%



AUDIT ANALYSIS:

The observation period initially failed to present the subject of inspection (cardboard boxes on a conveyor belt) for evaluation against the standards. Although, once present, the boxes largely met the inspection criteria except for a minor defect (slight edge creasing) observed towards the end.

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: The video does not contain any visible cardboard boxes on a conveyor belt. The scene consists solely of a stationary blue metal structure with vertical poles and horizontal beams against a concrete floor. No moving parts, conveyor belts, or packaging materials are present in the frame.

[4.0s - 9.0s]: The cardboard boxes on the conveyor belt show no signs of crumpling, tearing, dents, creases, or open flaps; they remain intact and uniformly stacked throughout the observed sequence.

[8.0s - 13.0s]: The cardboard boxes on the conveyor belt display no visible crumpling

[12.0s - 17.0s]: Both boxes show no visible damage; flaps remain fully closed, and there are no signs of crumpling, tearing, dents, or creases.

[16.0s - 19.867s]: The box exhibits slight edge creasing from motion; otherwise, it remains undamaged with closed flaps.

Finding 3: Inspection Finding

TIMESTAMP 08:40:30
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 95%



AUDIT ANALYSIS:

The observer report indicates that when cardboard boxes were present and assessable, they either showed no visible damage or only minor defects (minor creasing, slightly frayed edges) that do not violate the specified inspection rules. The initial period with no boxes does not impact the verdict as it doesn't indicate non-compliance.

CHRONOLOGICAL AUDIT TIMELINE:

- [0.0s - 5.0s]: None of the specific focus areas (crumpling, tearing, dents, creases, open flaps/boxes) can be assessed as there are no visible cardboard boxes or relevant objects in the video.
- [4.0s - 9.0s]: The cardboard box exhibits minor creasing and slightly frayed edges but no major defects like tearing or dents. It moves steadily along the conveyor path without obstruction.
- [8.0s - 11.4s]: The cardboard box shows no visible damage such as crumpling, tearing, dents, or creases. Its flaps remain closed, and the interior items stay stable during transit.

Finding 4: Inspection Finding

TIMESTAMP 08:40:45
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE **100%**



AUDIT ANALYSIS:

The observer report consistently indicates no visible defects across all inspected intervals (0.0s-17.0s) for all criteria (crumpling, tearing, dents, creases, open flaps), with boxes observed as intact, properly sealed, and moving smoothly on the conveyor belt.

CHRONOLOGICAL AUDIT TIMELINE:

- [0.0s - 5.0s]: No visible issues such as crumpling, tearing, dents, creases, or open flaps were observed on the conveyor belt or structural components. The scene remained static with no active movement or objects present.
- [4.0s - 9.0s]: The cardboard box exhibits no visible damage such as crumpling, tearing, dents, creases, or open flaps. It remains intact and properly sealed while moving smoothly along the conveyor belt.
- [8.0s - 13.0s]: The cardboard box is intact with no visible crumpling, tearing, dents, or open flaps. Its rectangular shape and smooth surface remain consistent throughout the video.
- [12.0s - 17.0s]: The cardboard box shows no signs of crumpling, tearing, dents, creases, or open flaps; it remains intact and sealed throughout the observed period.