

MANUFACTURING QUALITY ASSURANCE REPORT

EXECUTIVE SUMMARY

INSPECTION DATE	2026-02-13 10:14:23
VIDEO SOURCE	stream_6bb9997b_2026-02-13T10-12-18.553866Z_st_0.000_end_6.267_clip_1.mp4, stream_6bb9997b_2026-02-13T10-12-18.553866Z_st_9.967_end_29.800_clip_2.mp4, stream_6bb9997b_2026-02-13T10-12-18.553866Z_st_35.367_end_46.733_clip_3.mp4, stream_6bb9997b_2026-02-13T10-12-18.553866Z_st_53.067_end_70.033_clip_4.mp4
OVERALL VERDICT	FAIL

SUMMARY: The inspection series showed mixed compliance, with two events meeting all standards perfectly, but two others revealing significant defects (Event 3: multiple defects; Event 4: implied severe deformation). Overall, the presence of clear, rule-violating defects in half of the events leads to a fail. Compliance was highly inconsistent across observed events.

PROJECTED IMPROVEMENTS

- Implement stricter quality control to eliminate crumpling, creases, and open flaps as observed in Event 3.
- Clarify inspection rules to explicitly define and penalize 'partial collapse' or similar severe deformations as seen in Event 4.
- Enhance observer consistency to accurately apply scoring, given the discrepancy in scoring logic between fully compliant and partially defective events.

POSITIVE HIGHLIGHTS

- Events 1 and 2 demonstrated perfect compliance with all inspection standards, indicating capable quality control processes when functioning optimally.
- In Event 3, the absence of tearing and dents in all observed boxes shows some aspect of box handling or manufacturing is meeting standards.
- The majority of the observation period in Event 4 initially showed compliance, suggesting that under normal conditions, boxes meet the primary inspection criteria.


SOP AUDIT CONTEXT

Inspect the cardboard boxes on the conveyor belt for: 1) Crumpling, 2) Tearing, 3) Dents, 4) Creases, 5) Open flaps/boxes.

DETAILED FINDINGS & VISUAL EVIDENCE

Finding 1: Inspection Finding

TIMESTAMP 10:13:26
SOP SECTION Packaging & Shipping Standards
COMPLIANCE SCORE **100%**



AUDIT ANALYSIS:

Both observed time frames indicate no signs of crumpling, tearing, dents, creases, or open flaps on the cardboard boxes, fully complying with all inspection rules.


CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: Neither box shows any visible signs of damage. Both boxes maintain their structural integrity without any crumpling, tearing, dents, or creases. All flaps remain closed and undamaged.

[4.0s - 6.3s]: The cardboard box on the conveyor belt shows no visible signs of damage: it is intact without crumpling, tearing, dents, creases, or open flaps.

Finding 2: Inspection Finding

TIMESTAMP 10:13:41
SOP SECTION Packaging & Shipping Standards
COMPLIANCE SCORE **100%**



AUDIT ANALYSIS:

The observer report indicates no visible defects (crumpling, tearing, dents, creases, or open flaps) on any cardboard boxes observed throughout the entire video timeline. Although the initial scene showed an empty conveyor belt, subsequent observations confirmed intact boxes meeting all inspection criteria.

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: The video does not show any cardboard boxes, crumpling, tearing, dents, creases, or open flaps on the conveyor belt. The scene shows a stationary blue metal structure and an empty floor with white markings, indicating no active packaging or movement in the captured timeframe.

[4.0s - 9.0s]: No visible anomalies detected in the cardboard boxes; they appear intact with no signs of crumpling, tearing, dents, creases, or open flaps.

[8.0s - 13.0s]: No instances of crumpling, tearing, dents, creases, or open flaps detected on either cardboard box during the observed sequence.

[12.0s - 17.0s]: Neither box exhibits noticeable crumpling, tearing, dents, or creases; both remain intact with closed flaps. The leading box is slightly tilted relative to the trailing one but retains its rectangular form.

[16.0s - 19.867s]: The cardboard box remains intact with no visible damage; it shows no crumpling, tearing, dents, or creases, and all flaps are securely closed.

Finding 3: Inspection Finding

TIMESTAMP 10:13:58
SOP SECTION Packaging & Shipping Standards
COMPLIANCE SCORE 60%



AUDIT ANALYSIS:

The inspection revealed multiple defects across observed boxes, including crumpling, creases, and open flaps, which violate the inspection rules. Although not all boxes were defective (initial period with no boxes) and some defects were described as 'slight', the presence of defects in the observed boxes leads to an overall fail. The absence of tearing and dents in all observed boxes partially mitigates the score.

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No cardboard boxes are present on the conveyor belt; therefore, no assessment of crumpling, tearing, dents, creases, or open flaps can be provided.

[4.0s - 9.0s]: The inspected cardboard box displays **crumpling** around its edges and corners, **creases** along fold lines, and **open flaps** (implied by the interaction with the robotic arm). No tearing or dents are observed.

[8.0s - 11.4s]: The cardboard boxes exhibit slight crumpling and noticeable creases after colliding on the conveyor belt. No tearing or dents are present.

Finding 4: Inspection Finding

TIMESTAMP 10:14:16
SOP SECTION Packaging & Shipping Standards
COMPLIANCE SCORE 80%



AUDIT ANALYSIS:

Although the majority of the observation period showed compliance with all inspection rules, a critical defect (partial collapse) was observed, indicating a failure to maintain structural integrity, which is implied necessary for passing despite not being explicitly listed. However, since 'partial collapse' isn't explicitly defined in the rules but implies a severe form of 'crumpling' or 'deformation not listed', and given the primary rules were mostly met, a high compliance score is still awarded.

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No observable instances of crumpling, tearing, dents, creases, or open flaps on the conveyor belt. No cardboard boxes are present in the frame.

[4.0s - 9.0s]: No observable anomalies or defects in the cardboard box related to the specified criteria (crumpling, tearing, dents, creases, open flaps). The box moves smoothly along the conveyor belt without deformation or damage.

[8.0s - 13.0s]: The cardboard box exhibits slight tilting and partial collapse as it slides along the conveyor belt, but shows no visible crumpling, tearing, dents, creases, or open flaps prior to this deformation.

[12.0s - 17.0s]: No visible anomalies detected; the cardboard box remains intact without crumpling, tearing, dents, creases, or open flaps.