

MANUFACTURING QUALITY ASSURANCE REPORT

EXECUTIVE SUMMARY

INSPECTION DATE	2026-02-13 12:36:00
VIDEO SOURCE	stream_08e6711e_2026-02-13T12-34-17.314563Z_st_0.000_end_6.267_clip_1.mp4, stream_08e6711e_2026-02-13T12-34-17.314563Z_st_9.967_end_29.800_clip_2.mp4, stream_08e6711e_2026-02-13T12-34-17.314563Z_st_35.367_end_46.733_clip_3.mp4, stream_08e6711e_2026-02-13T12-34-17.314563Z_st_53.067_end_70.033_clip_4.mp4
OVERALL VERDICT	FAIL

SUMMARY: The inspection series failed to meet the standards due to recurring minor defects (dents, creases) across multiple events, despite mostly compliant observations. Incomplete visibility in one event raised additional compliance concerns. Overall, non-compliance with rules 3 and 4 was noted in two events.

PROJECTED IMPROVEMENTS

- Enhance quality control to eliminate minor dents and creases, ensuring stricter adherence to rules 3 and 4.
- Improve conveyor belt monitoring to ensure continuous visibility of cardboard boxes for accurate assessment.
- Establish clear guidelines on the severity threshold for defects to guide verdict decisions (e.g., defining 'minor' defects' impact on overall verdict).

POSITIVE HIGHLIGHTS

- Event 1 demonstrated perfect compliance with all inspection standards, showcasing capability for flawless output.
- No critical failures (tearing, open flaps, or crumpling) were observed across all inspected events, indicating strong adherence to high-priority rules.
- The majority of observations across events indicated a high level of adherence to the specified standards, highlighting overall process effectiveness.


SOP AUDIT CONTEXT

Inspect the cardboard boxes on the conveyor belt for: 1) Crumpling, 2) Tearing, 3) Dents, 4) Creases, 5) Open flaps/boxes.

DETAILED FINDINGS & VISUAL EVIDENCE

Finding 1: Inspection Finding

TIMESTAMP 12:35:07
SOP SECTION Packaging & Shipping Standards
COMPLIANCE SCORE 100%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No anomalies or artifacts detected.

[4.0s - 6.3s]: The cardboard box on the conveyor belt shows no visible crumpling, tearing, dents, or excessive creases. Its flaps remain closed and intact.

Finding 2: Inspection Finding

TIMESTAMP 12:35:23
SOP SECTION Packaging & Shipping Standards
COMPLIANCE SCORE 80%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No instances of the specified defects (crumpling, tearing, dents, creases, open flaps) were observed as no cardboard boxes were present in the video.

[4.0s - 9.0s]: No anomalies or artifacts detected. Cardboard boxes show no signs of crumpling, tearing, dents, creases, or open flaps during the observed motion.

[8.0s - 13.0s]: No anomalies detected. Cardboard boxes remain intact and properly aligned throughout the observed sequence.

[12.0s - 17.0s]: No significant anomalies observed. Cardboard boxes display minor dents and creases but remain intact without tearing or open flaps.

[16.0s - 19.867s]: No visible damage such as crumpling, tearing, dents, creases, or open flaps.

Finding 3: Inspection Finding

TIMESTAMP 12:35:38
SOP SECTION Packaging & Shipping Standards
COMPLIANCE SCORE **50%**



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:


[0.0s - 5.0s]: No cardboard boxes are visible in the video; therefore, no assessment of crumpling, tearing, dents, creases, or open flaps can be made. The scene consists solely of blue metal structural components and a gray floor.

[4.0s - 9.0s]: The cardboard box shows signs of creasing and slight deformation due to movement along the conveyor belt, but no tearing, dents, open flaps, or crumpling is observed.

[8.0s - 11.4s]: No anomalies or artifacts present.

Finding 4: Inspection Finding

TIMESTAMP 12:35:53
SOP SECTION Packaging & Shipping Standards
COMPLIANCE SCORE **80%**



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No relevant features observed.

[4.0s - 9.0s]: The cardboard box exhibits minor creasing around its edges and corners but remains intact with closed flaps and no visible tears or dents.

[8.0s - 13.0s]: The cardboard box shows no visible signs of crumpling, tearing, dents, creases, or open flaps; it remains intact and consistently shaped throughout the video.

[12.0s - 17.0s]: The cardboard box shows no visible signs of crumpling, tearing, dents, or creases. Its flaps remain closed and intact throughout the movement.

