

EV Battery Analysis Report

Generated On: 24-06-2026 17:03:16

Executive Summary

Metric	Value
Latest SoC	89.85%
Latest SoH	94.37%
Latest Voltage	390.8 V
Maximum Temperature	41.34 °C
Battery Health	Good
Charging Duration	2.3 Hours
Overall Status	Normal Operation

Dataset Information

Number of Records: 8640

Start Time: 2026-05-15 00:00:00

End Time: 2026-05-15 23:59:50

Battery Health Summary

Latest SoC: 89.85%

Minimum SoC: 87.08%

Maximum SoC: 89.88%

Latest SoH: 94.37%

Battery Health Status: Good

Charging Analysis

Total Charging Duration: 2.3 hours

Charging Activity Status: Moderate charging activity

State of Charge Trend




Figure 1: State of Charge variation over time.

Voltage Analysis

Battery Voltage Over Time




Figure 2: Battery pack voltage variation over time.

Voltage ranged from 376.52 V to 397.71 V.

Current Analysis

Battery Current Over Time




Figure 3: Battery pack current variation over time.

Maximum discharge current: 18.93 A

Maximum charging current: -254.19 A

Temperature Analysis

Battery Temperature Over Time




Figure 4: Battery pack temperature variation over time.

Maximum battery temperature recorded was 41.34 °C.

Temperature Status: Normal

Alerts and Warnings

No critical alerts detected.

Conclusion

The battery operated with a maximum temperature of 41.34°C, maintained a State of Health of 94.37%, and showed moderate charging activity. Overall battery condition was assessed as Normal Operation.