

Accessibility Report:

- **Website Name:** Chateau de Chantilly Cafe is a Cafe in Chantilly, VA 20151
- **URL:** <https://chantillybakery.com/>
- **Date Observed:** October 15, 2021
- **By:** Kristie Phan
- **Summary:** For this assignment, I assessed the web accessibility of a local bakery business known as “Chateau de Chantilly Cafe” where the overall accessibility review is adequate seeing how the website has minor errors with distinguishable content. Although WAVE detected some accessibility issues in the Alerts, Structural Elements, and Aria label, some errors detected can be omitted.

The following apply to the entire page:
en-US

powered by WebAIM

Address: https://chantillybakery.com/ Styles: OFF ON

Summary

Errors: 0 Contrast Errors: 1

Alerts: 35 Features: 17

Structural Elements: 15 ARIA: 30

View details >

Chateau de Chantilly BAKERY & COFFEE

Cakes Sandwiches

Criteria Report:

1. **Page Title: PASSED** - Observed six pages in the website's navigation tab that contains good titles in the window bar that briefly describes the content of each page.

Chateau de Chantilly Cafe Serves | Reviews - Chateau de Chantilly | Gallery - Chateau de Chantilly | Contact - Chateau de Chantilly | +

← → ⌂ ⌄ chantillybakery.com


Chateau de Chantilly Cafe Serves | Reviews - Chateau de Chantilly | Gallery - Chateau de Chantilly

Chateau de Chantilly Cafe Serves
Coffee in Chantilly, VA 20151
chantillybakery.com


Blackboard Learn Library Genesis Citation M

- Utilized Google Chrome browser to evaluate the browser tabs.

2. Alternative Text for Images: FAILED - there are two out of fourteen total images on the homepage that don't have an alternative text included in their code as well as fourteen additional images in the “Gallery” page where it matters most as a visual-only page. Alternative text is also missing in each section of the “Our Foods” tab; however, is not important for understanding the content since the subject matter is straightforward as is such as “cake” and “coffee”. The images are also featured on the homepage button attribute while the paragraphs provided on each page are enough to convey purpose.



- Alt Text is necessary for the following images because the first one is a header/banner image which needs visual content at the front page whereas the second one showcases the interior view of the cafe. It may help give the viewers an idea of what to expect when visiting the establishment.
- Other images on the homepage successfully used alternative text appropriately.




- The *Gallery* page is missing alternative text and is necessary to include if the gallery function fails to load. Moreover, the images shown conveys information that is useful to the business's brand applications.


3. Text (Headings): FAILED - There is no meaningful hierarchy in heading where a heading structure is not present throughout the website's code. There are five `<h1>` in the homepage which could be changed to `<h2>` while `<h1>` can be used on the brand name if the developer adds it on the banner image. Or make “Chateau de Chantilly Cafe is a Cafe in Chantilly, VA 20151” as `<h1>` and change the page structure around to put Navigation on top of the Main structure.




- **Text (Contrast Ratio): PASSED w/ one error** - The color contrast of text is good overall. However, there is only one contrast error that needs to be fixed. The original contrast ratio is 1.08:1 where the foreground (text) color can be increased to 7.07:1 (minimum) ratio in order for the WCAG levels to pass.



- **Text (Resize text): PASSED w/ one error** - Increasing the size of text and image is good overall where they get bigger appropriately and none of the content disappears or gets cut off up to 250%. However at 300%, contact information on the navigation overlaps page content and the Navigation bar covers more than half of the screen at 400%+ that makes browsing difficult.



4. Interaction: FAILED - Keyboard access in tab focus is present utilizing tab order and tab-to-all . However, the tab visual set-up to indicate the current location of the tab section is difficult to navigate and is only detected in some areas. There is only a small URL link at the bottom left of the window that helps distinguish where the tab is which may be inconvenient to those who are unable to read small text. This can be easily fixed if the developer includes the tab focus to be highlighted to all the attributes to help identify the tab location. Otherwise, the Form fields seem to work well in the Contact section with the labels positioned correctly.



5. General: PASSED (overall) - Basic structure check is satisfactory overall despite recommending that the “Navigation” tab should go above the “Main” structure. Alternative text can be seen for most images and provides appropriate information in the homepage. While the headings structure needs improvement, the website accessibility is adequate overall

The following apply to the entire page:
en-US

WAVE
web accessibility evaluation tool

Address: https://chantillybakery.com/

Styles: OFF ON

Structure

Summary Details Reference Structure Contrast

Header

Main

Cake

Sandwiches

Pastries

Coffee

Desserts

Navigation

Footer

Chateau de Chantilly Cafe

Chateau de Chantilly Cafe

Home

Our Food

Cake

Sandwiches

Pastries

Coffee

Desserts

Reviews

Galler

Contact

Home

Cake

</>