



Customer: YAGEO SUZHOU Date: 23-Dec-15 Time: 10:00

Participant From Maruwa		Participant From Organizer		Report To
1. Mr Ogawa	MD	1. Ms Julia	Purchase Chief	1. Mr.Anthony,Mr.Ogawa,Mr.Sukenari
2. Mr Matsumoto	Sales	2. Ms Vivian Xu	IQC	2. Mr.Seeni,Mr.Naga,Mr.Sinna
3. Sivakumar	MMSB QA	3. Mr Jone	IQC	3. Mr.Theva,Mr.Shahrudin,Mr.Fauzi
4 Ronny Fang	Shanghai Sale	4 Mr Robin	SUPV IQC	4 Mr. Sukenari, Mr. Matsumoto
5.		5.		5.

Agenda

Meeting started of with Quality group.
The details as below (Please refer to the attach sheet for details)



YAGEO SUZHOU QUALITY MEETING							23/12/2015	
No	Complaint / Request	Product	Image	Details	MARUWA Comment	PIC	DATE	
1	Packing date & Inspection report	All Product		Request Maruwa to check whether the Packing date & Inspection report date to be same or greater. (Requested by their customer)	Will check and feedback whether can be done or not	Siva Mr Satya	29/12	
2	Burr afterBAR breaking	YA2010 YA2512		Detecting BURR on bar breaking. The position of burr is random.	Need to verify since the slit depth in spec. This be cause by hairline crack which penetrates deeper and during breaking, this creates the crack	Mr Siva PROD: TBA		Report YAGEO - 30/12
3	Colour abnormal	M TYPE & POWER CHIP		Colour not sticking on product	a. Evaluated NG product with Maruwa colour and problem still occurs. B. 8 Lots sample brought and no any colour issue for both Maruwa colour and YAGEO colour c. Due to line down, YAGEO will do mini firing and ccolour the product for 100kpcs. (The cost estimated ~ RM4500 d. Maruwa suspecting the cost is from colouring machine but no conclusion made	Mr Inagaki		Report YAGEO - 29/12
4	Angle spec	3080M	NA	YAGEO measurement shows above 40micron from Maruwa's max spec	a. Verify with Maruwa master, variance shows 15micron b. Product measurement done on standard method that is index on right side => rectified c. Maruwa requested YAGEO to re-verify the NG samples since the measurement was wrong	Mr Siva Mr Nazli		YAGEO feedback - 28/12
5	New carton	All Product	NA	For crack improvement, carton box upgraded but next to upgrade the inner cushion	Will start to implement for 7910M	Mr Siva Mr Peter (Warehouse)	29/12	
6	Return goods	As per list		Return status	Concluded 1. YAGEO will return all crack NG total qty: 995999pcs - 25/12 2. Balance return will be carry out in - Jan 2016 (480Kpcs) 3. Colour abnormal will be decided base from Maruwa's report	Ms Julia - YAGEO Mr Siva Mr Ronny		Dec'15 Jan'16
7	Special release	As per list		NG Claim	Total USD 2865	Mr Ronny Mr Ogawa		24/12/15
8	YAGEO On-hold	All product		Yageo will clear all on-hold in quarterly basis	Maruwa	Ms Julia - YAGEO Mr Siva - Maruwa		Mar-16

RETURN GOODS STATUS
Product have been packed and waiting to pull out to Port. The carton have been pasted with YAGEO's NG indication. The total of 20 pallets and the goods have to be brought back to Malaysia for re-packing.
Below is the carton indications



Conclusion & Opinion

Generally most of the customer problem have been resolve and we need to focus on 2 areas.
A. Colour issues
B. Angle issues
Target to solve this issues by Dec'15 ~ Jan'16. Great co-operation shown by YAGEO team and will continue to improve the Maruwa's performance.

No	Complaint / Request	Product	Image	Details	MARUWA Comment	PIC	DATE
1	Packing date & Inspection report	All Product		Request Maruwa to check whether the Packing date & Inspection report date to be same or greater. (Requested by their customer)	Will check and feedback whether can be done or not	Siva Mr Satya	29/12
2	Burr afterBAR breaking	YA2010 YA2512		Detecting BURR on bar breaking. The position of burr is random.	Need to verify since the slit depth in spec. This be cause by hairline crack which penetrates deeper and during breaking, this creates the crack	Mr Siva PROD: TBA	Report YAGEO - 30/12
3	Colour abnormal	M TYPE & POWER CHIP		Colour not sticking on product	a. Evaluated NG product with Maruwa colour and problem still occurs. B. 8 Lots sample brought and no any colour issue for both Maruwa colour and YAGEO colour c. Due to line down, YAGEO will do mini firing and ccolour the product for 100kpcs. (The cost estimated ~ RM4500 d. Maruwa suspecting the cost is from colouring machine but no conclusion made	Mr Inagaki	Report YAGEO - 29/12
4	Angle spec	3080M	NA	YAGEO measurement shows above 40micron from Maruwa's max spec	a. Verify with Maruwa master, varience shows 15micron b. Product measurement done on standard method that is index on right side => rectified c. Maruwa requested YAGEO to re-verify the NG samples since the measurement was wrong	Mr Siva Mr Nazli	YAGEO feedback - 28/12
5	New carton	All Product	NA	For crack improvement, carton box upgraded but next to upgrade the inner cushion	Will start to implement for 7910M	Mr Siva Mr Peter (Warehouse)	29/12
6	Return goods	As per list		Return status	Concluded 1. YAGEO will return all crack NG total qty: 995999pcs - 25/12 2. Balance return will be carry out in - Jan 2016 (480Kpcs) 3. Colour abnormal will be decided base from Maruwa's report	Ms Julia - YAGEO Mr Siva Mr Ronny	Dec'15 Jan'16
7	Special release	As per list		NG Claim	Total USD 2865	Mr Ronny Mr Ogawa	24/12/15
8	YAGEO On-hold	All product		Yageo will clear all on-hold in quarterly basis	Maruwa	Ms Julia - YAGEO Mr Siva - Maruwa	Mar-16