



Customer Visit Report

MM-IN-RD-9100-P06-04
Rev: 1

Customer: Haemonetics Penang				Date: 22-Mar-23	Time: 9:15
Participant From Maruwa		Participant From Organizer		Report To	
1. Mr Siva	Maruwa Malaysia	1. Mr Allan	Plant Director	1. Datuk Anthony & Mr Sasaki	
2. Ms Adibah	QA	2. Mr Saw	Engineering Mgr	2. Mr Sinna & Mr Nazli	
3.		3. Mr Chun Seng	Engineering	3. Mr Okui & Mr Kitauji	
4		4 Ms Wen Chee	Purchaser	4 Mr Sathia & Ms Pang	
5.		5. Ms Sim	Material Planner	5. Mr Mori & Mr Ogawa	

Agenda

Meeting started of with quality Discussion

Time : 9:00am ~ 10:30am

Failuers mainly on the dimension

OD 2 - Product placement on the seal crown is tilted due to Maruwa's dimension is at the min which need to be improved.

ID - Current failure is locytite glue overflow due to the dimension at the max.

Visual Failures

Highest visual failure detected at HAE is stain. Currently HAE is doing 100% incoming check for visual and detetcted 0.1% stain. Sample provided for Maruwa review

Detail of the quality discussion is shown attached file

Commercial Discussion : 10:30am ~ 12:30pm

1. Quantity projection as below

Apr- 350kpcs (PO issued)

May - 525kpcs (PO 4th week)

Jun - 700kpcs

2. Tooling scheduling

Tool C - 29th Mar

Tool D ~F : 29th April

3. Logistics - US

Requested Maruwa to follow similar packaging method as per current pink supplier (Morgan).

4. COC - Inspection report

Need to be attached for alll shipment and base from Mterial Lot No (Can be repeating COC for same lot no's)

Details of action item as per attached report

Meeting adjourned at 5:15pm

Conclusion & Opinion

Mr Alln commented that Maruwa's product yield have improved from 90% => 96%. Maruwa need to further improve on the dimension & product angle.


Next focus will be US shipment & quality level since US operation is fully automated.

Requested to have a bi-monthly quality review between HAE Penang & MM to resolve all the commercial & quality issues.


HAE & MM - QUALITY & COMMERCIAL ACTION PLAN

No	Section	Process	Activity	Date	Pic
1		IQC	1. HAE-IQC sampling for 32pcs for every lot of shipment. 2. Measurement method used by HAE: inch - HAE provided caliper for MM to do some confirmation on the dimension. 3. Inspection for OQC- start to measure in inches.	30th March 2023 -Validation for OQC using the caliper in inches.	Adibah Ramlah
2	Quality	In-Process	Product abnormality - despite control under spec for the dimension: 1. Outer diameter 2 2. Inner diameter	On-going process	Siva Adibah
		Tool C Validation	Tool C will be shipped out on 26th March and expected to be in MM on 28th March - HAE will be doing the OQ&PQ Evaluation on Tool C due to changes in firing temperature & inner angle (45°)	4th April 2023	Adibah
		Tooling Inventory	Mould D Mould E Mould F Will be estimated to be in MM on 29th April 2023	29th April 2023	Muto
		Standardization of limit sample for defect criteria	HAE gives some sample to standardize the defect limit sample between HAE and MM.	22nd April 2023	Ramlah
4	Commercial	Purchase Order	March- 175k April- 350k May-525k 9.3 million will be issued on the first week of May 2023	22nd April 2023	Siva Sazlina
5	Packaging		1. HAE requested on US shipment on 27th April 2023 will the same carton using triwall as the 1st shipment.		Siva

Outer Diameter 1 SPC Trend



Outer Diameter 2 SPC Trend



Inner Diameter 1 SPC Trend

