




Conveyor Design




TITLE	MARUWA		A4
	SCALE:1:50	SHEET 1 OF 1	



TITLE	MARUWA		A4
	SCALE:1:50	SHEET 1 OF 1	



TITLE		A4
MARUWA		
SCALE:1:50		SHEET 1 OF 1



D

C

B

A

6

5

4

3

2


1

D

C

B


A



FLIPPING MECHANISM

DETAIL C

TITLE		A4
MARUWA		
SCALE:1:50		SHEET 1 OF 1



D

C

B

A

6 5 4 3 2 1

ERROR
SORTING
MECHANISM


SORTING BOX

D

C

B

A




DETAIL D

TITLE	MARUWA		A4
SCALE:1:50	SHEET 1 OF 1		

6 5 4 3 2 1

Defects Detection

No.	Defect Name	Unprocessed Image		Processed Image	
1	Katasuki				


Remarks:

Can see unwanted marks due to:

- Dust
- Improper part handling (scratch, fingerprints)


Countermeasure:

- Usage of sticky roller and ionizer to remove dust
- Run part on conveyor to reduce improper handling

No.	Defect Name	Unprocessed Image			Processed Image		
2	Pinhole						

Remarks:

Can detect defect

No.	Defect Name	Unprocessed Image		Processed Image	
3	Rough				


Remarks:

Can see unwanted marks due to:

- Dust
- Improper part handling (scratch, fingerprints)

Countermeasure:

- Usage of sticky roller and ionizer to remove dust
- Run part on conveyor to reduce improper handling

No.	Defect Name	Unprocessed Image		Processed Image	
4	Spot Bumpy				



Remarks:

Can see unwanted marks due to:

- Dust
- Improper part handling (scratch, fingerprints)

Countermeasure:

- Usage of sticky roller and ionizer to remove dust
- Run part on conveyor to reduce improper handling


No.	Defect Name	Unprocessed Image	Processed Image
5	Edge Warp		

Remarks:

Can detect defect.

Countermeasure:

- Suggestion to use 3D Laser Profiler for better accuracy

No.	Defect Name	Unprocessed Image		Processed Image	
6	Bumpy				

Remarks:

Can detect defect.

Countermeasure:

- Suggestion to use 3D Laser Profiler for better accuracy