




INSPECTION STANDARD (HT LAB)

Page 01 of 01

☐ Prototype	☐ Pre-Launch	☒ Production	Date (Original)		01/10/2016		
Part Name:- POD Gear 40 ~ 37 teeth		Part No.:- 2210C01301		Inspection Standard Number		SIP/3026/200	
Customer :- TAFE AGCO		Change Level.:-00		Part Stage		HT Lab.	
Sr.No.	Parameter	Special Char. Class	Methods				Reaction Plan
			Product Specification	Inspection Method	Inspection Frequency	Control Method	
1.	Surface Hardness	✱	58~64 HRC	Rockwell Hardness Tester	1Pc/Lot	FMT-HT-39	A
2.	ECD Measurement at 513HV at PCD	✱	0.75~1.30 mm	Vicker Hardness Tester	1Pc/Lot	FMT-HT-39	A
3.	Surface Hardness on Internal Bore	✱	58 HRC Min	Rockwell Hardness Tester	1Pc/Lot	FMT-HT-39	A
4.	Surface Carbon Content	✱	0.8~1.10%	Microscope	1Pc/Lot	FMT-HT-39	A
5.	Core Hardness at RCD	▶	28~43 HRC	Rockwell Hardness Tester	1Pc/Lot	FMT-HT-39	A
6.	Micro Case	✱	Tempered Martensite + RA <30% Max.	Microscope	1Pc/Lot	FMT-HT-39	A
7.	Core Micro	✱	LCTM Or Baintic Structure	Microscope	1Pc/Lot	FMT-HT-39	A

OPEN SKTCH

Material- 8620H



Reaction Plan: A-यदि Inspektion करते समय कम्पोनेंट खराब मिले तो खराब कम्पोनेंट को Rejection का टैग लगाकर Rejection टेबल पर रखें और उसके बारे में Department के Incharge को बतायें ।

Legends: ☒ Special Characteristics as Per Drawing ☒ Special Characteristics For Process ☒ Special Characteristics For Safety

Change Details

Date	Rev. No.	Change	Reason for Change	Date	Rev. No.	Change	Reason for Change