






INSPECTION STANDARD (HT LAB)

Page 01 of 01

☐ Prototype	☐ Pre-Launch	☒ Production	Date (Original)		08/05/15		
Part Name:- Gear Final Drive Reduction (LH) Z-50/12 (Helical)			Part No.:- D10209610D		Inspection Standard Number SIP/2054/140		
Customer :- Escorts			Change Level.:-00		Part Stage HT Lab.		
Sr.No.	Parameter	Special Char. Class	Methods				Reaction Plan
			Product Specification	Inspection Method	Inspection Frequency	Control Method	
1.	Surface Hardness	*	58~62 HRC	Rockwell Hardness Tester	1Pc/Lot	HT Lab Report	A
2.	ECD Check On 513 HV At Gear PCD Z-50	*	0.9~1.2 mm	Vicker Hardness Tester/ Micro Vicker hardness tester	1Pc/Lot	HT Lab Report	A
3.	ECD Check On 513 HV At Gear Root Z-50	*	0.96 mm Min.	Vicker Hardness Tester/ Micro Vicker hardness tester	1Pc/Lot	HT Lab Report	A
4.	Core Hardness Check On Tooth Center As Per Figure.	*	32~41 HRC	Rockwell Hardness Tester	1Pc/Lot	HT Lab Report	A
5.	Case Micro	*	Tempered Martensite And Must Be Free From Network Carbide. Fine, Uniform Dispersed Carbide Less Than 5% Are Acceptable + RA<15%	Microscope (100x~500x)	1Pc/Lot	HT Lab Report	A
6.	Core Micro	*	LCTM+Bainitic Network Or Undissolved Ferrite Is Not Desirable.	Microscope (100x~500x)	1Pc/Lot	HT Lab Report	A
7.	Surface Carbon Content	*	0.8~1.0 %	Microscope (100x~500x)	1Pc/Lot	HT Lab Report	A
8.	IGO	*	0.025 mm Max.	Microscope (100x~500x)	1Pc/Lot	HT Lab Report	A

OPEN. SKTCH

Material:- 20MnCr5-S

ECD & Core Hardness
Checking Location

Note :-1) The Case Depth At The Root Shall Not Be less than 0.96 mm.
2) Sample To Be Cut At Center Of Gear Width For Inspection.

Reaction Plan: A-यदि Inspection करते समय कम्पोनेट खराब मिले तो खराब कम्पोनेट को Rejection का टैग लगाकर Rejection टेबल पर रखें और उसके बारे में Department के Incharge को बतायें।

Legends: ☒ Special Characteristics as Per Drawing ☒ Special Characteristics For Process ☒ Special Characteristics For Safety

Change Details

Date	Rev. No.	Change	Reason for Change	Date	Rev. No.	Change	Reason for Change

Prepared By: