





INSPECTION STANDARD (HT LAB)


MILESTONE							
☐ Prototype	☒ Pre-Launch	☐ Production	Date (Original)		03/11/2023		
Part Name:- Intermediate Shaft		Part No.:- 93653687		Inspection Standard Number		SIP/31007/230	
Customer :- TMTL		Change Level.:-00		Part Stage		HT Lab.	
Sr.No.	Parameter	Special Char. Class	Methods				Reaction Plan
			Product Specification	Inspection Method	Inspection Frequency	Control Method	
1.	Surface Hardness	*	59-63 HRC	Rockwell Hardness Tester	1Pc/Lot	FMT-HT-39	A
2.	ECD Check 550HV1 At Gear PCD	*	1.1~1.4 mm	Vicker Hardness Tester/Micro Vicker Hardness Tester	1Pc/Lot	FMT-HT-39	A
3.	ECD Check 550HV1 In Undercuts	*	0.35 min.	Vicker Hardness Tester/Micro Vicker Hardness Tester	1Pc/Lot	FMT-HT-39	A
4.	Surface Hardness at Dia.Ø20.0	*	58 HRC Min.	Rockwell Hardness Tester	1Pc/Lot	FMT-HT-39	A
5.	Surface Hardness at Dia.Ø40.0	*	58 HRC Min.	Rockwell Hardness Tester	1Pc/Lot	FMT-HT-39	A
6.	Core Hardness at Gear PCD	*	42 HRC Max.	Rockwell Hardness Tester	1Pc/Lot	FMT-HT-39	A
7.	Core Hardness at Gear RCD	*	32 HRC Min.	Rockwell Hardness Tester	1Pc/Lot	FMT-HT-39	A
8.	Micro Case	*	Tempered Martensite+ RA<12%, Carbide (Globular) Upto 5% Max.	Microscope (100x~500x)	1Pc/Lot	FMT-HT-39	A
9.	Micro Core	*	LCM+Bainitic Structure, Ferrite Upto 5%	Microscope (100x~500x)	1Pc/Lot	FMT-HT-39	A
10.	IGO / NMTP	*	20 Micron Max.	Microscope (100x~500x)	1Pc/Lot	FMT-HT-39	A

OPTIONAL SKETCH

Material- 20MnCr5



Transverse For Hardness Check
(Take Every Impression At a Distance Of 0.1mm)



Note :- #Case Depth & Core Hardness values to be checked on Gear 'K'

Reaction Plan: A-यदि Inspektion करते समय कम्पोनेट खराब मिले तो खराब कम्पोनेट को Rejection का टैग लगाकर Rejection टेबल पर रखें और उसके बारे में Department के Incharge को बतायें ।

Legends: ☒ Special Characteristics as Per Drawing ☒ Special Characteristics For Process ☒ Special Characteristics For Safety

Change Details

Date	Rev. No.	Change	Reason for Change	Date	Rev. No.	Change	Reason for Change