





☐	Prototype	☐	Pre-Launch	☒	Production	Date (Original)	08.01.2023	
Part Name:- Ring Gear Z-60			Part No.:- CAI25452			Inspection Standard Number	SIP/4522/180	
Customer :- CARRARO			Change Level.:-00			Part Stage	HT Lab.	
Sr.No.	Parameter	Special Char. Class	Methods				Reaction Plan	
			Product Specification	Inspection Method	Inspection Frequency	Control Method		
1.	Surface Hardness	*	58~62 HRC	Rockwell Hardness Tester	1Pc/Lot	HT Lab Report	A	
2.	ECD Measured To 550HV1	*	0.7mm~1.1mm	Micro Vicker Hardness Tester/ Vicker Hardness Tester	1Pc/Lot	HT Lab Report	A	
3.	Core Hardness	*	36~45 HRC	Rockwell Hardness Tester	1Pc/Lot	HT Lab Report	A	
4.	Case Micro	*	Tempered Martensite+ RA 20% Max& No Carbides Shall Be Allowed	Microscope At 100X~500X	1Pc/Lot	HT Lab Report	A	
5.	Core Micro	*	LCM+Bainitic Structure	Microscope At 100X~500X	1Pc/Lot	HT Lab Report	A	
6.	Oxidation Layer	*	15 Micron Max	Microscope At 100X~500X	1Pc/Lot	HT Lab Report	A	

Space For Sketch:

Material:-20MnCr5(EN-10084)



Transverse For Hardness Check
(Take Every Impression At a Distance Of 0.1mm)

Reaction Plan: A-यदि Inspection करते समय कम्पोनेंट खराब मिले तो खराब कम्पोनेंट को Rejection का टैग लगाकर Rejection टेबल पर रखें और उसके बारे में Department के Incharge को बतायें।

Legends: ☒ Special Characteristics as Per Drawing ☒ Special Characteristics For Process ☒ Special Characteristics For Safety

Change Details

Date	Rev. No.	Change	Reason for Change	Date	Rev. No.	Change	Reason for Change

Prepared By:

Checked By: