


# 24H3-191C


Single Gate



## Structure Summary

Facility ID	24H3-191C
Maximo Asset ID	GIS-1593585
MSD Service Area	Sulphur (Area 1)
Ownership	MSD
Status	Active

Pipe	Clock	Flow	Connection
1	6	Out	24H3-196C
2	12	In	24H3-190C



## General Information

System	Combined
Data Layer	ssInlet
Subtype	Single
Original InletType	<Null>
Inlet Type	Grate
Date	October 11, 2024
Weather	Dry
Diving Structure?	No
Report Asset Integrity Issue?	Yes

## Asset Integrity

Emergency Repair?	No
Issue Description	Bottom corners of the grate are broken, lid is on the rim but barely.

Issue Photo



Issue Date	October 11, 2024
------------	------------------

## Location

Address	Ave, Saint Louis, City of St. Louis, Missouri 63109, USA
Manually Update Address?	No
Location Code	(H) Alley
Surface Type	(A) Asphalt

**Area Photo (Post-Inspection)**



**Topside Photo**



**Wall Material**

Brick

**Additional Location Photos**

## Pipe Connections (2 Items)

### Pipe Connections - 1. 6, Out, (BR) Brick, 24H3-196C

MSD pipe facility ID	24H3-191C:24H3-196C
Pipe System	C
Pipe Number	1
Can you verify pipe characteristics?	Yes
Trench Grate Y/N	No
Pipe Status	Active
Clock Position	6
Pipe Direction	Out
Pipe Type	(GR) Gravity Connection
Pipe Shape	(E) Egg Shaped
Pipe Height	56
Pipe Material	(BR) Brick
Rehab Type	NONE
Connecting Structure ID	24H3-196C

#### Pipe Photo - Report



#### Additional Pipe Photos

### Pipe Connections - 2. 12, In, (BR) Brick, 24H3-190C

MSD pipe facility ID	24H3-190C:24H3-191C
Pipe System	C
Pipe Number	2
Can you verify pipe characteristics?	Yes

Trench Grate Y/N	No
Pipe Status	Active
Clock Position	12
Pipe Direction	In
Pipe Type	(GR) Gravity Connection
Pipe Shape	(E) Egg Shaped
Pipe Height	56
Pipe Material	(BR) Brick
Rehab Type	NONE
Connecting Structure ID	24H3-190C

**Pipe Photo - Report**



**Additional Pipe Photos**