
FSR 온도 테스트 그래프


2022-02-10


test	temp	mean	max	RR-est	RR-ref
2022-02-08 #1	low	636	6448	9	0.0
2022-02-08 #2	low	455	4876	8	8.5
2022-02-08 #3	low	540	5584	8	8.5
2022-02-08 #4	low	505	5348	9	10.0
2022-02-08 #5	low	549	5540	8	0.0
2022-02-09 #1	high	6798	12864	14	13.0
2022-02-09 #2	high	0	0	0	0.0
2022-02-09 #3	high	7973	12976	8	7.5
2022-02-09 #4	high	7284	12960	12	11.5
2022-02-09 #5	high	7690	12976	11	13.5
2022-02-10 #1	room	1683	5812	10	10.5


2022-02-08 저온 테스트






















































2022-02-09 고온 테스트







































2022-02-10 상온 테스트

