
1/8" Aircraft Cable


NOT FOR DISTRIBUTION



Canvas to be stapled on site. Excess cut and covered by pre-sewn, pre-grommeted 3" white webbing. Webbing has a flap sewn to the underside which is then stapled to the MDF. Pre-attached threw grommets 1/8" aircraft cable looped and crimped with sleeve. Pulled taught threw 1/8" hole in Aluminum, stopped with compressed sleeve. Cable cut as close to stop as possible.

Date: 6/25/08
Time: 2:33:29 PM
File name: ZegnaOBO V3.vwx

NOT FOR DISTRIBUTION



VECTORWORKS EDUCATIONAL VERSION