



Builder	DRB Group
Region	North Carolina
Division	Raleigh
Community	Sidney Creek TH (NC)(RAL)
Lot	00.0644
Street Address	644 Sefton Park Dr.
Field Manager	Gabriel Rounds
	Eric Morphy
Reviewer	Terry Cureton
Date	7/6/2026
Type	New Review
Product Type	Townhouse

Score	94.25%
Second Look, Paint & Drywall?	No
Possible Points	100.00
Adj. Possible Points	100.00
Tic Marks	11
# of Items	19
Customer Exceptions	0
Weather Exceptions	0
Division Exceptions	0
Builder Items	0
No Action Items	0

Rescheduling Notes

6/26 to 7/1 to 6

Reschedules

Tic Mark Items

Item	Tic Marks	Description	Points
Minor Drywall	3		0.25
Minor Paint	5		0.5
Minor Clean	3		0.25

Items

Room	Trade	Item	Description	Points	Initials	
Bedroom - Owner's	Cleaning	1905 - Floors Dirty	Stain on master bedroom carpet, back left under window	0.25		
Bedroom 1	Doors	50000D - Damage	Front right bedroom closet door jamb is chipped, left middle side	0.25		
Bedroom 1	Doors	50005 - Missing Pieces	Front right bedroom door missing hinge or base bump	0.25		
Bedroom 1	Windows	13000D - Damage	Front right bedroom, front window lock is loose and window difficult to open	0.25		
Bedroom 2	Interior_Trim	1500D - Damage	Front left bedroom door casing not flush to wall, inconsistent gaps. Right side, bedroom side	0.25		
Exterior	Concrete_Flatwork	520 - Stain	Stains on front porch slab	0.25		
Exterior	Paint	1730 - Item Not Painted	Lintel above garage door is not painted at edge	0.25		
Exterior	Roofing	2000D - Damage	Drip edge not flush and is raised, front gable, right side	0.25		
Garage	Concrete_Flatwork	500D - Damage	Gouge in garage slab and fire caulk stains	0.25		
Garage	Drywall	1405 - Missing Pieces	Drywall missing, left side of garage entry door, garage side	0.25		
Garage	Drywall	1400D -Damage	Drywall corner is wavy and out of square, right side of powder bath pedestal sink	0.25		
Kitchen/Dinette	Builder_Specific	10010 - No Service Contact List	Contractor list missing, cabinet doors under sink	0.25		
Kitchen/Dinette	Cabinets	1630 - Drawer/Door Issue	Top drawer, right of fridge opening is damaged, inside left edge	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	Lower cabinet, right of fridge opening, bottom skin is damaged	0.25		
Kitchen/Dinette	Doors	50000D - Damage	Chip in top center of back entry door jamb	0.25		
Kitchen/Dinette	Doors	50005 - Missing Pieces	Back entry door is missing hinge or basebump	0.25		
Kitchen/Dinette	Exterior_Trim	20070 - Tarnished Threshold	Back entry door, threshold is tarnished	0.25		
Kitchen/Dinette	Interior_Trim	1560 - Out of plumb/square	Front right of kitchen island, base board is bowed	0.25		
Stairs/Hall	Stairs_and_Rails	21005 - Missing Pieces	Newel post top cap missing , bottom right of stairs at first landing	0.25		

Scored Photos



Bedroom - Owner's
1905 - Floors Dirty
Stain on master bedroom carpet, back left under window




Bedroom 1
13000D - Damage
Front right bedroom, front window lock is loose and window difficult to open



Bedroom 1
50000D - Damage
Front right bedroom closet door jamb is chipped left middle side



Bedroom 1
50005 - Missing Pieces
Front right bedroom door missing hinge or base bump



Bedroom 2
1500D - Damage
Front left bedroom door casing not flush to wall, inconsistent gaps. Right side, bedroom side




Exterior
1730 - Item Not Painted
Lintel above garage door is not painted at edge




Exterior
2000D - Damage
Drip edge not flush and is raised, front gable, right side



Exterior
520 - Stain
Stains on front porch slab



Garage
1400D -Damage
Drywall corner is wavy and out of square, right side of powder bath pedestal sink



Garage
1405 - Missing Pieces
Drywall missing, left side of garage entry door, garage side



Garage
500D - Damage
Gouge in garage slab and fire caulk stains




Kitchen/Dinette
10010 - No Service Contact List
Contractor list missing, cabinet doors under sink



Kitchen/Dinette
1560 - Out of plumb/square
Front right of kitchen island, base board is bowed



Kitchen/Dinette
1600D - Damage
Lower cabinet, right of fridge opening, bottom skin is damaged




Kitchen/Dinette
1630 - Drawer/Door Issue
Top drawer, right of fridge opening is damaged, inside left edge




Kitchen/Dinette
20070 - Tarnished Threshold
Back entry door, threshold is tarnished



Kitchen/Dinette
50000D - Damage
Chip in top center of back entry door jamb



Kitchen/Dinette
50005 - Missing Pieces
Back entry door is missing hinge or basebump



Stairs/Hall
21005 - Missing Pieces
Newel post top cap missing , bottom right of stairs at first landing



