


(a) 256 通道 F56 补修前后逐路对照



(b) 256 通道 F56 补修前后变化率 (#7/#31 重合 152.007 mm)

