

Calibration results

=====

Camera-system parameters:

cam0 (/stereo_1_0/left/image_rect):

type: <class 'aslam_cv.libaslam_cv_python.DistortedPinholeCameraGeometry'>

distortion: [-0.03244176 -0.01143044 0.01076826 -0.02467524] +- [0.00408406 0.00185086 0.00048504 0.00128089]

projection: [163.19620135 155.38906094 130.03377015 159.94706176] +- [1.21718641 1.17225927 0.77846644 0.5922492]

reprojection error: [-0.000002, -0.000000] +- [0.467834, 0.311315]

Target configuration

=====

Type: checkerboard

Rows

Count: 8


Distance: 0.02 [m]

Cols



Count: 11

Distance: 0.02 [m]



cam0: estimated poses





cam0: polar error



cam0: azimuthal error



cam0: reprojection errors



Location of removed outlier corners

