

Calibration results

=====

Camera-system parameters:

cam0 (/stereo_0_3/left/image_rect):

type: <class 'aslam_cv.libaslam_cv_python.DistortedPinholeCameraGeometry'>

distortion: [-0.0069228 -0.00056886 -0.00032984 -0.00425187] +- [0.01145138 0.0076935 0.00253006 0.00302205]

projection: [158.77065737 159.24200551 158.60457216 158.95712839] +- [2.87450797 2.79419901 1.80637204 1.7564655]

reprojection error: [0.000000, 0.000000] +- [0.145264, 0.127430]

Target configuration

=====

Type: checkerboard

Rows

Count: 8


Distance: 0.02 [m]

Cols



Count: 11

Distance: 0.02 [m]



cam0: estimated poses





cam0: polar error



cam0: azimuthal error



cam0: reprojection errors



Location of removed outlier corners

cam0

