

Calibration results

=====

Camera-system parameters:

cam0 (/stereo_1_0/left/image_rect):

type: <class 'aslam_cv.libaslam_cv_python.DistortedPinholeCameraGeometry'>

distortion: [-0.00097834 -0.00423095 -0.00059881 -0.00220103] +- [0.00813477 0.00772478 0.00194087 0.00162183]

projection: [158.26787203 158.46856174 158.94481681 159.20472502] +- [1.62985233 1.6524271 1.0558375 1.21808511]

reprojection error: [-0.000000, -0.000000] +- [0.149120, 0.116025]

Target configuration

=====

Type: checkerboard

Rows

Count: 8


Distance: 0.02 [m]

Cols



Count: 11

Distance: 0.02 [m]



cam0: estimated poses




cam0: polar error



cam0: azimuthal error



cam0: reprojection errors



Location of removed outlier corners

