

Calibration results

=====

Camera-system parameters:

cam0 (/stereo_1_0/left/image_rect):

type: <class 'aslam_cv.libaslam_cv_python.DistortedPinholeCameraGeometry'>

distortion: [-0.00296652 -0.00051959 0.00057932 -0.00208619] +- [0.00728193 0.00665078 0.00194256 0.0015542]

projection: [158.84236748 159.13888401 159.39007245 159.66667039] +- [1.59816252 1.5606832 1.08726017 1.2568019]

reprojection error: [0.000000, -0.000000] +- [0.138561, 0.133509]

Target configuration

=====

Type: checkerboard

Rows

Count: 8


Distance: 0.02 [m]

Cols



Count: 11

Distance: 0.02 [m]



cam0: estimated poses





cam0: polar error



cam0: azimuthal error



cam0: reprojection errors



Location of removed outlier corners

