
Result protocol
CO2 Test

Mileage:		**Manufacturer:**	VW Multivan
VIN:		**Engine code:**	DRNB
Initial registration date:			

Rating

The measurement was evaluated as OK.
The measured CO2 value is inside the normal range. No exhaust gas is present in the cooling system.



Measured values

	Unit	Min.	Max.
CO2	[ppm]	628.9	2300.9
Pressure	[mbar]	1018.7	1371.3

Safety instruction

The test engineer accepts and confirms the safety instructions by pressing the Next button (F8)