

Test Report

No.: XMNPC24002659601

Date: Dec 17, 2024

Page 1 of 4

Client Name: TWINCO (XIAMEN) OFFICE SUPPLIES CO.,LTD.

Client Address: NO. 105, XIAGUANG ROAD, XIN YANG INDUSTRIAL AREA, HAI CANG DISTRICT,
XIAMEN CITY, FUJIAN,P.R. CHINA

Sample Name: 6000 TWIN LIFT Stepstool

The above sample(s) and information were provided by the client.

SGS Job No.: XMIN2412003011PC01

Sample Receiving Date: Dec 09, 2024

Testing Period: Dec 09, 2024 ~ Dec 16, 2024

Test Requested: Select test(s) as requested by the client.

Test Method(s): Please refer to next page(s).

Test Result(s): Please refer to next page(s).

	Test Requirement	Conclusion
1	Phthalates	Pass

Signed for and on behalf of
SGS CSTC Standards Technical Services Co., Ltd. Xiamen Branch

Rae chen

Rae Chen
Approved Signatory

Scan to see the report



XMNPC24002659601
Verification:
check.sgsonline.com.cn



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC Standards Technical Services Co., Ltd.
Xiamen Branch (Food & Food Laboratory)

No.31 Xianghong Road, Xiang'an Torch Industrial Zone, Xiamen, Fujian Province, China. 361101
中国·福建·厦门·火炬(翔安)产业区翔虹路31号 邮编: 361101

t 400-691-0488 www.sgsgroup.com.cn
t 400-691-0488 sgs.china@sgs.com

Test Report

No.: XMNPC24002659601

Date: Dec 17, 2024

Page 2 of 4

Test Result(s):

Test Part Description:

SN ID	Sample No.	SGS Sample ID	Description
SN1	001	XMN24-0026596-0001.C001	Lt-grey plastic part
SN2	A2	XMN24-0026596-0001.C002	Black soft material part
SN3	A3	XMN24-0026596-0001.C003	Black plastic part
SN4	001+A2+A3	XMN24-0026596-0002	Lt-grey plastic part + Black soft material part + Black plastic part

Remarks:

- (1) 1 mg/kg = 1 ppm = 0.0001%
- (2) MDL = Method Detection Limit
- (3) ND = Not Detected (< MDL)
- (4) "-" = Not Regulated

Phthalates

Test Method: With reference to EN 14372:2004, analysis was performed by GC-MS.

Test Item(s)	CAS No.	Limit	Unit(s)	MDL	001+A2+A3
Dibutyl Phthalate(DBP)	84-74-2	0.1	%	0.003	ND
Bis-(2-ethylhexyl) Phthalate(DEHP)	117-81-7	0.1	%	0.003	ND
Benzyl Butyl Phthalate(BBP)	85-68-7	0.1	%	0.003	ND
Diisononyl Phthalate (DINP)	28553-12-0 /68515-48-0	0.1	%	0.010	ND
Di-n-Octyl Phthalate(DNOP)	117-84-0	0.1	%	0.003	ND
Diisodecyl Phthalate (DIDP)	26761-40-0 /68515-49-1	0.1	%	0.010	ND
Diisobutyl Phthalate(DIBP)	84-69-5	0.1	%	0.003	ND
Dipentyl Phthalates (DnPP)	131-18-0	0.1	%	0.003	ND
Dicyclohexyl Phthalate(DCHP)	84-61-7	0.1	%	0.003	ND
Bis(2-methoxyethyl)phthalate(DMEP)	117-82-8	0.1	%	0.003	ND
Diisopentyl Phthalate(DIPP)	605-50-5	0.1	%	0.003	ND
n-pentyl Isopentyl Phthalate(nPIPP)	776297-69-9	0.1	%	0.003	ND
1,2-benzenedicarboxylic Acid, dihexyl ester branched and linear(DHxP)	68515-50-4	0.1	%	0.010	ND
Conclusion					Pass

Notes:

- (1) The limit was provided by the client.

Unless otherwise stated, the decision rule for conformity reporting is based on Binary Statement for Simple Acceptance Rule (w=0) stated in ILAC-G8:09/2019.



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

No.31 Xianghong Road, Xiang'an Torch Industrial Zone, Xiamen, Fujian Province, China. 361101
中国·福建·厦门·火炬(翔安)产业区翔虹路31号 邮编: 361101

t 400-691-0488 www.sgsgroup.com.cn
t 400-691-0488 sgs.china@sgs.com

Test Report


No.: XMNPC24002659601

Date: Dec 17, 2024

Page 3 of 4

ATTACHMENTS

Phthalates Testing Flow Chart



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSI Standards Technical Services Co., Ltd.
Xiamen Branch Inspection & Testing Services

No.31 Xianghong Road, Xiang'an Torch Industrial Zone, Xiamen, Fujian Province, China. 361101
中国·福建·厦门·火炬(翔安)产业区翔虹路31号 邮编: 361101

t 400-691-0488 www.sgsgroup.com.cn
t 400-691-0488 sgs.china@sgs.com

Test Report

No.: XMNPC24002659601

Date: Dec 17, 2024

Page 4 of 4

Sample Photo:



SGS authenticate the photo on original report only

*** End of Report ***



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CTC Standards Technical Services Co., Ltd.
Xiamen Branch Testing, Inspection and Food Laboratory

No.31 Xianghong Road, Xiang'an Torch Industrial Zone, Xiamen, Fujian Province, China. 361101
中国·福建·厦门·火炬(翔安)产业区翔虹路31号 邮编: 361101

t 400-691-0488 www.sgsgroup.com.cn
t 400-691-0488 sgs.china@sgs.com

Member of the SGS Group (SGS SA)