



Case number CAS-0024758063

Order number WO-34968781 | Visit Date 12/09/2025

Instrument Details

Instrument/Module cobas 6800

Serial Number 1376

Internal Instrument Name

Additional Details

PO

Customer Details

Customer Number 0052027574

Customer Name P'CHOMKLAO HOSPITAL
รพ.พระจอมเกล้า

Street Address 53 ถ.รถไฟ ต.คลองกระเซง

ZIP 76000 - Phetchaburi

Contact Name Supaporn Sae-aeaw

Contact Phone +66864684997

Service Activity Code Service Visit

Purpose of Visit

Instrument: cobas 6800 V2 (S/N 1376), P'CHOMKLAO HOSPITAL รพ.พระจอมเกล้า

Issue: The instrument detected a supply on processing plate park position A of the instrument deck of the transfer module.

Action:

- Suggested that the customer performed manual cleanup-transfer module and cleaned the processing plate park position A >> The system was not back to standby.
- Restarted the instrument >> The system was not back to standby.
- After analyzing the PR by Tellme >> No additional information was obtained.
- Transfer the case to the FSE (K. Chanon) for further inspection.

Performed Activities

- Adjust sensor detect processing plate park pos.A, QC cassette park position
- Test sensor function
- Test cleanup instrument, Preparation instrument (pass)

Time Report


Category	Start	End	Hours	Billing Type
05913616001-Service labour time	12/09/2025 12:45 PM	12/09/2025 4:45 PM	4	Free of Charge

Signature or Stamp

Customer
Supaporn Sae-aeaw

Roche Support
Chanon Ittisakulphun

Sign here



By signing this document

- Customer representative confirms they have reviewed the work carried out as described and accepts the system for use.
- Roche Support person confirms the above mentioned work and checks have been completed..
- .

Hotline : 1800-0193-99
Tel : 02 7912200
Line Id : @rcscthailand

Roche Customer Support Center