

Key Punch Data:		County	Source	Emission	Action	Date	Agency/			
Number		Number	Point #	Type	Mo Day Yr	Indiv. ID				
1	1	101101	172217	174113	17411	191217	1121	1711151791	E211	1N1
		1 3 4	7 8	12 13 15	16 18	52	54	59	66 68	80

Compliance Status

Line 2 (Dup. cols. 1-15 from Line 1)

1010151	11	101
16 18	78	80

(NOTE: Columns not shown must be left blank)
(Do not punch Line 2 if column 78 is blank)

Company: Martin Marietta SIC: _____
 Address: Lyons County: Boulder
 Person Contacted: Gerald Anderson Phone: _____
 Inspected by: Parsons / Mesch Time: / AM ☒ PM

1. Followed on weeks emissions, complaints.
2. Mr Anderson in Process reported as 'normally' operating.
3. Discussed emissions, progress toward compliance.

Study on HC emissions due to be done soon. (mid Feb.)

Construction to begin June-July '79


Due to be done Jan. 1980

Emission ~~was~~ of HC the same all the time, condensation of
 HC only occurs if ambient temp. is < 30°F.


meeting re compliance, 'extension' etc. w/ yr ago. Letter or other
 commitment needed - will check our files.

4. Re. Mesch of this office called Mr Anderson at 4 pm today -
 Mr Anderson will send letter(s) from recent past and
 present status of compliance.

5. Plant to shut down for repairs this weekend for a period of 3 wks.



to be process from the Anderson



ACTION	TYPE - DESCRIPTION
12	Inspection
22	Source Test
23	Capacity Observation
24	Odor Observation

COMPLIANCE STATUS CODES

- 0 - Unknown
- 1 - Not in Compliance
- 2 - In Compliance by Source Test
- 3 - In Compliance by Inspection
- 4 - In Compliance by Certification
- 5 - In Compliance with Increments of Progress
- 6 - Not in Compliance with Increments of Progress
- 7 - Unknown Compliance with Increments of Progress
- 8 - No Applicable State Regulation
- 9 - In Compliance -- Closed Down

Key Punch Data:		County	Source	Emission	Action	Date			Agency/
		Number	Number	Point #	Type	Mo	Day	Yr	Indiv. ID
Line	101101	0220	010103	0001	121	01	03	79	0101
	1	3	4	7	8	12	13	15	16
	16	18	52	54	59	66	68	80	81
Compliance Status									

Line 2 (Dup. cols. 1-15 from Line 1)

101051

16 18

11

78

101

80

(NOTE: Columns not shown must be left blank)
(Do not punch Line 2 if column 78 is blank)

Company: Martin Marietta Cement Co
Address: Lyons
Person Contacted: Sam Angelo
Inspected by: Parsons / Mesch


SIC: _____

County: Boulder

Phone: _____

Time: 11 AM/PM

1. Insp per complaints on high stack emissions.
2. opacity noted at 0-5% at stack tip, 10-20% beyond steam plume break point. (Reg 1, IA1) *KM*
3. Mr. Angelo indicated some problems recently with air lines in baghouse system freezing, thus causing lowered baghouse collection efficiency. Heat tracing is being repaired.
4. Mr. Anderson (plant mgr.) to be back Friday. We will contact him then for more information on compliance progress, etc.
5. Mr. Angelo was reminded of upset reporting procedures.



Key Punch Data:				County Number	Source Number	Emission Point #	Action Type	Date Mo Day Yr	Agency/Indiv. ID
1	1	01101	0220	00003	007	12121	12	090673	009
1	3	1221	8	12	13	15	16	18	52
									54
									59
									66
									68
									80

Compliance Status

Line 2 (Dup. cols. 1-15 from Line 1)

1010151	31	101
16	18	78
		80

(NOTE: Columns not shown must be left blank)
(Do not punch Line 2 if column 78 is blank)

Company: Martin Marietta Cement SIC: _____
 Address: PO 467, Lyons County: Boulder
 Person Contacted: Cerald Anderson Phone: _____
 Inspected by: Ken Meach Time: 1:30 AM/PM

Routine inspection on Regulation #1
 In compliance by inspection.

Large pit quarry - some dust generated
 by heavy equipment in quarry but
 is not leaving the pit.

Roads have recently been watered.
 Caterpillar tractor in pit is burning
 diesel with heavy emissions.

Key Punch Data:				County Number	Source Number	Emission Point #	Action Type	Date Mo Day Yr	Agency/Indiv. ID
L	1	101101	0230	000193	0061	191917	112	09126178	0019
1	3	7	0	12	13	15	52	54	59

Compliance Status

Line 2 (Dup. cols. 1-15 from Line 1)

1010151	31	101
16 18	78	80

(NOTE: Columns not shown must be left blank)
(Do not punch Line 2 if column 78 is blank)

Company: Martin Marietta Cement SIC: _____
 Address: PO 467, Lyons County: Boulder
 Person Contacted: Gerald Anderson Phone: _____
 Inspected by: Ken Menden Time: 1:30 AM/PM

Routine inspection on Regulation #1
 In compliance by inspection.

Coal unloading, storage and crushing
 showed ~~no~~ ^{no} emissions. This
 system is sealed with coal dust
 injected into kiln for combustion.

AIR POLLUTION CONTROL - FIELD INSPECTION WORK SHEET

Key Punch Data:		County Number	Co Number	Emission Point #	Ion Type	Date Mo Day Yr	Agency/ Indiv. ID
Line 1	101101 1 3	0230 42287	000003 8	005 12 13 15	191217 16 18 52	12 092678 56 59	COA 66 68 60
Compliance Status							

Line 2 (Dup. cols. 1-15 from Line 1)

101051
16 18 76
121
60

(NOTE: Columns not shown must be left blank)
(Do not punch Line 2 if column 78 is blank)

Company: <u>Martin Marietta Cement</u>	SIC: _____
Address: <u>PO 467, Lyons</u>	County: <u>Boulder</u>
Person Contacted: <u>Cerald Anderson</u>	Phone: _____
Inspected by: <u>Ken Meach</u>	Time: <u>1:30</u> AM/PM

Routine inspection on Regulation #1
in compliance by inspection.
Coal fired boiler in operation ~~and~~
showed no visible emission. Low
sulphur coal used.

AIR POLLUTION CONTROL - FIELD INSPECTOR WORK SHEET

Key Punch Data:	County Number	Source Number	Emission Point #	Action Type	Date Mo Day Yr	Agency/Indiv. ID
1 1 0 1 1 0 1	0230	000003	004	12	09 06 78	EE19
1 3 4 8 2 2 1 7	0	12	13 15	52	54	59 66 68 80

Compliance Status

Line 2 (Dup. cols. 1-15 from Line 1)

0 0 5 1 3 1 1 0 1
16 18 78 80

(NOTE: Columns not shown must be left blank)
(Do not punch Line 2 if column 78 is blank)

Company: Martin Marietta Cement SIC: _____
Address: PO 467, Lyons County: Boulder
Person Contacted: Gerald Anderson Phone: _____
Inspected by: Ken Meade Time: 1:30 AM/PM

Routine inspection on Regulation #1
In compliance by inspection.
Open storage of clinker not a problem
at this time. a structure has
been built over storage area.

AIR POLLUTION CONTROL - FIELD INSPECTION WORK SHEET

Punch Data:			County	Source	Emission		Action	Date			Agency/				
			Number	Number	Point #		Type	Mo	Day	Yr	Indiv. ID				
Line 1	101101	0220	00093	0031	191217	12	092678	66	68	60					
	1	3	7	8	12	13	15	16	18	52	54	59	66	68	80

Compliance Status

Line 2 (Dup. cols. 1-15 from Line 1)

101051	31	101
16	18	70
		80

(NOTE: Columns not shown must be left blank)
(Do not punch Line 2 if column 70 is blank)

Company: Martin Marietta Cement

SIC: _____

Address: PO 467, Lyons

County: Boulder

Person Contacted: Cecilia Anderson

Phone: _____

Inspected by: Ken Menden

Time: 1:30 AM/PM

*Routine inspection on Regulation #1
In compliance by inspection.*

*Handling - transport belts have
vacuum system to remove fugitive dust.
Particulates removed in baghouse for reuse.*

AIR POLLUTION CONTROL - FIELD INSPECTOR WORK SHEET

Key Punch Data:				County Number	Source Number	Emission Point #	Action Type	Date Mo Day Yr	Agency/Indiv. ID
1	1	01101	0220	00003	002	1991	12	090678	CEA
1	3	4	7	8	12	13	15	16	18
								52	54
								59	66
								68	80

Compliance Status

Line 2 (Dup. cols. 1-15 from Line 1)

01051
16 18

31
78

RECEIVED
191
000

(NOTE: Columns not shown must be left blank)
(Do not punch Line 2 if column 78 is blank)

Company: Martin Marietta Cement SIC: _____
Address: PO 467, Lyons County: Boulder
Person Contacted: Gerald Anderson Phone: _____
Inspected by: Ken Mendel Time: 1:30 PM

Routine inspection on Regulation #1
In compliance by inspection.
Primary + Secondary Crushers.
No visible emissions seen.
Baghouse filter system.

Key Punch Data:		County Number	Source Number	Emission Point #	Action Type	Date Mo Day Yr	Agency/Indiv. ID
L	1	101101	0220	00003	001	1917	12
		1	3	7	8	12	13

Compliance Status

Line 2 (Dup. cols. 1-15 from Line 1)

101051	31	101
16	18	78
		80

(NOTE: Columns not shown must be left blank)
(Do not punch Line 2 if column 78 is blank)

Company: Martin Marietta Cement SIC: _____
 Address: PO 467, Lyons County: Boulder
 Person Contacted: Cecilia Anderson Phone: _____
 Inspected by: Kerr Messer Time: 1:30 AM/PM (C)

Routine inspection on Regulation #1
 In compliance by inspection.
 Cement Kiln dryer grinder.

Baghouse filter system, in operation
 at time of inspection. No emissions
 visible.

Kerogen afterburner will be installed by
 January 1980

Key Punch Data:		County	Source	Emission	Action	Date	Agency/
		Number	Number	Point #	Type	Mo Day Yr	Indiv. ID
1	01101	02201	00003	001	19171	11223771	11111
1	3	4	7	8	12	13	15
16	18	52	54	59	66	68	80

Compliance Status

Line 2 (Dup. cols. 1-15 from Line 1)

01051	31	101
16	18	78
		80

(NOTE: Columns not shown must be left blank)
 (Do not punch Line 2 if column 78 is blank)

Company: MARTIN MARIETTA CEMENT SIC: _____
 Address: LYONS County: BOULDER
 Person Contacted: _____ Phone: _____
 Inspected by: ROGERS Time: 7:30 AM/PM

OBSERVED KILN STACK EMISSIONS IN RESPONSE
 TO A COMPLAINT OF EXCESSIVE EMISSIONS,
 KILN IN OPERATION BUT NO VISIBLE EMIS-
 SIONS WHATEVER WERE OBSERVED, THIS SOURCE
 HAS BEEN, AND WILL CONTINUE TO BE KEPT
 UNDER REGULAR SURVEILLANCE, PARTICULARLY
 DURING MORNING HOURS WHEN VIOLATIONS
 ARE MOST LIKELY.

FILE
 INDEXED
 SERIALIZED
 10-1-68

ACTION TYPE -- DESCRIPTION

12 - Inspection
22 - Source Test
23 - Opacity Observation
24 - Odor Observation

COMPLIANCE STATUS CODES

0 - Unknown
1 - Not in Compliance
2 - In Compliance by Source Test
3 - In Compliance by Inspection
4 - In Compliance by Certification
5 - In Compliance with Increments of Progress
6 - Not in Compliance with Increments of Progress
7 - Unknown Compliance with Increments of Progress
8 - No Applicable State Regulation
9 - In Compliance -- Closed Down

AIR

ION CONTROL - FIELD INSPEC

ORK SHEET

Key Punch Data:				County Number	Source Number	Emission Point #	Action Type	Date Mo Day Yr			Agency/ Indiv. ID			
1	0	1	0	02	00003	AA4	23	1	2	3	7	7	1	N
1	3	4	7	8	12	13	15	16	18	52	54	59	66	80

Compliance Status

Line 2 (Dup. cols. 1-15 from Line 1)

0	0	5	3	1
16	18	78	80	

(NOTE: Columns not shown must be left blank)
(Do not punch Line 2 if column 78 is blank)

Company: MARTIN MARIETTA CEMENT SIC: _____
 Address: LTOWS County: BOULDER
 Person Contacted: _____ Phone: _____
 Inspected by: RAHRS Time: 7:30 AM/PM

OBSERVED FUGITIVE EMISSIONS FROM
 OPEN CEMENT STORAGE, STORAGE PILE
 COVERED BY A-FRAME SHED OPEN
 ON SOUTH SIDE. NO EMISSIONS OF
 20% OR GREATER, BUT APPEARS TO HAVE
 THE POTENTIAL FOR VIOLATIONS.

ACTION TYPE - DESCRIPTION

12 - Inspection
22 - Source Test
23 - Opacity Observation
24 - Odor Observation

COMPLIANCE STATUS CODES

0 - Unknown
1 - Not in Compliance
2 - In Compliance by Source Test
3 - In Compliance by Inspection
4 - In Compliance by Certification
5 - In Compliance with Increments of Progress
6 - Not in Compliance with Increments of Progress
7 - Unknown Compliance with Increments of Progress
8 - No Applicable State Regulation
9 - In Compliance -- Closed Down