Empire Pass Master Owner's Association

Level 2 Reserve Study



Report Period - 01/01/2021 - 12/31/2021

Client Reference Number	10620
Property Type	Master
Number of Units	550
Fiscal Year End	12/31

Type of Study

Date of Property Inspection

Prepared By

Analysis Method

Funding Goal

Update w/Site Visit
6/11/2020

Dale Gifford
Cash Flow
Full Funding

Report prepared on - Thursday, July 16, 2020



TEL: (888) 356-3783 | Fax: (866) 279-9662 | WWW.COMPLEXSOLUTIONSLTD.COM

Table of Contents

Introduction

•	Executive Summary	page 1
•	Introduction	page 2
•	General Information and Frequently Asked Questions	page 3 - 4

Reserve Analysis

•	Funding Summary	page 5
•	Percent Funded – Graph	page 6
•	Component Inventory	page 7
•	Significant Components	page 8
•	Significant Components – Graph	page 9
•	Yearly Summary	page 10
•	Yearly Reserve Contributions – Graph	page 11
•	Component Funding Information	page 12 - 13
•	Yearly Cash Flow	page 14
•	Yearly Reserve Expenditures – Graph	page 15
•	Projected Reserve Expenditures by Year	page 16 - 21

Component Evaluation

• Component Evaluation page 1 - 29

Glossary of Commonly used Words and Phrases

Executive Summary – Empire Pass Master Owner's Association – ID # 10620

Information to complete this Reserve Study was gathered by performing an on-site inspection of the common area elements. In addition, we also obtained information by contacting any vendors and/or contractors that have worked on the property recently, as well as communicating with the property representative (BOD Member and/or Community Manager). To the best of our knowledge, the conclusions and recommendations of this report are considered reliable and accurate insofar as the information obtained from these sources.

Projected Starting Balance as of 01/01/2021	\$876,949
Ideal Reserve Balance as of 01/01/2021	\$768,288
Percent Funded as of 01/01/2021	114%
Recommended Reserve Contribution (per month)	\$14,150
Recommended Special Assessment	\$0

Empire Pass Master Owner's Association is a 550-unit Master community. Construction on the community was completed in ongoing.

Currently Programmed Projects

Projects programmed to occur this fiscal year (FY2021) include sign posts repaint (Comp# 213), stone veneer repairs (Comp# 390), asphalt 2019 slurry seal (Comp# 402), asphalt 2021 slurry seal (Comp# 402), asphalt crack seal (Comp# 403), curbing partial replace (Comp# 406), asphalt Ruby Hollow replace (Comp# 490), sign posts install/replace (Comp# 808), guard rails repair (Comp# 1007), retaining walls repair (Comp# 1890), water lines repair (Comp# 2090), and metal bridge maintenance (Comp# 2302). We have programmed an estimated \$159,850 in reserve expenditures toward the completion of these projects. (See page 15)

Significant Reserve Projects

The association's significant reserve projects are stone veneer repairs (Comp# 390), asphalt twisted branch major rehab (Comp# 401), asphalt slurry seal (Comp# 402), and asphalt crack seal (Comp# 403). The fiscal significance of these components is approximately 14%, 12%, 10%, and 8% respectively (see page 9). A component's significance is calculated by dividing its replacement cost by its useful life. In this way, not only is a component's replacement cost considered but also the frequency of occurrence. These components most significantly contribute to the total monthly reserve contribution. As these components have a high level of fiscal significance the association should properly maintain them to ensure they reach their full useful lives.

Reserve Funding

In comparing the projected starting reserve balance of \$876,949 versus the ideal reserve balance of \$768,288 we find the association's reserve fund to be approximately 114% funded. This indicates a strong reserve fund position. In order to continue to strengthen the account fund, we suggest adopting a monthly reserve contribution of \$14,150 (\$25.73/unit) per month. If the contribution falls below this rate, then the reserve fund may fall into a situation where special assessments, deferred maintenance, and lower property values are likely at some point in the future.

Introduction

Reserve Study Purpose

The purpose of this Reserve Study is to provide the Association with a budgeting tool to help ensure that there are adequate reserve funds available to perform future reserve projects. The detailed schedules will serve as an advance warning that major projects will need to be addressed in the future. This will allow the Association to have ample time to obtain competitive bids for each project. It will also help to ensure the physical well-being of the property and ultimately enhance each owner's investment, while limiting the possibility of unexpected major projects that may lead to special assessments.

Preparer's Credentials

Mr. Gifford has been working in the community association industry for the last 16 years. Prior to taking a position, as the Regional Project Manager covering the Utah region, at Complex Solutions, he worked in community association management in Utah. While in community association management his positions included, Maintenance Supervisor, Senior Portfolio Manager and Vice President of Community Management. His work in community association management gave him extensive experience with; budget creation, reserves and reserve budgeting, community inspections and analyzing common area components.

- Professional Reserve Analyst (PRA) designation from Association of Professional Reserve Analysts (APRA), PRA #2320
- Reserve Specialist (RS) designation from Community Associations Institute (CAI), RS# 231
- Personally has prepared over 1,400 reserve studies in Salt Lake City Utah and surrounding areas
- Bachelor of Science in Chemistry from Emporia State University
- Certified Manager of Community Associations® (CMCA®) designation from the National Board of Certification for Community Association Managers (NBC-CAM)
- Association Management Specialist® (AMS®) designation from Community Associations Institute (CAI)
- Professional Community Association Manager® (PCAM®) designation from Community Associations Institute (CAI). PCAM# 1740.
- Active member and former Board member and chapter President of the Utah Chapter of Community Associations Institute (UCCAI)
- Recipient of Community Associations Institute's (CAI) annual award of Excellence in Chapter Leadership for service an achievement in 2010

Budget Breakdown

Every association conducts their business within a budget. There are typically two main parts to this budget, the Operating budget and the Reserve budget. The operating budget includes all expenses that occur on an annual basis as well as general maintenance and repairs. Typical operating budget line items include management fees, maintenance expenses, utilities, etc. The reserve budget is primarily made up of replacement items such as roofing, fencing, mechanical equipment, etc., that do not normally occur on an annual basis.

Report Sections

Reserve Analysis: this section contains the evaluation of the association's reserve balance, income, and expenses. It includes a finding of the client's current reserve fund status (measured as percent funded) and a recommendation for an appropriate reserve allocation rate (also known as the funding plan).

Component Evaluation: this section contains information regarding the physical status and replacement cost of reserve components the association is responsible to maintain. It is important to understand that while the component inventory will remain relatively "stable" from year to year, the condition assessment and life estimates will most likely vary from year to year.

General Information and Frequently Asked Questions

Is it the law to have a Reserve Study conducted?

The Government requires a reserve study in approximately 20 states. Also, the Association's governing documents may require a reserve fund be established. This does not mean a Reserve Study is required, but how are you going to know if you have enough money in the reserve fund if you do not have the proper information?

Why is it important to perform a Reserve Study?

This report provides the essential information that is needed to guide the Association in establishing the reserve portion of the total monthly assessment. The reserve fund is critical to the future of the association because it helps ensure that reserve projects can be completed on time. When projects are completed on time, deferred maintenance and the lower property values that typically accompany it can be avoided. It is suggested that a third party professionally prepare the Reserve Analysis Study since there is no vested interest in the property.

After we have a Reserve Study, what do we do with it?

Please take the time to review the report carefully and make sure the component information is complete and accurate. If there are any inaccuracies, or changes such as a component that the association feels should be added, removed, or altered, please inform us immediately so we may revise the report. Use the report to help establish your budget for the upcoming fiscal year.

How often do we review and update our Reserve Study?

There is a misconception that a Reserve Study is good for an extended period of time since the report has projections for a thirty year period. The assumptions, interest rates, inflation rates and other information used to create this report change each year. Scheduled events may not happen, unpredictable circumstances could occur, deterioration rates can be unpredictable and repair/replacement costs will vary from causes that are unforeseen. These variations alter the results of the Reserve Study. The Reserve Study should be professionally reviewed each year by having a Level III "no site visit" update reserve study performed. The Reserve Study should be professionally updated every three years by having a Level II "site visit" update reserve study performed.

What is a "Reserve Component" versus an "Operating Component"?

A "Reserve" component is an item that is the responsibility of the association to maintain, has a limited useful life, predictable remaining useful life, typically occurs on a cyclical basis that exceeds one year, and costs above a minimum threshold amount. An "Operating" component is typically a fixed expense that occurs on an annual basis.

What are the GREY areas of "maintenance" items that are often seen in a Reserve Study?

One of the most popular questions revolves around major "maintenance" items, such as painting the buildings or seal coating the asphalt. You may hear from your accountant that since painting or seal coating is not replacing a "capital" item, it cannot be considered a reserve component. However, it is the opinion of several major Reserve Study providers, including Complex Solutions, that these components meet the criteria of a reserve component.

Information and Data Gathered:

The information contained in this report is based on estimates and assumptions gathered from various sources. Estimated life expectancies are based upon conditions that were readily visible and accessible at the time of the site visit. While every effort has been made to ensure accurate results, this report reflects the judgment of Complex Solutions, Ltd. and should not be construed as a guarantee or assurance of predicting future events.

What happens during the Site Visit?

During the site visit we identify the common area components that we have determined require reserve funding. These components are quantified and a physical condition is observed. The site visit is conducted on the common areas as reported by client.

What is the Financial Analysis?

We project the starting balance by taking the most recent reserve fund balance as stated by the client and add expected reserve contributions to the end of the fiscal year. We then subtract the expenses of any pending projects. We compare this number to the Fully Funded Balance and arrive at the Percent Funded level. Based on that level of funding we then recommend a Funding Plan to help ensure the adequacy of funding in the future.

Measures of reserve fund financial strength are as follows:

- 0% 30% Funded is considered a "weak" financial position. Associations that fall into this category are more likely to have special assessments and deferred maintenance. Action should be taken to improve the financial strength of the reserve fund.
- **31% 69% Funded** is considered a "fair" financial position. Associations that fall into this category are less likely to experience special assessments and deferred maintenance than being in a weak financial position. Action should be taken to improve the financial strength of the reserve fund.
- 70% 99% Funded is considered a "strong" financial position. Associations that fall into this category are less likely to experience special assessments and deferred maintenance than being in a fair financial position. Action should be taken to improve the financial strength of the reserve fund.
- 100% Funded is considered an "ideal" financial position. Action should be taken to maintain the financial strength of the reserve

Disclosures:

Information provided to the preparer of a reserve study by an official representative of the association regarding financial, historical, physical, quantitative or reserve project issues will be deemed reliable by the preparer. A reserve study will be a reflection of information provided to the preparer of the reserve study. The total of actual or projected reserves required as presented in the reserve study is based upon information provided that was not audited.

A reserve study is not intended to be used to perform an audit, an analysis of quality, a forensic study or a background check of historical records. An on-site inspection conducted in conjunction with a reserve study should not be deemed to be a project audit or quality inspection.

The results of this study are based on the independent opinion of the preparer and his experience and research during the course of his career in preparing Reserve Studies. In addition the opinions of experts on certain components have been gathered through research within their industry and with client's actual vendors. There is no implied warrantee or guarantee regarding our life and cost estimates/predictions. There is no implied warrantee in any of our work product. Our results and findings will vary from another preparer's results and findings. A Reserve Study is necessarily a work in progress and subsequent Reserve Studies will vary from prior studies.

The projected life expectancy of the reserve components and the funding needs of the reserves of the association are based upon the association performing appropriate routine and preventative maintenance for each component. Failure to perform such maintenance can negatively impact the remaining useful life of the component and dramatically increase the funding needs of the reserves of the association.

This Reserve Study assumes that all construction assemblies and components identified herein are built properly and are free from defects in materials and/or workmanship. Defects can lead to reduced useful life and premature failure. It was not the intent of this Reserve Study to inspect for or to identify defects. If defects exist, repairs should be made so that the construction components and assemblies at the community reach the full and expected useful lives.

Site Visits: Should a site visit have been performed during the preparation of this reserve study no invasive testing was performed. The physical analysis performed during the site visit was not intended to be exhaustive in nature and may have included representative sampling. Estimated life expectancies and life cycles are based upon conditions that were readily accessible and visible at the time of the site visit. We have assumed any and all components have been properly built and will reach normal, typical life expectancies. A reserve study is not intended to identify or fund for construction defects. We did not and will not look for or identify construction defects during our site visit. In addition, environmental hazards (such as lead paint, asbestos, radon, etc.), have been excluded from this report.

Update Reserve Studies:

Level II Studies: Quantities of major components as reported in previous reserve studies are deemed to be accurate and reliable. The reserve study relies upon the validity of previous reserve studies.

Level III Studies: In addition to the above we have not visited the property when completing a Level III "No Site Visit" study. Therefore we have not verified the current condition of the components.

Insurance: We carry general and professional liability insurance as well as workers' compensation insurance.

Actual or Perceived Conflicts of Interest: There are no potential actual or perceived conflicts of interest that we are aware of.

Inflation and Interest Rates: The after tax interest rate used in the financial analysis may or may not be based on the clients reported after tax interest rate. If it is, we have not verified or audited the reported rate. The inflation rate may also be based on an amount we believe appropriate given the 30-year horizon of this study and may or may not reflect current or historical inflation rates.

Funding Summary

Beginning	Assum	ptions

# of units	550
Fiscal Year End	31-Dec
Budgeted Monthly Reserve Allocation	\$8,333
Projected Starting Reserve Balance	\$876,949
Ideal Starting Reserve Balance	\$768,288

Economic Assumptions

Projected Inflation Rate	3.00%
Reported After-Tax Interest Rate	0.10%

Current Reserve Status

Current Balance as a % of Ideal Balance	114%
Current Dalance as a 70 or lucal Dalance	117/0

Recommendations


Recommended Monthly Reserve Allocation	\$14,150
Per Unit	\$25.73
Future Annual Increases	3.00%
For number of years:	30
Increases thereafter:	0.00%
70% Funded Monthly Reserve Allocation Reference	\$13,275
Per Unit	\$24.14
Future Annual Increases	3.00%
For number of years:	30
Increases thereafter:	0.00%

Changes From Prior Year

Recommended Increase to Reserve Allocation	\$5,817
as Percentage	70%



Percent Funded - Graph





Component Inventory

Category	ID#	Component Name	Useful Life (yrs.)	Remaining Useful Life (yrs.)	DAGE	Worst Cost
Roofing	107	Transit Center Roof - Replace	25	8	\$3,000	\$5,000
	120	Transit Center Guttering - Repair/Re	eplac N/A		\$0	\$0
Painted Surfaces	213	Sign Posts - Repaint	1	0	\$1,000	\$1,100
	217	Transit Center - Repair/Repaint	6	4	\$3,400	\$3,600
	219	Wood Surfaces - Stain	4	1	\$35,000	\$37,000
Siding Materials	390	Stone Veneer - Repairs	1	0	\$20,000	\$22,000
Drive Materials	401	Asphalt - Banner Court - Major Reha	ab 16	4	\$14,000	\$18,000
	401	Asphalt - Empire Club Drive - Major	Reha 16	18	\$92,000	\$122,000
	401	Asphalt - Hawkeye Place - Major Re	hab 16	1	\$19,000	\$23,000
	401	Asphalt - Northside Court - Major Re	ehab 16	6	\$16,000	\$21,000
	401	Asphalt - Red Cloud Trail - Major Re	ehab 16	2	\$61,000	\$81,000
	401	Asphalt - Red Cloud Trail 2016 - Ma	jor R 16	11	\$75,000	\$100,000
	401	Asphalt - Ruby Hollow - Major Reha	b 16	16	\$22,950	\$30,600
	401	Asphalt - Silver Strike Trail - Major F	Reha 16	11	\$46,950	\$62,600
	401	Asphalt - Twisted Branch - Major Re	hab 16	3	\$252,900	\$337,200
	401	Asphalt - Village Way - Major Rehab	16	15	\$31,000	\$41,000
	402	Asphalt - 2018 - Slurry Seal	3	0	\$2,500	\$2,700
	402	Asphalt - 2021 - Slurry Seal	3	0	\$34,000	\$38,000
	402	Asphalt - Slurry Seal	3	1	\$44,000	\$48,000
	403	Asphalt - Crack Seal	1	0	\$12,000	\$14,000
	406	Curbing - Partial Replace	10	0	\$18,000	\$22,000
	490	Asphalt - Ruby Hollow - Replace	99	0	\$35,000	\$45,000
Prop. Identification	า 801	Monument Signs - Refurbish	20	4	\$9,000	\$10,500
	808	Sign Posts - Install/Replace	1	0	\$2,000	\$2,200
Life / Safety	903	Camera System - Replace	8	3	\$1,600	\$1,800
	990	Fire Hydrants - Repair/Replace	3	2	\$5,000	\$6,000
Fencing	1007	Guard Rails - Repair	1	0	\$2,000	\$2,200
Light Fixtures	1604	Bridge & Pole Lights - Replace	20	5	\$161,000	\$184,000
Landscaping	1890	Retaining Walls - Repair	10	0	\$5,000	\$6,000
Utility Systems	2090	Water Lines - Repair	1	0	\$5,000	\$6,000
Buildings / Structu	2302	Bridges Surfaces - Refurbish	20	18	\$145,000	\$155,000
	2302	Metal Bridge - Maintenance	4	0	\$10,000	\$12,000



Significant Components


ID#	ID # Component Name		Useful Remaining Life Useful Life	Average Current	Significance: (Curr Cost/UL)	
		(yrs.)	(yrs.)	Cost	As\$	As %
107	Transit Center Roof - Replace	25	8	\$4,000	\$160	0.1049%
213	Sign Posts - Repaint	1	0	\$1,050	\$1,050	0.6885%
217	Transit Center - Repair/Repaint	6	4	\$3,500	\$583	0.3825%
219	Wood Surfaces - Stain	4	1	\$36,000	\$9,000	5.9016%
390	Stone Veneer - Repairs	1	0	\$21,000	\$21,000	13.7703%
401	Asphalt - Banner Court - Major Rehab	16	4	\$16,000	\$1,000	0.6557%
401	Asphalt - Empire Club Drive - Major Rel	16	18	\$107,000	\$6,688	4.3852%
401	Asphalt - Hawkeye Place - Major Rehat	16	1	\$21,000	\$1,313	0.8606%
401	Asphalt - Northside Court - Major Rehal	16	6	\$18,500	\$1,156	0.7582%
401	Asphalt - Red Cloud Trail - Major Rehat	16	2	\$71,000	\$4,438	2.9098%
401	Asphalt - Red Cloud Trail 2016 - Major I	16	11	\$87,500	\$5,469	3.5860%
401	Asphalt - Ruby Hollow - Major Rehab	16	16	\$26,775	\$1,673	1.0973%
401	Asphalt - Silver Strike Trail - Major Reha	16	11	\$54,775	\$3,423	2.2449%
401	Asphalt - Twisted Branch - Major Rehat	16	3	\$295,050	\$18,441	12.0921%
401	Asphalt - Village Way - Major Rehab	16	15	\$36,000	\$2,250	1.4754%
402	Asphalt - 2018 - Slurry Seal	3	0	\$2,600	\$867	0.5683%
402	Asphalt - 2021 - Slurry Seal		0	\$36,000	\$12,000	7.8688%
402	Asphalt - Slurry Seal	3	1	\$46,000	\$15,333	10.0545%
403	Asphalt - Crack Seal	1	0	\$13,000	\$13,000	8.5245%
406	Curbing - Partial Replace	10	0	\$20,000	\$2,000	1.3115%
490	Asphalt - Ruby Hollow - Replace	99	0	\$40,000	\$0	0.0000%
801	Monument Signs - Refurbish	20	4	\$9,750	\$488	0.3197%
808	Sign Posts - Install/Replace	1	0	\$2,100	\$2,100	1.3770%
903	Camera System - Replace	8	3	\$1,700	\$213	0.1393%
990	Fire Hydrants - Repair/Replace	3	2	\$5,500	\$1,833	1.2022%
1007	Guard Rails - Repair	1	0	\$2,100	\$2,100	1.3770%
1604	Bridge & Pole Lights - Replace	20	5	\$172,500	\$8,625	5.6557%
1890	Retaining Walls - Repair	10	0	\$5,500	\$550	0.3607%
2090	Water Lines - Repair	1	0	\$5,500	\$5,500	3.6065%
2302	Bridges Surfaces - Refurbish	20	18	\$150,000	\$7,500	4.9180%
2302	Metal Bridge - Maintenance	4	0	\$11,000	\$2,750	1.8033%



Significant Components - Graph



- ■401 Asphalt Twisted Branch Major Rehab
- ■402 Asphalt Slurry Seal
- ■403 Asphalt Crack Seal
- ■All Other



ID#	O# Component Name		Remaining Useful Life	Average Current	Signification (Curr Co.	
		(yrs.)	(yrs.)	Cost	As\$	As %
390	Stone Veneer - Repairs	1	0	\$21,000	\$21,000	14%
401	Asphalt - Twisted Branch - Major Reha	16	3	\$295,050	\$18,441	12%
402	Asphalt - Slurry Seal	3	1	\$46,000	\$15,333	10%
403	Asphalt - Crack Seal	1	0	\$13,000	\$13,000	8%
All Other	See Expanded Table For Breakdown				\$84,728	56%




Yearly Summary

Year	Fully Funded	Starting Reserve	%	Reserve	Interest	Reserve	Ending Reserve
	Balance	Balance	Funded	Contributions	Income	Expenses	Balance
2021	\$768,288	\$876,949	114%	\$169,800	\$882	\$159,850	\$887,781
2022	\$776,880	\$887,781	114%	\$174,894	\$900	\$152,183	\$911,392
2023	\$798,133	\$911,392	114%	\$180,141	\$938	\$128,634	\$963,837
2024	\$856,226	\$963,837	113%	\$185,545	\$849	\$415,346	\$734,885
2025	\$625,749	\$734,885	117%	\$191,111	\$757	\$147,442	\$779,312
2026	\$669,448	\$779,312	116%	\$196,845	\$728	\$299,962	\$676,923
2027	\$562,665	\$676,923	120%	\$202,750	\$718	\$121,614	\$758,777
2028	\$641,840	\$758,777	118%	\$208,833	\$808	\$111,611	\$856,806
2029	\$739,321	\$856,806	116%	\$215,098	\$923	\$82,657	\$990,170
2030	\$875,344	\$990,170	113%	\$221,550	\$1,024	\$155,725	\$1,057,020
2031	\$946,157	\$1,057,020	112%	\$228,197	\$1,091	\$160,934	\$1,125,374
2032	\$1,019,878	\$1,125,374	110%	\$235,043	\$1,109	\$268,853	\$1,092,673
2033	\$990,987	\$1,092,673	110%	\$242,094	\$1,147	\$134,521	\$1,201,393
2034	\$1,106,114	\$1,201,393	109%	\$249,357	\$1,234	\$186,137	\$1,265,847
2035	\$1,178,249	\$1,265,847	107%	\$256,838	\$1,357	\$76,008	\$1,448,034
2036	\$1,372,901	\$1,448,034	105%	\$264,543	\$1,488	\$185,943	\$1,528,122
2037	\$1,467,287	\$1,528,122	104%	\$272,479	\$1,559	\$211,861	\$1,590,299
2038	\$1,545,151	\$1,590,299	103%	\$280,654	\$1,643	\$177,268	\$1,695,327
2039	\$1,668,543	\$1,695,327	102%	\$289,073	\$1,490	\$700,296	\$1,285,595
2040	\$1,264,707	\$1,285,595	102%	\$297,745	\$1,095	\$679,484	\$904,952
2041	\$878,215	\$904,952	103%	\$306,678	\$966	\$185,578	\$1,027,017
2042	\$997,115	\$1,027,017	103%	\$315,878	\$1,074	\$222,026	\$1,121,944
2043	\$1,090,550	\$1,121,944	103%	\$325,354	\$1,177	\$216,041	\$1,232,435
2044	\$1,201,720	\$1,232,435	103%	\$335,115	\$1,351	\$99,173	\$1,469,728
2045	\$1,445,628	\$1,469,728	102%	\$345,168	\$1,537	\$211,614	\$1,604,820
2046	\$1,590,339	\$1,604,820	101%	\$355,523	\$1,470	\$626,563	\$1,335,250
2047	\$1,321,573	\$1,335,250	101%	\$366,189	\$1,465	\$108,369	\$1,594,535
2048	\$1,588,351	\$1,594,535	100%	\$377,175	\$1,531	\$504,955	\$1,468,287
2049	\$1,464,811	\$1,468,287	100%	\$388,490	\$1,543	\$240,804	\$1,617,516
2050	\$1,620,107	\$1,617,516	100%	\$400,145	\$1,717	\$203,254	\$1,816,123



Reserve Contributions - Graph





Component Funding Information

ID	Component Name	UL	RUL	Quantity	Average Current Cost	Ideal Balance	Current Fund Balance	Monthly
107	Transit Center Roof - Replace	25	8	Approx 340 Sq.ft.	\$4,000	\$2,720	\$3,105	\$14.85
213	Sign Posts - Repaint	1	0	(52) Sign Posts	\$1,050	\$1,050	\$1,199	\$97.43
217	Transit Center - Repair/Repaint	6	4	(1) Transit Center	\$3,500	\$1,167	\$1,332	\$54.13
219	Wood Surfaces - Stain	4	1	See General Notes	\$36,000	\$27,000	\$30,819	\$835.07
390	Stone Veneer - Repairs	1	0	Extensive Sq.ft.	\$21,000	\$21,000	\$23,970	\$1,948.50
401	Asphalt - Banner Court - Major Rehab	16	4	Approx 8,825 Sq.ft.	\$16,000	\$12,000	\$13,697	\$92.79
401	Asphalt - Empire Club Drive - Major Rehab	16	18	Approx 60,750 Sq.ft.	\$107,000	\$0	\$0	\$620.51
401	Asphalt - Hawkeye Place - Major Rehab	16	1	Approx 12,300 Sq.ft.	\$21,000	\$19,688	\$22,472	\$121.78
401	Asphalt - Northside Court - Major Rehab	16	6	Approx 10,050 Sq.ft.	\$18,500	\$11,563	\$13,198	\$107.28
401	Asphalt - Red Cloud Trail - Major Rehab	16	2	Approx 40,425 Sq.ft.	\$71,000	\$62,125	\$70,911	\$411.74
401	Asphalt - Red Cloud Trail 2016 - Major Rehal	16	11	Approx 50,000 Sq.ft.	\$87,500	\$27,344	\$31,211	\$507.42
401	Asphalt - Ruby Hollow - Major Rehab	16	16	Approx 15,300 Sq.ft.	\$26,775	\$0	\$0	\$155.27
401	Asphalt - Silver Strike Trail - Major Rehab	16	11	Approx 31,300 Sq.ft.	\$54,775	\$17,117	\$19,538	\$317.65
401	Asphalt - Twisted Branch - Major Rehab	16	3	Approx 168,600 Sq.ft.	\$295,050	\$239,728	\$273,633	\$1,711.03
401	Asphalt - Village Way - Major Rehab	16	15	Approx 20,225 Sq.ft.	\$36,000	\$2,250	\$2,568	\$208.77
402	Asphalt - 2018 - Slurry Seal	3	0	Approx 12,300 Sq.ft.	\$2,600	\$2,600	\$2,968	\$80.41
402	Asphalt - 2021 - Slurry Seal	3	0	Approx 178,650 Sq.ft.	\$36,000	\$36,000	\$41,092	\$1,113.43
402	Asphalt - Slurry Seal	3	1	Approx 226,825 Sq.ft.	\$46,000	\$30,667	\$35,004	\$1,422.72
403	Asphalt - Crack Seal	1	0	Approx 417,775 Sq.ft.	\$13,000	\$13,000	\$14,839	\$1,206.22
406	Curbing - Partial Replace	10	0	Approx 5,735 Linear ft.	\$20,000	\$20,000	\$22,829	\$185.57
490	Asphalt - Ruby Hollow - Replace	99	0	Approx 15,300 Sq.ft.	\$40,000	\$40,000	\$45,657	\$0.00
801	Monument Signs - Refurbish	20	4	(3) Signs	\$9,750	\$7,800	\$8,903	\$45.23
808	Sign Posts - Install/Replace	1	0	(52) Sign Posts	\$2,100	\$2,100	\$2,397	\$194.85
903	Camera System - Replace	8	3	(1) System	\$1,700	\$1,063	\$1,213	\$19.72
990	Fire Hydrants - Repair/Replace	3	2	(1) System	\$5,500	\$1,833	\$2,093	\$170.11
1007	Guard Rails - Repair	1	0	Approx 4,645 Linear ft.	\$2,100	\$2,100	\$2,397	\$194.85
1604	Bridge & Pole Lights - Replace	20	5	(23) Fixtures	\$172,500	\$129,375	\$147,673	\$800.28
1890	Retaining Walls - Repair	10	0	Extensive Sq.ft.	\$5,500	\$5,500	\$6,278	\$51.03
2090	Water Lines - Repair	1	0	Extensive Linear ft.	\$5,500	\$5,500	\$6,278	\$510.32
2302	Bridges Surfaces - Refurbish	20	18	(5) Structures	\$150,000	\$15,000	\$17,121	\$695.89



ID	Component Name	nr	RUL	Quantity	Average Current Cost	Ideal Balance	Current Fund Balance	Monthly
2302	Metal Bridge - Maintenance	4	0	(1) Bridge	\$11,000	\$11,000	\$12,556	\$255.16
					\$1,322,400	\$768,288	\$876,949	\$14,150

Current Fund Balance as a percentage of Ideal Balance: 114%




Yearly Cash Flow

Year	2021	2022	2023	2024	2025
Starting Balance	\$876,949	\$887,781	\$911,392	\$963,837	\$734,885
Reserve Income	\$169,800	\$174,894	\$180,141	\$185,545	\$191,111
Interest Earnings	\$882	\$900	\$938	\$849	\$757
Special Assessments	\$0	\$0	\$0	\$0	\$0
Funds Available	\$1,047,631	\$1,063,575	\$1,092,471	\$1,150,231	\$926,754
Reserve Expenditures	\$159,850	\$152,183	\$128,634	\$415,346	\$147,442
Ending Balance	\$887,781	\$911,392	\$963,837	\$734,885	\$779,312
Year	2026	2027	2028	2029	2030
Starting Balance	\$779,312	\$676,923	\$758,777	\$856,806	\$990,170
Reserve Income	\$196,845	\$202,750	\$208,833	\$215,098	\$221,550
Interest Earnings	\$728	\$718	\$808	\$923	\$1,024
Special Assessments	\$0	\$0	\$0	\$0	\$0
Funds Available	\$976,885	\$880,391	\$968,417	\$1,072,827	\$1,212,744
Reserve Expenditures	\$299,962	\$121,614	\$111,611	\$82,657	\$155,725
Ending Balance	\$676,923	\$758,777	\$856,806	\$990,170	\$1,057,020
Year	2031	2032	2033	2034	2035
Starting Balance	\$1,057,020	\$1,125,374	\$1,092,673	\$1,201,393	\$1,265,847
Reserve Income	\$228,197	\$235,043	\$242,094	\$249,357	\$256,838
Interest Earnings	\$1,091	\$1,109	\$1,147	\$1,234	\$1,357
Special Assessments	\$0	\$0	\$0	\$0	\$0
Funds Available	\$1,286,308	\$1,361,526	\$1,335,914	\$1,451,984	\$1,524,042
Reserve Expenditures	\$160,934	\$268,853	\$134,521	\$186,137	\$76,008
Ending Balance	\$1,125,374	\$1,092,673	\$1,201,393	\$1,265,847	\$1,448,034
Year	2036	2037	2038	2039	2040
Starting Balance	\$1,448,034	\$1,528,122	\$1,590,299	\$1,695,327	\$1,285,595
Starting Balance Reserve Income	\$1,448,034 \$264,543	\$1,528,122 \$272,479	\$1,590,299 \$280,654	\$1,695,327 \$289,073	\$1,285,595 \$297,745
Starting Balance Reserve Income Interest Earnings	\$1,448,034 \$264,543 \$1,488	\$1,528,122 \$272,479 \$1,559	\$1,590,299 \$280,654 \$1,643	\$1,695,327 \$289,073 \$1,490	\$1,285,595 \$297,745 \$1,095
Starting Balance Reserve Income Interest Earnings Special Assessments	\$1,448,034 \$264,543 \$1,488 \$0	\$1,528,122 \$272,479 \$1,559 \$0	\$1,590,299 \$280,654 \$1,643 \$0	\$1,695,327 \$289,073 \$1,490 \$0	\$1,285,595 \$297,745 \$1,095 \$0
Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available	\$1,448,034 \$264,543 \$1,488 \$0 \$1,714,065	\$1,528,122 \$272,479 \$1,559 \$0 \$1,802,160	\$1,590,299 \$280,654 \$1,643 \$0 \$1,872,595	\$1,695,327 \$289,073 \$1,490 \$0 \$1,985,891	\$1,285,595 \$297,745 \$1,095 \$0 \$1,584,435
Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available Reserve Expenditures	\$1,448,034 \$264,543 \$1,488 \$0 \$1,714,065 \$185,943	\$1,528,122 \$272,479 \$1,559 \$0 \$1,802,160 \$211,861	\$1,590,299 \$280,654 \$1,643 \$0 \$1,872,595 \$177,268	\$1,695,327 \$289,073 \$1,490 \$0 \$1,985,891 \$700,296	\$1,285,595 \$297,745 \$1,095 \$0 \$1,584,435 \$679,484
Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available	\$1,448,034 \$264,543 \$1,488 \$0 \$1,714,065	\$1,528,122 \$272,479 \$1,559 \$0 \$1,802,160	\$1,590,299 \$280,654 \$1,643 \$0 \$1,872,595	\$1,695,327 \$289,073 \$1,490 \$0 \$1,985,891	\$1,285,595 \$297,745 \$1,095 \$0 \$1,584,435
Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available Reserve Expenditures	\$1,448,034 \$264,543 \$1,488 \$0 \$1,714,065 \$185,943	\$1,528,122 \$272,479 \$1,559 \$0 \$1,802,160 \$211,861	\$1,590,299 \$280,654 \$1,643 \$0 \$1,872,595 \$177,268	\$1,695,327 \$289,073 \$1,490 \$0 \$1,985,891 \$700,296	\$1,285,595 \$297,745 \$1,095 \$0 \$1,584,435 \$679,484
Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available Reserve Expenditures Ending Balance	\$1,448,034 \$264,543 \$1,488 \$0 \$1,714,065 \$185,943 \$1,528,122	\$1,528,122 \$272,479 \$1,559 \$0 \$1,802,160 \$211,861 \$1,590,299	\$1,590,299 \$280,654 \$1,643 \$0 \$1,872,595 \$177,268 \$1,695,327 2043 \$1,121,944	\$1,695,327 \$289,073 \$1,490 \$0 \$1,985,891 \$700,296 \$1,285,595 2044 \$1,232,435	\$1,285,595 \$297,745 \$1,095 \$0 \$1,584,435 \$679,484 \$904,952
Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available Reserve Expenditures Ending Balance Year	\$1,448,034 \$264,543 \$1,488 \$0 \$1,714,065 \$185,943 \$1,528,122	\$1,528,122 \$272,479 \$1,559 \$0 \$1,802,160 \$211,861 \$1,590,299	\$1,590,299 \$280,654 \$1,643 \$0 \$1,872,595 \$177,268 \$1,695,327	\$1,695,327 \$289,073 \$1,490 \$0 \$1,985,891 \$700,296 \$1,285,595	\$1,285,595 \$297,745 \$1,095 \$0 \$1,584,435 \$679,484 \$904,952
Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available Reserve Expenditures Ending Balance Year Starting Balance	\$1,448,034 \$264,543 \$1,488 \$0 \$1,714,065 \$185,943 \$1,528,122 2041 \$904,952	\$1,528,122 \$272,479 \$1,559 \$0 \$1,802,160 \$211,861 \$1,590,299 2042 \$1,027,017	\$1,590,299 \$280,654 \$1,643 \$0 \$1,872,595 \$177,268 \$1,695,327 2043 \$1,121,944	\$1,695,327 \$289,073 \$1,490 \$0 \$1,985,891 \$700,296 \$1,285,595 2044 \$1,232,435	\$1,285,595 \$297,745 \$1,095 \$0 \$1,584,435 \$679,484 \$904,952 2045 \$1,469,728
Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available Reserve Expenditures Ending Balance Year Starting Balance Reserve Income	\$1,448,034 \$264,543 \$1,488 \$0 \$1,714,065 \$185,943 \$1,528,122 2041 \$904,952 \$306,678	\$1,528,122 \$272,479 \$1,559 \$0 \$1,802,160 \$211,861 \$1,590,299 2042 \$1,027,017 \$315,878	\$1,590,299 \$280,654 \$1,643 \$0 \$1,872,595 \$177,268 \$1,695,327 2043 \$1,121,944 \$325,354	\$1,695,327 \$289,073 \$1,490 \$0 \$1,985,891 \$700,296 \$1,285,595 2044 \$1,232,435 \$335,115	\$1,285,595 \$297,745 \$1,095 \$0 \$1,584,435 \$679,484 \$904,952 2045 \$1,469,728 \$345,168
Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available Reserve Expenditures Ending Balance Year Starting Balance Reserve Income Interest Earnings	\$1,448,034 \$264,543 \$1,488 \$0 \$1,714,065 \$185,943 \$1,528,122 2041 \$904,952 \$306,678 \$966	\$1,528,122 \$272,479 \$1,559 \$0 \$1,802,160 \$211,861 \$1,590,299 2042 \$1,027,017 \$315,878 \$1,074	\$1,590,299 \$280,654 \$1,643 \$0 \$1,872,595 \$177,268 \$1,695,327 2043 \$1,121,944 \$325,354 \$1,177	\$1,695,327 \$289,073 \$1,490 \$0 \$1,985,891 \$700,296 \$1,285,595 2044 \$1,232,435 \$335,115 \$1,351	\$1,285,595 \$297,745 \$1,095 \$0 \$1,584,435 \$679,484 \$904,952 2045 \$1,469,728 \$345,168 \$1,537 \$0 \$1,816,434
Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available Reserve Expenditures Ending Balance Year Starting Balance Reserve Income Interest Earnings Special Assessments	\$1,448,034 \$264,543 \$1,488 \$0 \$1,714,065 \$185,943 \$1,528,122 2041 \$904,952 \$306,678 \$966 \$0	\$1,528,122 \$272,479 \$1,559 \$0 \$1,802,160 \$211,861 \$1,590,299 2042 \$1,027,017 \$315,878 \$1,074 \$0	\$1,590,299 \$280,654 \$1,643 \$0 \$1,872,595 \$177,268 \$1,695,327 2043 \$1,121,944 \$325,354 \$1,177 \$0	\$1,695,327 \$289,073 \$1,490 \$0 \$1,985,891 \$700,296 \$1,285,595 2044 \$1,232,435 \$335,115 \$1,351 \$0	\$1,285,595 \$297,745 \$1,095 \$0 \$1,584,435 \$679,484 \$904,952 2045 \$1,469,728 \$345,168 \$1,537 \$0
Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available Reserve Expenditures Ending Balance Year Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available	\$1,448,034 \$264,543 \$1,488 \$0 \$1,714,065 \$185,943 \$1,528,122 2041 \$904,952 \$306,678 \$966 \$0 \$1,212,595	\$1,528,122 \$272,479 \$1,559 \$0 \$1,802,160 \$211,861 \$1,590,299 2042 \$1,027,017 \$315,878 \$1,074 \$0 \$1,343,970	\$1,590,299 \$280,654 \$1,643 \$0 \$1,872,595 \$177,268 \$1,695,327 2043 \$1,121,944 \$325,354 \$1,177 \$0 \$1,448,475	\$1,695,327 \$289,073 \$1,490 \$0 \$1,985,891 \$700,296 \$1,285,595 2044 \$1,232,435 \$335,115 \$1,351 \$0 \$1,568,901	\$1,285,595 \$297,745 \$1,095 \$0 \$1,584,435 \$679,484 \$904,952 2045 \$1,469,728 \$345,168 \$1,537 \$0 \$1,816,434
Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available Reserve Expenditures Ending Balance Year Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available Reserve Expenditures Ending Balance Year	\$1,448,034 \$264,543 \$1,488 \$0 \$1,714,065 \$185,943 \$1,528,122 2041 \$904,952 \$306,678 \$966 \$0 \$1,212,595 \$185,578 \$1,027,017	\$1,528,122 \$272,479 \$1,559 \$0 \$1,802,160 \$211,861 \$1,590,299 2042 \$1,027,017 \$315,878 \$1,074 \$0 \$1,343,970 \$222,026 \$1,121,944 2047	\$1,590,299 \$280,654 \$1,643 \$0 \$1,872,595 \$177,268 \$1,695,327 2043 \$1,121,944 \$325,354 \$1,177 \$0 \$1,448,475 \$216,041 \$1,232,435	\$1,695,327 \$289,073 \$1,490 \$0 \$1,985,891 \$700,296 \$1,285,595 2044 \$1,232,435 \$335,115 \$1,351 \$0 \$1,568,901 \$99,173 \$1,469,728	\$1,285,595 \$297,745 \$1,095 \$0 \$1,584,435 \$679,484 \$904,952 2045 \$1,469,728 \$345,168 \$1,537 \$0 \$1,816,434 \$211,614
Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available Reserve Expenditures Ending Balance Year Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available Reserve Expenditures Ending Balance Year Starting Balance Year Starting Balance	\$1,448,034 \$264,543 \$1,488 \$0 \$1,714,065 \$185,943 \$1,528,122 2041 \$904,952 \$306,678 \$966 \$0 \$1,212,595 \$185,578 \$1,027,017 2046 \$1,604,820	\$1,528,122 \$272,479 \$1,559 \$0 \$1,802,160 \$211,861 \$1,590,299 2042 \$1,027,017 \$315,878 \$1,074 \$0 \$1,343,970 \$222,026 \$1,121,944 2047 \$1,335,250	\$1,590,299 \$280,654 \$1,643 \$0 \$1,872,595 \$177,268 \$1,695,327 2043 \$1,121,944 \$325,354 \$1,177 \$0 \$1,448,475 \$216,041 \$1,232,435 2048 \$1,594,535	\$1,695,327 \$289,073 \$1,490 \$0 \$1,985,891 \$700,296 \$1,285,595 2044 \$1,232,435 \$335,115 \$1,351 \$0 \$1,568,901 \$99,173 \$1,469,728 2049 \$1,468,287	\$1,285,595 \$297,745 \$1,095 \$0 \$1,584,435 \$679,484 \$904,952 2045 \$1,469,728 \$345,168 \$1,537 \$0 \$1,816,434 \$211,614 \$1,604,820 2050 \$1,617,516
Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available Reserve Expenditures Ending Balance Year Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available Reserve Expenditures Ending Balance Year Starting Balance Year Starting Balance Reserve Income	\$1,448,034 \$264,543 \$1,488 \$0 \$1,714,065 \$185,943 \$1,528,122 2041 \$904,952 \$306,678 \$966 \$0 \$1,212,595 \$185,578 \$1,027,017 2046 \$1,604,820 \$355,523	\$1,528,122 \$272,479 \$1,559 \$0 \$1,802,160 \$211,861 \$1,590,299 2042 \$1,027,017 \$315,878 \$1,074 \$0 \$1,343,970 \$222,026 \$1,121,944 2047 \$1,335,250 \$366,189	\$1,590,299 \$280,654 \$1,643 \$0 \$1,872,595 \$177,268 \$1,695,327 2043 \$1,121,944 \$325,354 \$1,177 \$0 \$1,448,475 \$216,041 \$1,232,435 2048 \$1,594,535 \$377,175	\$1,695,327 \$289,073 \$1,490 \$0 \$1,985,891 \$700,296 \$1,285,595 2044 \$1,232,435 \$335,115 \$1,351 \$0 \$1,568,901 \$99,173 \$1,469,728 2049 \$1,468,287 \$388,490	\$1,285,595 \$297,745 \$1,095 \$0 \$1,584,435 \$679,484 \$904,952 2045 \$1,469,728 \$345,168 \$1,537 \$0 \$1,816,434 \$211,614 \$1,604,820 2050 \$1,617,516 \$400,145
Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available Reserve Expenditures Ending Balance Year Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available Reserve Expenditures Ending Balance Year Starting Balance Reserve Income Interest Earnings	\$1,448,034 \$264,543 \$1,488 \$0 \$1,714,065 \$185,943 \$1,528,122 2041 \$904,952 \$306,678 \$966 \$0 \$1,212,595 \$185,578 \$1,027,017 2046 \$1,604,820 \$355,523 \$1,470	\$1,528,122 \$272,479 \$1,559 \$0 \$1,802,160 \$211,861 \$1,590,299 2042 \$1,027,017 \$315,878 \$1,074 \$0 \$1,343,970 \$222,026 \$1,121,944 2047 \$1,335,250 \$366,189 \$1,465	\$1,590,299 \$280,654 \$1,643 \$0 \$1,872,595 \$177,268 \$1,695,327 2043 \$1,121,944 \$325,354 \$1,177 \$0 \$1,448,475 \$216,041 \$1,232,435 2048 \$1,594,535 \$377,175 \$1,531	\$1,695,327 \$289,073 \$1,490 \$0 \$1,985,891 \$700,296 \$1,285,595 2044 \$1,232,435 \$335,115 \$1,351 \$0 \$1,568,901 \$99,173 \$1,469,728 2049 \$1,468,287 \$388,490 \$1,543	\$1,285,595 \$297,745 \$1,095 \$0 \$1,584,435 \$679,484 \$904,952 2045 \$1,469,728 \$345,168 \$1,537 \$0 \$1,816,434 \$211,614 \$1,604,820 2050 \$1,617,516 \$400,145 \$1,717
Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available Reserve Expenditures Ending Balance Year Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available Reserve Expenditures Ending Balance Year Starting Balance Reserve Expenditures Ending Balance Year Starting Balance Reserve Income Interest Earnings Special Assessments	\$1,448,034 \$264,543 \$1,488 \$0 \$1,714,065 \$185,943 \$1,528,122 2041 \$904,952 \$306,678 \$966 \$0 \$1,212,595 \$185,578 \$1,027,017 2046 \$1,604,820 \$355,523 \$1,470 \$0	\$1,528,122 \$272,479 \$1,559 \$0 \$1,802,160 \$211,861 \$1,590,299 2042 \$1,027,017 \$315,878 \$1,074 \$0 \$1,343,970 \$222,026 \$1,121,944 2047 \$1,335,250 \$366,189 \$1,465 \$0	\$1,590,299 \$280,654 \$1,643 \$0 \$1,872,595 \$177,268 \$1,695,327 2043 \$1,121,944 \$325,354 \$1,177 \$0 \$1,448,475 \$216,041 \$1,232,435 2048 \$1,594,535 \$377,175 \$1,531 \$0	\$1,695,327 \$289,073 \$1,490 \$0 \$1,985,891 \$700,296 \$1,285,595 2044 \$1,232,435 \$335,115 \$1,351 \$0 \$1,568,901 \$99,173 \$1,469,728 2049 \$1,468,287 \$388,490 \$1,543 \$0	\$1,285,595 \$297,745 \$1,095 \$0 \$1,584,435 \$679,484 \$904,952 2045 \$1,469,728 \$345,168 \$1,537 \$0 \$1,816,434 \$211,614 \$1,604,820 2050 \$1,617,516 \$400,145 \$1,717 \$0
Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available Reserve Expenditures Ending Balance Year Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available Reserve Expenditures Ending Balance Year Starting Balance Reserve Expenditures Ending Balance Year Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available	\$1,448,034 \$264,543 \$1,488 \$0 \$1,714,065 \$185,943 \$1,528,122 2041 \$904,952 \$306,678 \$966 \$0 \$1,212,595 \$185,578 \$1,027,017 2046 \$1,604,820 \$355,523 \$1,470 \$0 \$1,961,813	\$1,528,122 \$272,479 \$1,559 \$0 \$1,802,160 \$211,861 \$1,590,299 2042 \$1,027,017 \$315,878 \$1,074 \$0 \$1,343,970 \$222,026 \$1,121,944 2047 \$1,335,250 \$366,189 \$1,465 \$0 \$1,702,904	\$1,590,299 \$280,654 \$1,643 \$0 \$1,872,595 \$177,268 \$1,695,327 2043 \$1,121,944 \$325,354 \$1,177 \$0 \$1,448,475 \$216,041 \$1,232,435 2048 \$1,594,535 \$377,175 \$1,531 \$0 \$1,973,242	\$1,695,327 \$289,073 \$1,490 \$0 \$1,985,891 \$700,296 \$1,285,595 2044 \$1,232,435 \$335,115 \$1,351 \$0 \$1,568,901 \$99,173 \$1,469,728 2049 \$1,468,287 \$388,490 \$1,543 \$0 \$1,858,320	\$1,285,595 \$297,745 \$1,095 \$0 \$1,584,435 \$679,484 \$904,952 2045 \$1,469,728 \$345,168 \$1,537 \$0 \$1,816,434 \$211,614 \$1,604,820 2050 \$1,617,516 \$400,145 \$1,717 \$0 \$2,019,377
Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available Reserve Expenditures Ending Balance Year Starting Balance Reserve Income Interest Earnings Special Assessments Funds Available Reserve Expenditures Ending Balance Year Starting Balance Reserve Expenditures Ending Balance Year Starting Balance Reserve Income Interest Earnings Special Assessments	\$1,448,034 \$264,543 \$1,488 \$0 \$1,714,065 \$185,943 \$1,528,122 2041 \$904,952 \$306,678 \$966 \$0 \$1,212,595 \$185,578 \$1,027,017 2046 \$1,604,820 \$355,523 \$1,470 \$0	\$1,528,122 \$272,479 \$1,559 \$0 \$1,802,160 \$211,861 \$1,590,299 2042 \$1,027,017 \$315,878 \$1,074 \$0 \$1,343,970 \$222,026 \$1,121,944 2047 \$1,335,250 \$366,189 \$1,465 \$0	\$1,590,299 \$280,654 \$1,643 \$0 \$1,872,595 \$177,268 \$1,695,327 2043 \$1,121,944 \$325,354 \$1,177 \$0 \$1,448,475 \$216,041 \$1,232,435 2048 \$1,594,535 \$377,175 \$1,531 \$0	\$1,695,327 \$289,073 \$1,490 \$0 \$1,985,891 \$700,296 \$1,285,595 2044 \$1,232,435 \$335,115 \$1,351 \$0 \$1,568,901 \$99,173 \$1,469,728 2049 \$1,468,287 \$388,490 \$1,543 \$0	\$1,285,595 \$297,745 \$1,095 \$0 \$1,584,435 \$679,484 \$904,952 2045 \$1,469,728 \$345,168 \$1,537 \$0 \$1,816,434 \$211,614 \$1,604,820 2050 \$1,617,516 \$400,145 \$1,717 \$0



Yearly Reserve Expenditures - Graph





Projected Reserve Expenditures by Year

Year	ID#	Component Name	Projected	Total Per
ı caı	ייי שו	Component Name	Cost	Annum
2021	213	Sign Posts - Repaint	\$1,050	
	390	Stone Veneer - Repairs	\$21,000	
	402	Asphalt - 2018 - Slurry Seal	\$2,600	
	402	Asphalt - 2021 - Slurry Seal	\$36,000	
	403	Asphalt - Crack Seal	\$13,000	
	406	Curbing - Partial Replace	\$20,000	
	490	Asphalt - Ruby Hollow - Replace	\$40,000	
	808	Sign Posts - Install/Replace	\$2,100	
	1007	Guard Rails - Repair	\$2,100	
	1890	Retaining Walls - Repair	\$5,500	
	2090	Water Lines - Repair	\$5,500	
	2302	Metal Bridge - Maintenance	\$11,000	\$159,850
2022	213	Sign Posts - Repaint	\$1,082	
	219	Wood Surfaces - Stain	\$37,080	
	390	Stone Veneer - Repairs	\$21,630	
	401	Asphalt - Hawkeye Place - Major Rehab	\$21,630	
	402	Asphalt - Slurry Seal	\$47,380	
	403	Asphalt - Crack Seal	\$13,390	
	808	Sign Posts - Install/Replace	\$2,163	
	1007	Guard Rails - Repair	\$2,163	
	2090	Water Lines - Repair	\$5,665	\$152,183
2023	213	Sign Posts - Repaint	\$1,114	
	390	Stone Veneer - Repairs	\$22,279	
	401	Asphalt - Red Cloud Trail - Major Rehab	\$75,324	
	403	Asphalt - Crack Seal	\$13,792	
	808	Sign Posts - Install/Replace	\$2,228	
	990	Fire Hydrants - Repair/Replace	\$5,835	
	1007	Guard Rails - Repair	\$2,228	
	2090	Water Lines - Repair	\$5,835	\$128,634
2024	213	Sign Posts - Repaint	\$1,147	
	390	Stone Veneer - Repairs	\$22,947	
	401	Asphalt - Twisted Branch - Major Rehab	\$322,409	
	402	Asphalt - 2018 - Slurry Seal	\$2,841	
	402	Asphalt - 2021 - Slurry Seal	\$39,338	
	403	Asphalt - Crack Seal	\$14,205	
	808	Sign Posts - Install/Replace	\$2,295	
	903	Camera System - Replace	\$1,858	
	1007	Guard Rails - Repair	\$2,295	
	2090	Water Lines - Repair	\$6,010	\$415,346
2025	213	Sign Posts - Repaint	\$1,182	•
-	217	Transit Center - Repair/Repaint	\$3,939	
	390	Stone Veneer - Repairs	\$23,636	
	401	Asphalt - Banner Court - Major Rehab	\$18,008	
	4 01	Asphall - Dannel Court - Major Renab	D10,000	

Year	Comp ID	Component Name	Projected Cost	Total Per Annum
	403	Asphalt - Crack Seal	\$14,632	
	801	Monument Signs - Refurbish	\$10,974	
	808	Sign Posts - Install/Replace	\$2,364	
	1007	Guard Rails - Repair	\$2,364	
	2090	Water Lines - Repair	\$6,190	
	2302	Metal Bridge - Maintenance	\$12,381	\$147,442
2026	213	Sign Posts - Repaint	\$1,217	
	219	Wood Surfaces - Stain	\$41,734	
	390	Stone Veneer - Repairs	\$24,345	
	403	Asphalt - Crack Seal	\$15,071	
	808	Sign Posts - Install/Replace	\$2,434	
	990	Fire Hydrants - Repair/Replace	\$6,376	
	1007	Guard Rails - Repair	\$2,434	
	1604	Bridge & Pole Lights - Replace	\$199,975	
	2090	Water Lines - Repair	\$6,376	\$299,962
2027	213	Sign Posts - Repaint	\$1,254	
	390	Stone Veneer - Repairs	\$25,075	
	401	Asphalt - Northside Court - Major Rehab	\$22,090	
	402	Asphalt - 2018 - Slurry Seal	\$3,105	
	402	Asphalt - 2021 - Slurry Seal	\$42,986	
	403	Asphalt - Crack Seal	\$15,523	
	808	Sign Posts - Install/Replace	\$2,508	
	1007	Guard Rails - Repair	\$2,508	
_	2090	Water Lines - Repair	\$6,567	\$121,614
2028	213	Sign Posts - Repaint	\$1,291	
	390	Stone Veneer - Repairs	\$25,827	
	402	Asphalt - Slurry Seal	\$56,574	
	403	Asphalt - Crack Seal	\$15,988	
	808	Sign Posts - Install/Replace	\$2,583	
	1007	Guard Rails - Repair	\$2,583	
_	2090	Water Lines - Repair	\$6,764	\$111,611
2029	107	Transit Center Roof - Replace	\$5,067	
	213	Sign Posts - Repaint	\$1,330	
	390	Stone Veneer - Repairs	\$26,602	
	403	Asphalt - Crack Seal	\$16,468	
	808	Sign Posts - Install/Replace	\$2,660	
	990	Fire Hydrants - Repair/Replace	\$6,967	
	1007	Guard Rails - Repair	\$2,660	
	2090	Water Lines - Repair	\$6,967	
	2302	Metal Bridge - Maintenance	\$13,934	\$82,657
2030	213	Sign Posts - Repaint	\$1,370	
	219	Wood Surfaces - Stain	\$46,972	
	390	Stone Veneer - Repairs	\$27,400	
	402	Asphalt - 2018 - Slurry Seal	\$3,392	
	402	Asphalt - 2021 - Slurry Seal	\$46,972	
	403	Asphalt - Crack Seal	\$16,962	
	808	Sign Posts - Install/Replace	\$2,740	

1007 Guard Rails - Repair \$2,740 \$155,725 \$2031 213 Sign Posts - Repair \$1,411 \$1,41	Year	Comp ID	Component Name	Projected Cost	Total Per Annum
2031 213 Sign Posts - Repaint \$1,411 217 Transit Center - Repair/Repaint \$4,704 390 Stone Veneer - Repairs \$28,222 402 Asphalt - Slurry Seal \$61,820 403 Asphalt - Crack Seal \$17,471 406 Curbing - Partial Replace \$26,678 808 Sign Posts - Install/Replace \$2,822 1007 Guard Rails - Repair \$2,822 1890 Retaining Walls - Repair \$7,392 2030 Water Lines - Repair \$7,392 2031 Stone Veneer - Repairs \$29,069 401 Asphalt - Red Cloud Trail 2016 - Major Rehab \$12,120 401 Asphalt - Sliver Strike Trail - Major Rehab \$17,995 403 Asphalt - Slever Strike Trail - Major Rehab \$17,995 404 Asphalt - Crack Seal \$17,995 405 Sign Posts - Install/Replace \$2,353 900 Fire Hydrants - Repair \$2,907 2090 Water Lines - Repair \$2,907 2091 Water Lines - Re		1007	Guard Rails - Repair	\$2,740	
217 Transit Center - Repair/Repaint \$4,704 390 Stone Veneer - Repairs \$28,222 402 Asphalt - Crack Seal \$17,471 406 Curbing - Partial Replace \$26,878 808 Sign Posts - Install/Replace \$2,822 1007 Guard Rails - Repair \$2,822 1007 Guard Rails - Repair \$2,822 1200 Water Lines - Repair \$2,822 1200 Water Lines - Repair \$7,392 \$160,934		2090	Water Lines - Repair	\$7,176	\$155,725
390	2031	213	Sign Posts - Repaint	\$1,411	
402		217	Transit Center - Repair/Repaint	\$4,704	
403		390	Stone Veneer - Repairs	\$28,222	
March Sugn Posts - Install/Replace \$26,878		402	Asphalt - Slurry Seal	\$61,820	
808 Sign Posts - Install/Replace \$2,822 1007 Guard Ralls - Repair \$2,822 2090 Water Lines - Repair \$7,392 \$160,934 2032 213 Sign Posts - Repaint \$1,453 390 Stone Veneer - Repairs \$29,069 401 Asphalt - Red Cloud Trail 2016 - Major Rehab \$121,120 401 Asphalt - Silver Strike Trail - Major Rehab \$75,821 403 Asphalt - Crack Seal \$17,995 808 Sign Posts - Install/Replace \$2,907 903 Camera System - Replace \$2,353 990 Fire Hydrants - Repair (Replace \$7,613 1007 Guard Rails - Repair \$2,907 2090 Water Lines - Repair \$2,907 2090 Water Lines - Repair \$2,907 402 Asphalt - 2018 - Slurry Seal \$3,707 402 Asphalt - State Seal \$11,497 402 Asphalt - Crack Seal \$15,535 808 Sign Posts - Install/Replace \$2,994 403 Asphalt - C		403	Asphalt - Crack Seal	\$17,471	
1007 Guard Rails - Repair \$2,822 Retaining Walls - Repair \$7,392 \$160,934 2032 213 Sign Posts - Repaint \$1,453 390 Stone Veneer - Repairs \$29,069 401 Asphalt - Red Cloud Trail 2016 - Major Rehab \$121,120 401 Asphalt - Silver Strike Trail - Major Rehab \$17,995 403 Asphalt - Crack Seal \$17,995 808 Sign Posts - Install/Replace \$2,907 903 Camera System - Replace \$2,353 990 Fire Hydrants - Repair/Replace \$7,613 1007 Guard Rails - Repair \$2,907 2090 Water Lines - Repairs \$2,907 2091 Water Lines - Repair \$1,497 300 Stone Veneer - Repairs \$2,907 402 Asphalt - 2021 - Slurry Seal \$1,497 403 Asphalt - 2021 - Slurry Seal \$1,497 404 Asphalt - 2021 - Slurry Seal \$1,497 405 Asphalt - 2021 - Slurry Seal \$1,535 406 Asphalt - 2021 - Slurry Seal \$1,535 407 Guard Rails - Repair \$2,994 408 Asphalt - Repair \$2,994 4090 Water Lines - Repair \$7,842 2090 Water Lines - Repair \$7,842 2090 Water Lines - Repair \$7,842 2091 Water Lines - Repair \$1,542 2092 Metal Bridge - Maintenance \$15,683 \$134,521 2034 213 Sign Posts - Install/Replace \$3,084 2030 Metal Bridge - Repair \$3,084 2030 Water Lines - Repair \$3,084 2030 Water L		406	Curbing - Partial Replace	\$26,878	
1890 Retaining Walls - Repair \$7,392 \$160,934			· ·	\$2,822	
2090 Water Lines - Repair \$7,392 \$160,934 2032 213 Sign Posts - Repaint \$1,453 390 Stone Veneer - Repairs \$29,069 401 Asphalt - Red Cloud Trail 2016 - Major Rehab \$121,120 401 Asphalt - Silver Strike Trail - Major Rehab \$75,821 403 Asphalt - Crack Seal \$17,995 808 Sign Posts - Install/Replace \$2,907 903 Camera System - Replace \$2,353 990 Fire Hydrants - Repair/Replace \$7,613 1007 Guard Rails - Repair \$2,907 2090 Water Lines - Repair \$7,613 390 Stone Veneer - Repairs \$29,907 402 Asphalt - 2018 - Slurry Seal \$3,707 402 Asphalt - 2021 - Slurry Seal \$1,535 403 Asphalt - Crack Seal \$18,535 404 Asphalt - Slurry Seal \$1,542 409 Water Lines - Repair \$2,994 2090 Water Lines - Repair \$2,994 2090 Metal Bridge - Ma		1007	Guard Rails - Repair	\$2,822	
2032		1890	Retaining Walls - Repair	\$7,392	
390 Stone Veneer - Repairs \$29,069 401 Asphalt - Red Cloud Trail 2016 - Major Rehab \$121,120 401 Asphalt - Strike Trail - Major Rehab \$75,821 403 Asphalt - Crack Seal \$17,995 808 Sign Posts - Install/Replace \$2,907 903 Camera System - Replace \$2,353 990 Fire Hydrants - Repair/Replace \$7,613 1007 Guard Rails - Repair \$2,907 2090 Water Lines - Repair \$2,907 2090 Water Lines - Repair \$1,497 390 Stone Veneer - Repairs \$29,941 402 Asphalt - 2018 - Slurry Seal \$3,707 402 Asphalt - 2021 - Slurry Seal \$3,707 402 Asphalt - 2021 - Slurry Seal \$51,327 403 Asphalt - Crack Seal \$18,535 808 Sign Posts - Install/Replace \$2,994 2090 Water Lines - Repair \$7,842 2090 Water Lines - Repair \$7,842 2090 Water Lines - Repair \$1,542 2014 213 Sign Posts - Repaint \$1,542 2024 213 Sign Posts - Repaint \$1,542 219 Wood Surfaces - Stain \$52,867 390 Stone Veneer - Repairs \$30,839 402 Asphalt - Slurry Seal \$67,553 403 Asphalt - Crack Seal \$19,091 808 Sign Posts - Install/Replace \$3,084 1007 Guard Rails - Repair \$3,084 2090 Water Lines - Repair \$3,084 20		2090	Water Lines - Repair	\$7,392	\$160,934
401	2032	213	Sign Posts - Repaint	\$1,453	
401		390	Stone Veneer - Repairs	\$29,069	
403 Asphalt - Crack Seal \$17,995 808 Sign Posts - Install/Replace \$2,907 900 Camera System - Replace \$2,353 990 Fire Hydrants - Repair/Replace \$7,613 1007 Guard Rails - Repair \$2,907 2090 Water Lines - Repair \$7,613 2033 213 Sign Posts - Repaint \$1,497 390 Stone Veneer - Repairs \$29,941 402 Asphalt - 2018 - Slurry Seal \$3,707 402 Asphalt - 2021 - Slurry Seal \$51,327 403 Asphalt - Crack Seal \$18,535 808 Sign Posts - Install/Replace \$2,994 1007 Guard Rails - Repair \$2,994 2030 Water Lines - Repair \$7,842 2302 Metal Bridge - Maintenance \$15,683 \$134,521 2034 213 Sign Posts - Repairt \$52,867 390 Stone Veneer - Repairs \$30,839 402 Asphalt - Crack Seal \$19,091 808 Sign Posts - Install/Replace \$3,084 1007 Guard Rails - Repair		401	Asphalt - Red Cloud Trail 2016 - Major Rehab	\$121,120	
808 Sign Posts - Install/Replace \$2,907 903 Camera System - Replace \$2,353 990 Fire Hydrants - Repair/Replace \$7,613 1007 Guard Rails - Repair \$2,907 2090 Water Lines - Repair \$2,907 2090 Water Lines - Repair \$2,907 2090 Water Lines - Repair \$2,907 390 Stone Veneer - Repairs \$29,941 402 Asphalt - 2018 - Slurry Seal \$3,707 402 Asphalt - 2018 - Slurry Seal \$51,327 403 Asphalt - Crack Seal \$18,535 808 Sign Posts - Install/Replace \$2,994 1007 Guard Rails - Repair \$2,994 2000 Water Lines - Repairr \$7,842 2302 Metal Bridge - Maintenance \$15,683 \$134,521 2034 213 Sign Posts - Repairs \$3,083 402 Asphalt - Slurry Seal \$67,553 403 Asphalt - Slurry Seal \$67,553 403 Asphalt - Slurry Seal \$67,553 <td></td> <td>401</td> <td>Asphalt - Silver Strike Trail - Major Rehab</td> <td>\$75,821</td> <td></td>		401	Asphalt - Silver Strike Trail - Major Rehab	\$75,821	
903 Camera System - Replace \$2,353 990 Fire Hydrants - Repair/Replace \$7,613 1007 Guard Rails - Repair \$2,907 2090 Water Lines - Repair \$1,497 390 Stone Veneer - Repairs \$29,941 402 Asphalt - 2018 - Slurry Seal \$3,707 402 Asphalt - 2021 - Slurry Seal \$3,707 403 Asphalt - Crack Seal \$18,535 808 Sign Posts - Install/Replace \$2,994 2090 Water Lines - Repair \$2,994 2090 Water Lines - Repair \$7,842 2302 Metal Bridge - Maintenance \$15,683 \$134,521 2034 213 Sign Posts - Repair \$52,867 390 Stone Veneer - Repair \$3,084 402 Asphalt - Crack Seal \$1,542 219 Wood Surfaces - Stain \$52,867 390 Stone Veneer - Repairs \$30,839 402 Asphalt - Slurry Seal \$67,553 403 Asphalt - Crack Seal \$19,091 808 Sign Posts - Install/Replace \$3,084 1007 Guard Rails - Repair \$3,084 2090 Water Lines - Repair \$3,084 2090 Water Lines - Repair \$3,084 402 Asphalt - Crack Seal \$19,091 808 Sign Posts - Install/Replace \$3,084 403 Asphalt - Crack Seal \$19,091 808 Sign Posts - Repair \$8,077 \$186,137 2035 213 Sign Posts - Repair \$3,084 403 Asphalt - Crack Seal \$19,664 808 Sign Posts - Repair \$3,1764 403 Asphalt - Crack Seal \$19,664 808 Sign Posts - Repair \$3,1764 403 Asphalt - Crack Seal \$19,664 808 Sign Posts - Repair/Replace \$3,176 990 Fire Hydrants - Repair/Replace \$3,176 990 Fire Hydrants - Repair/Replace \$3,176 990 Fire Hydrants - Repair/Replace \$3,176 2090 Water Lines - Repair \$3,176 2090 Water Lines - Repair \$3,176 2090 Water Lines - Repair/Replace \$3,176 2090 Water Lines - Repair/Replace \$3,176 2090 Water Lines - Repair/Replace \$3,176 2090 Water Lines - Repair		403	Asphalt - Crack Seal	\$17,995	
990 Fire Hydrants - Repair/Replace \$7,613 1007 Guard Rails - Repair \$2,907 2090 Water Lines - Repair \$7,613 \$268,853 2033 213 Sign Posts - Repaint \$1,497 390 Stone Veneer - Repairs \$29,941 402 Asphalt - 2018 - Slurry Seal \$3,707 402 Asphalt - 2021 - Slurry Seal \$51,327 403 Asphalt - Crack Seal \$18,535 808 Sign Posts - Install/Replace \$2,994 1007 Guard Rails - Repair \$2,994 2090 Water Lines - Repair \$7,842 2090 Water Lines - Repair \$7,842 2302 Metal Bridge - Maintenance \$15,683 \$134,521 2034 213 Sign Posts - Repaint \$1,542 219 Wood Surfaces - Stain \$52,867 390 Stone Veneer - Repairs \$30,839 402 Asphalt - Slurry Seal \$67,553 403 Asphalt - Crack Seal \$19,091 808 Sign Posts		808	Sign Posts - Install/Replace	\$2,907	
1007 Guard Rails - Repair \$2,907 2090 Water Lines - Repair \$7,613 \$268,853 \$2033 213 Sign Posts - Repairt \$1,497 390 Stone Veneer - Repairs \$2,9941 402 Asphalt - 2018 - Slurry Seal \$3,707 402 Asphalt - 2021 - Slurry Seal \$51,327 403 Asphalt - Crack Seal \$18,535 808 Sign Posts - Install/Replace \$2,994 2090 Water Lines - Repair \$2,994 2090 Water Lines - Repair \$15,683 \$134,521 \$2034 213 Sign Posts - Repair \$1,542 219 Wood Surfaces - Stain \$52,867 390 Stone Veneer - Repairs \$30,839 402 Asphalt - Slurry Seal \$67,553 403 Asphalt - Crack Seal \$19,091 808 Sign Posts - Install/Replace \$3,084 1007 Guard Rails - Repair \$3,084 2090 Water Lines - Repair \$3,084 2090 Stone Veneer - Repairs \$3,084 2090 20,000 20,		903	Camera System - Replace	\$2,353	
2090 Water Lines - Repair \$7,613 \$268,853 2033 213 Sign Posts - Repaint \$1,497 390 Stone Veneer - Repairs \$29,941 402 Asphalt - 2018 - Slurry Seal \$3,707 402 Asphalt - 2018 - Slurry Seal \$51,327 403 Asphalt - Crack Seal \$18,535 808 Sign Posts - Install/Replace \$2,994 1007 Guard Rails - Repair \$2,994 2090 Water Lines - Repair \$7,842 2302 Metal Bridge - Maintenance \$15,683 \$134,521 2034 213 Sign Posts - Repairt \$1,542 219 Wood Surfaces - Stain \$52,867 390 Stone Veneer - Repairs \$30,839 402 Asphalt - Slurry Seal \$67,553 403 Asphalt - Crack Seal \$19,091 808 Sign Posts - Install/Replace \$3,084 1007 Guard Rails - Repair \$1,588 390 Stone Veneer - Repairs \$31,764 403 Asphalt -		990	Fire Hydrants - Repair/Replace	\$7,613	
2033 213 Sign Posts - Repaint \$1,497 390 Stone Veneer - Repairs \$29,941 402 Asphalt - 2018 - Slurry Seal \$3,707 402 Asphalt - Corack Seal \$51,327 403 Asphalt - Crack Seal \$18,535 808 Sign Posts - Install/Replace \$2,994 1007 Guard Rails - Repair \$2,994 2090 Water Lines - Repair \$7,842 2302 Metal Bridge - Maintenance \$15,683 \$134,521 2034 213 Sign Posts - Repaint \$1,542 219 Wood Surfaces - Stain \$52,867 390 Stone Veneer - Repairs \$30,839 402 Asphalt - Slurry Seal \$67,553 403 Asphalt - Crack Seal \$19,091 808 Sign Posts - Install/Replace \$3,084 1007 Guard Rails - Repair \$3,084 2090 Water Lines - Repair \$31,764 403 Asphalt - Crack Seal \$19,664 390 Stone Veneer - Repairs \$31,766 403 Asphalt - Crack Seal \$19,664		1007	Guard Rails - Repair	\$2,907	
390 Stone Veneer - Repairs \$29,941 402 Asphalt - 2018 - Slurry Seal \$3,707 402 Asphalt - 2021 - Slurry Seal \$51,327 403 Asphalt - Crack Seal \$18,535 808 Sign Posts - Install/Replace \$2,994 1007 Guard Rails - Repair \$2,994 2090 Water Lines - Repair \$2,994 2030 Metal Bridge - Maintenance \$15,683 \$134,521 2034 213 Sign Posts - Repaint \$1,542 219 Wood Surfaces - Stain \$52,867 390 Stone Veneer - Repairs \$30,839 402 Asphalt - Slurry Seal \$67,553 403 Asphalt - Crack Seal \$19,091 808 Sign Posts - Install/Replace \$3,084 1007 Guard Rails - Repair \$3,084 2090 Water Lines - Repairs \$31,764 403 Asphalt - Crack Seal \$1,588 390 Stone Veneer - Repairs \$31,764 403 Asphalt - Crack Seal \$1,586 405 Asphalt - Crack Seal \$1,586		2090	Water Lines - Repair	\$7,613	\$268,853
402 Asphalt - 2018 - Slurry Seal \$3,707 402 Asphalt - 2021 - Slurry Seal \$51,327 403 Asphalt - Crack Seal \$18,535 808 Sign Posts - Install/Replace \$2,994 1007 Guard Rails - Repair \$2,994 2090 Water Lines - Repair \$7,842 2302 Metal Bridge - Maintenance \$15,683 \$134,521 2034 213 Sign Posts - Repaint \$1,542 219 Wood Surfaces - Stain \$52,867 390 Stone Veneer - Repairs \$30,839 402 Asphalt - Slurry Seal \$67,553 403 Asphalt - Crack Seal \$19,091 808 Sign Posts - Install/Replace \$3,084 1007 Guard Rails - Repair \$3,084 2090 Water Lines - Repairs \$1,588 390 Stone Veneer - Repairs \$31,764 403 Asphalt - Crack Seal \$19,664 403 Asphalt - Crack Seal \$19,664 403 Asphalt - Crack Seal \$19,664 408 Sign Posts - Install/Replace \$3,176	2033	213	Sign Posts - Repaint	\$1,497	
402 Asphalt - 2021 - Slurry Seal \$51,327 403 Asphalt - Crack Seal \$18,535 808 Sign Posts - Install/Replace \$2,994 1007 Guard Rails - Repair \$2,994 2090 Water Lines - Repair \$7,842 2302 Metal Bridge - Maintenance \$15,683 \$134,521 2034 213 Sign Posts - Repaint \$1,542 219 Wood Surfaces - Stain \$52,867 390 Stone Veneer - Repairs \$30,839 402 Asphalt - Slurry Seal \$67,553 403 Asphalt - Crack Seal \$19,091 808 Sign Posts - Install/Replace \$3,084 1007 Guard Rails - Repair \$3,084 2035 213 Sign Posts - Repaint \$1,588 390 Stone Veneer - Repairs \$31,764 403 Asphalt - Crack Seal \$19,664 808 Sign Posts - Install/Replace \$3,176 990 Fire Hydrants - Repair/Replace \$8,319 1007 Guard Rails - Repair \$3,176 2090 Water Lines - Repair \$3,		390	Stone Veneer - Repairs	\$29,941	
403 Asphalt - Crack Seal \$18,535 808 Sign Posts - Install/Replace \$2,994 1007 Guard Rails - Repair \$2,994 2090 Water Lines - Repair \$7,842 2302 Metal Bridge - Maintenance \$15,683 \$134,521 2034 213 Sign Posts - Repaint \$1,542 219 Wood Surfaces - Stain \$52,867 390 Stone Veneer - Repairs \$30,839 402 Asphalt - Slurry Seal \$67,553 403 Asphalt - Crack Seal \$19,091 808 Sign Posts - Install/Replace \$3,084 1007 Guard Rails - Repair \$8,077 \$186,137 2035 213 Sign Posts - Repaint \$1,588 390 Stone Veneer - Repairs \$31,764 403 Asphalt - Crack Seal \$19,664 808 Sign Posts - Install/Replace \$3,176 990 Fire Hydrants - Repair/Replace \$8,319 1007 Guard Rails - Repair \$3,176 2090 Water Lines - Repair \$3,176 2090 Water Lines - Repair <td></td> <td>402</td> <td>Asphalt - 2018 - Slurry Seal</td> <td>\$3,707</td> <td></td>		402	Asphalt - 2018 - Slurry Seal	\$3,707	
808 Sign Posts - Install/Replace \$2,994 1007 Guard Rails - Repair \$2,994 2090 Water Lines - Repair \$7,842 2302 Metal Bridge - Maintenance \$15,683 \$134,521 2034 213 Sign Posts - Repaint \$1,542 219 Wood Surfaces - Stain \$52,867 390 Stone Veneer - Repairs \$30,839 402 Asphalt - Slurry Seal \$67,553 403 Asphalt - Crack Seal \$19,091 808 Sign Posts - Install/Replace \$3,084 1007 Guard Rails - Repair \$3,084 2090 Water Lines - Repair \$8,077 \$186,137 2035 213 Sign Posts - Repair \$1,588 390 Stone Veneer - Repairs \$31,764 403 Asphalt - Crack Seal \$19,664 808 Sign Posts - Install/Replace \$3,176 990 Fire Hydrants - Repair/Replace \$8,319 1007 Guard Rails - Repair \$3,176 2090 Water Lines - Repair \$8,319 1007 Guard Rails - Repair <td></td> <td>402</td> <td>Asphalt - 2021 - Slurry Seal</td> <td>\$51,327</td> <td></td>		402	Asphalt - 2021 - Slurry Seal	\$51,327	
1007 Guard Rails - Repair \$2,994 2090 Water Lines - Repair \$7,842 2302 Metal Bridge - Maintenance \$15,683 \$134,521 2034 213 Sign Posts - Repaint \$1,542 219 Wood Surfaces - Stain \$52,867 390 Stone Veneer - Repairs \$30,839 402 Asphalt - Slurry Seal \$67,553 403 Asphalt - Crack Seal \$19,091 808 Sign Posts - Install/Replace \$3,084 1007 Guard Rails - Repair \$3,084 2090 Water Lines - Repair \$8,077 \$186,137 2035 213 Sign Posts - Repairt \$1,588 390 Stone Veneer - Repairs \$31,764 403 Asphalt - Crack Seal \$19,664 808 Sign Posts - Install/Replace \$3,176 990 Fire Hydrants - Repair/Replace \$8,319 1007 Guard Rails - Repair \$3,176 2090 Water Lines - Repair \$3,176 2090 Water Lines - Repair \$3,176		403	Asphalt - Crack Seal	\$18,535	
2090 Water Lines - Repair \$7,842 2302 Metal Bridge - Maintenance \$15,683 \$134,521 2034 213 Sign Posts - Repaint \$1,542 219 Wood Surfaces - Stain \$52,867 390 Stone Veneer - Repairs \$30,839 402 Asphalt - Slurry Seal \$67,553 403 Asphalt - Crack Seal \$19,091 808 Sign Posts - Install/Replace \$3,084 2090 Water Lines - Repair \$3,084 2090 Water Lines - Repair \$8,077 \$186,137 2035 213 Sign Posts - Repaint \$1,588 390 Stone Veneer - Repairs \$31,764 403 Asphalt - Crack Seal \$19,664 808 Sign Posts - Install/Replace \$3,176 990 Fire Hydrants - Repair/Replace \$8,319 1007 Guard Rails - Repair \$3,176 2090 Water Lines - Repair \$3,176 2090 Water Lines - Repair \$3,176		808	Sign Posts - Install/Replace	\$2,994	
2302 Metal Bridge - Maintenance \$15,683 \$134,521 2034 213 Sign Posts - Repaint \$1,542 219 Wood Surfaces - Stain \$52,867 390 Stone Veneer - Repairs \$30,839 402 Asphalt - Slurry Seal \$67,553 403 Asphalt - Crack Seal \$19,091 808 Sign Posts - Install/Replace \$3,084 1007 Guard Rails - Repair \$3,084 2090 Water Lines - Repair \$8,077 \$186,137 2035 213 Sign Posts - Repaint \$1,588 390 Stone Veneer - Repairs \$31,764 403 Asphalt - Crack Seal \$19,664 808 Sign Posts - Install/Replace \$3,176 990 Fire Hydrants - Repair/Replace \$8,319 1007 Guard Rails - Repair \$3,176 2090 Water Lines - Repair \$3,176 2090 Water Lines - Repair \$3,176		1007	Guard Rails - Repair	\$2,994	
2034 213 Sign Posts - Repaint \$1,542 219 Wood Surfaces - Stain \$52,867 390 Stone Veneer - Repairs \$30,839 402 Asphalt - Slurry Seal \$67,553 403 Asphalt - Crack Seal \$19,091 808 Sign Posts - Install/Replace \$3,084 1007 Guard Rails - Repair \$3,084 2090 Water Lines - Repair \$8,077 \$186,137 2035 213 Sign Posts - Repaint \$1,588 390 Stone Veneer - Repairs \$31,764 403 Asphalt - Crack Seal \$19,664 808 Sign Posts - Install/Replace \$3,176 990 Fire Hydrants - Repair/Replace \$8,319 1007 Guard Rails - Repair \$3,176 2090 Water Lines - Repair \$3,176		2090	Water Lines - Repair	\$7,842	
219 Wood Surfaces - Stain \$52,867 390 Stone Veneer - Repairs \$30,839 402 Asphalt - Slurry Seal \$67,553 403 Asphalt - Crack Seal \$19,091 808 Sign Posts - Install/Replace \$3,084 1007 Guard Rails - Repair \$3,084 2090 Water Lines - Repair \$8,077 \$186,137 2035 213 Sign Posts - Repaint \$1,588 390 Stone Veneer - Repairs \$31,764 403 Asphalt - Crack Seal \$19,664 808 Sign Posts - Install/Replace \$3,176 990 Fire Hydrants - Repair/Replace \$8,319 1007 Guard Rails - Repair \$3,176 2090 Water Lines - Repair \$3,176 2090 Water Lines - Repair \$3,176		2302	Metal Bridge - Maintenance	\$15,683	\$134,521
390 Stone Veneer - Repairs \$30,839 402 Asphalt - Slurry Seal \$67,553 403 Asphalt - Crack Seal \$19,091 808 Sign Posts - Install/Replace \$3,084 1007 Guard Rails - Repair \$3,084 2090 Water Lines - Repair \$8,077 \$186,137 2035 213 Sign Posts - Repaint \$1,588 390 Stone Veneer - Repairs \$31,764 403 Asphalt - Crack Seal \$19,664 808 Sign Posts - Install/Replace \$3,176 990 Fire Hydrants - Repair/Replace \$8,319 1007 Guard Rails - Repair \$3,176 2090 Water Lines - Repair \$8,319	2034	213	Sign Posts - Repaint	\$1,542	
402 Asphalt - Slurry Seal \$67,553 403 Asphalt - Crack Seal \$19,091 808 Sign Posts - Install/Replace \$3,084 1007 Guard Rails - Repair \$3,084 2090 Water Lines - Repair \$8,077 \$186,137 2035 213 Sign Posts - Repaint \$1,588 390 Stone Veneer - Repairs \$31,764 403 Asphalt - Crack Seal \$19,664 808 Sign Posts - Install/Replace \$3,176 990 Fire Hydrants - Repair/Replace \$8,319 1007 Guard Rails - Repair \$3,176 2090 Water Lines - Repair \$8,319		219	Wood Surfaces - Stain	\$52,867	
403 Asphalt - Crack Seal \$19,091 808 Sign Posts - Install/Replace \$3,084 1007 Guard Rails - Repair \$3,084 2090 Water Lines - Repair \$8,077 2035 213 Sign Posts - Repaint \$1,588 390 Stone Veneer - Repairs \$31,764 403 Asphalt - Crack Seal \$19,664 808 Sign Posts - Install/Replace \$3,176 990 Fire Hydrants - Repair/Replace \$8,319 1007 Guard Rails - Repair \$3,176 2090 Water Lines - Repair \$8,319		390	Stone Veneer - Repairs	\$30,839	
808 Sign Posts - Install/Replace \$3,084 1007 Guard Rails - Repair \$3,084 2090 Water Lines - Repair \$8,077 \$186,137 2035 213 Sign Posts - Repaint \$1,588 390 Stone Veneer - Repairs \$31,764 403 Asphalt - Crack Seal \$19,664 808 Sign Posts - Install/Replace \$3,176 990 Fire Hydrants - Repair/Replace \$8,319 1007 Guard Rails - Repair \$3,176 2090 Water Lines - Repair \$8,319		402	Asphalt - Slurry Seal	\$67,553	
1007 Guard Rails - Repair \$3,084 2090 Water Lines - Repair \$8,077 \$186,137 2035 213 Sign Posts - Repaint \$1,588 390 Stone Veneer - Repairs \$31,764 403 Asphalt - Crack Seal \$19,664 808 Sign Posts - Install/Replace \$3,176 990 Fire Hydrants - Repair/Replace \$8,319 1007 Guard Rails - Repair \$3,176 2090 Water Lines - Repair \$8,319		403	Asphalt - Crack Seal	\$19,091	
2090 Water Lines - Repair \$8,077 \$186,137 2035 213 Sign Posts - Repaint \$1,588 390 Stone Veneer - Repairs \$31,764 403 Asphalt - Crack Seal \$19,664 808 Sign Posts - Install/Replace \$3,176 990 Fire Hydrants - Repair/Replace \$8,319 1007 Guard Rails - Repair \$3,176 2090 Water Lines - Repair \$8,319		808	Sign Posts - Install/Replace	\$3,084	
2035 213 Sign Posts - Repaint \$1,588 390 Stone Veneer - Repairs \$31,764 403 Asphalt - Crack Seal \$19,664 808 Sign Posts - Install/Replace \$3,176 990 Fire Hydrants - Repair/Replace \$8,319 1007 Guard Rails - Repair \$3,176 2090 Water Lines - Repair \$8,319		1007	Guard Rails - Repair	\$3,084	
390 Stone Veneer - Repairs \$31,764 403 Asphalt - Crack Seal \$19,664 808 Sign Posts - Install/Replace \$3,176 990 Fire Hydrants - Repair/Replace \$8,319 1007 Guard Rails - Repair \$3,176 2090 Water Lines - Repair \$8,319 \$76,008		2090	Water Lines - Repair	\$8,077	\$186,137
403 Asphalt - Crack Seal \$19,664 808 Sign Posts - Install/Replace \$3,176 990 Fire Hydrants - Repair/Replace \$8,319 1007 Guard Rails - Repair \$3,176 2090 Water Lines - Repair \$8,319 \$76,008	2035	213	Sign Posts - Repaint	\$1,588	
808 Sign Posts - Install/Replace \$3,176 990 Fire Hydrants - Repair/Replace \$8,319 1007 Guard Rails - Repair \$3,176 2090 Water Lines - Repair \$8,319 \$76,008		390	Stone Veneer - Repairs	\$31,764	
990 Fire Hydrants - Repair/Replace \$8,319 1007 Guard Rails - Repair \$3,176 2090 Water Lines - Repair \$8,319 \$76,008		403	Asphalt - Crack Seal	\$19,664	
990 Fire Hydrants - Repair/Replace \$8,319 1007 Guard Rails - Repair \$3,176 2090 Water Lines - Repair \$8,319 \$76,008		808	Sign Posts - Install/Replace	\$3,176	
1007 Guard Rails - Repair \$3,176 2090 Water Lines - Repair \$8,319 \$76,008		990	·		
2090 Water Lines - Repair \$8,319 \$76,008			·		
			·		\$76,008
	2036	213	Sign Posts - Repaint		

Year	Comp ID	Component Name	Projected Cost	Total Per Annum
	390	Stone Veneer - Repairs	\$32,717	
	401	Asphalt - Village Way - Major Rehab	\$56,087	
	402	Asphalt - 2018 - Slurry Seal	\$4,051	
	402	Asphalt - 2021 - Slurry Seal	\$56,087	
	403	Asphalt - Crack Seal	\$20,254	
	808	Sign Posts - Install/Replace	\$3,272	
	1007	Guard Rails - Repair	\$3,272	
	2090	Water Lines - Repair	\$8,569	\$185,943
2037	213	Sign Posts - Repaint	\$1,685	
	217	Transit Center - Repair/Repaint	\$5,616	
	390	Stone Veneer - Repairs	\$33,699	
	401	Asphalt - Ruby Hollow - Major Rehab	\$42,966	
	402	Asphalt - Slurry Seal	\$73,816	
	403	Asphalt - Crack Seal	\$20,861	
	808	Sign Posts - Install/Replace	\$3,370	
	1007	Guard Rails - Repair	\$3,370	
	2090	Water Lines - Repair	\$8,826	
	2302	Metal Bridge - Maintenance	\$17,652	\$211,861
2038	213	Sign Posts - Repaint	\$1,735	
	219	Wood Surfaces - Stain	\$59,503	
	390	Stone Veneer - Repairs	\$34,710	
	401	Asphalt - Hawkeye Place - Major Rehab	\$34,710	
	403	Asphalt - Crack Seal	\$21,487	
	808	Sign Posts - Install/Replace	\$3,471	
	990	Fire Hydrants - Repair/Replace	\$9,091	
	1007	Guard Rails - Repair	\$3,471	
	2090	Water Lines - Repair	\$9,091	\$177,268
2039	213	Sign Posts - Repaint	\$1,788	
	390	Stone Veneer - Repairs	\$35,751	
	401	Asphalt - Empire Club Drive - Major Rehab	\$182,160	
	401	Asphalt - Red Cloud Trail - Major Rehab	\$120,873	
	402	Asphalt - 2018 - Slurry Seal	\$4,426	
	402	Asphalt - 2021 - Slurry Seal	\$61,288	
	403	Asphalt - Crack Seal	\$22,132	
	808	Sign Posts - Install/Replace	\$3,575	
	1007	Guard Rails - Repair	\$3,575	
	2090	Water Lines - Repair	\$9,363	
	2302	Bridges Surfaces - Refurbish	\$255,365	\$700,296
2040	213	Sign Posts - Repaint	\$1,841	
	390	Stone Veneer - Repairs	\$36,824	
	401	Asphalt - Twisted Branch - Major Rehab	\$517,372	
	402	Asphalt - Slurry Seal	\$80,661	
	403	Asphalt - Crack Seal	\$22,796	
	808	Sign Posts - Install/Replace	\$3,682	
	903	Camera System - Replace	\$2,981	
	1007	Guard Rails - Repair	\$3,682	
	2090	Water Lines - Repair	\$9,644	\$679,484

Year	Comp ID	Component Name	Projected Cost	Total Per Annum
2041	213	Sign Posts - Repaint	\$1,896	
	390	Stone Veneer - Repairs	\$37,928	
	401	Asphalt - Banner Court - Major Rehab	\$28,898	
	403	Asphalt - Crack Seal	\$23,479	
	406	Curbing - Partial Replace	\$36,122	
	808	Sign Posts - Install/Replace	\$3,793	
	990	Fire Hydrants - Repair/Replace	\$9,934	
	1007	Guard Rails - Repair	\$3,793	
	1890	Retaining Walls - Repair	\$9,934	
	2090	Water Lines - Repair	\$9,934	
	2302	Metal Bridge - Maintenance	\$19,867	\$185,578
2042	213	Sign Posts - Repaint	\$1,953	
	219	Wood Surfaces - Stain	\$66,971	
	390	Stone Veneer - Repairs	\$39,066	
	402	Asphalt - 2018 - Slurry Seal	\$4,837	
	402	Asphalt - 2021 - Slurry Seal	\$66,971	
	403	Asphalt - Crack Seal	\$24,184	
	808	Sign Posts - Install/Replace	\$3,907	
	1007	Guard Rails - Repair	\$3,907	
	2090	Water Lines - Repair	\$10,232	\$222,026
2043	213	Sign Posts - Repaint	\$2,012	
	217	Transit Center - Repair/Repaint	\$6,706	
	390	Stone Veneer - Repairs	\$40,238	
	401	Asphalt - Northside Court - Major Rehab	\$35,448	
	402	Asphalt - Slurry Seal	\$88,141	
	403	Asphalt - Crack Seal	\$24,909	
	808	Sign Posts - Install/Replace	\$4,024	
	1007	Guard Rails - Repair	\$4,024	
	2090	Water Lines - Repair	\$10,539	\$216,041
2044	213	Sign Posts - Repaint	\$2,072	
	390	Stone Veneer - Repairs	\$41,445	
	403	Asphalt - Crack Seal	\$25,657	
	808	Sign Posts - Install/Replace	\$4,145	
	990	Fire Hydrants - Repair/Replace	\$10,855	
	1007	Guard Rails - Repair	\$4,145	
	2090	Water Lines - Repair	\$10,855	\$99,173
2045	213	Sign Posts - Repaint	\$2,134	
	390	Stone Veneer - Repairs	\$42,689	
	402	Asphalt - 2018 - Slurry Seal	\$5,285	
	402	Asphalt - 2021 - Slurry Seal	\$73,181	
	403	Asphalt - Crack Seal	\$26,426	
	801	Monument Signs - Refurbish	\$19,820	
	808	Sign Posts - Install/Replace	\$4,269	
	1007	Guard Rails - Repair	\$4,269	
	2090	Water Lines - Repair	\$11,180	
	2302	Metal Bridge - Maintenance	\$22,361	\$211,614
2046	213	Sign Posts - Repaint	\$2,198	

Year	Comp ID	Component Name	Projected Cost	Total Per Annum
-	219	Wood Surfaces - Stain	\$75,376	
	390	Stone Veneer - Repairs	\$43,969	
	402	Asphalt - Slurry Seal	\$96,314	
	403	Asphalt - Crack Seal	\$27,219	
	808	Sign Posts - Install/Replace	\$4,397	
	1007	Guard Rails - Repair	\$4,397	
	1604	Bridge & Pole Lights - Replace	\$361,177	
	2090	Water Lines - Repair	\$11,516	\$626,563
2047	213	Sign Posts - Repaint	\$2,264	
	390	Stone Veneer - Repairs	\$45,288	
	403	Asphalt - Crack Seal	\$28,036	
	808	Sign Posts - Install/Replace	\$4,529	
	990	Fire Hydrants - Repair/Replace	\$11,861	
	1007	Guard Rails - Repair	\$4,529	
	2090	Water Lines - Repair	\$11,861	\$108,369
2048	213	Sign Posts - Repaint	\$2,332	
	390	Stone Veneer - Repairs	\$46,647	
	401	Asphalt - Red Cloud Trail 2016 - Major Rehab	\$194,363	
	401	Asphalt - Silver Strike Trail - Major Rehab	\$121,671	
	402	Asphalt - 2018 - Slurry Seal	\$5,775	
	402	Asphalt - 2021 - Slurry Seal	\$79,966	
	403	Asphalt - Crack Seal	\$28,877	
	808	Sign Posts - Install/Replace	\$4,665	
	903	Camera System - Replace	\$3,776	
	1007	Guard Rails - Repair	\$4,665	
	2090	Water Lines - Repair	\$12,217	\$504,955
2049	213	Sign Posts - Repaint	\$2,402	_
	217	Transit Center - Repair/Repaint	\$8,008	
	390	Stone Veneer - Repairs	\$48,046	
	402	Asphalt - Slurry Seal	\$105,245	
	403	Asphalt - Crack Seal	\$29,743	
	808	Sign Posts - Install/Replace	\$4,805	
	1007	Guard Rails - Repair	\$4,805	
	2090	Water Lines - Repair	\$12,584	
	2302	Metal Bridge - Maintenance	\$25,167	\$240,804
2050	213	Sign Posts - Repaint	\$2,474	
	219	Wood Surfaces - Stain	\$84,836	
	390	Stone Veneer - Repairs	\$49,488	
	403	Asphalt - Crack Seal	\$30,635	
	808	Sign Posts - Install/Replace	\$4,949	
	990	Fire Hydrants - Repair/Replace	\$12,961	
	1007	Guard Rails - Repair	\$4,949	
	2090	Water Lines - Repair	\$12,961	\$203,254

Component Evaluation

Comp #: 107 Transit Center Roof - Replace





Location: Common Area

Quantity: Approx 340 Sq.ft.

Life Expectancy: 25 Remaining Life: 8

Best Cost: \$3,000

Estimate to replace

Worst Cost: \$5,000

Higher estimate

Source of Information: CSL Cost Database

Observations:

The roof is in good condition. We recommend funding to replace this component approximately every 25 - 35 years. Remaining life based on current age.

General Notes:



Comp #: 120 Transit Center Guttering - Repair/Replace





Location: Common Area

Quantity: Approx 30 Linear ft.

Life Expectancy: N/A Remaining Life:

Best Cost: \$0

Worst Cost: \$0

Source of Information:

Observations:

Due to the mimimal amount of, and cost of replacing this component, reserve funding is not appropriate. Repair and replace as necessary as an operating expense.





Comp #: Sign Posts - Repaint 213





Common Area Location:

Quantity: (52) Sign Posts

Life Expectancy: 1 Remaining Life: 0

Best Cost: \$1,000

Estimate to repaint

Worst Cost: \$1,100

Higher estimate

Source of Information: Research with Client

Observations:

Research with the client reveals this component is partially repainted every year.

General Notes:

Quantity description:

(18) - Pole Light Posts (24) - Road Sign Posts (10) - Street Sign Posts



Comp #: 217 Transit Center - Repair/Repaint





Location: Common Area

Quantity: (1) Transit Center

Life Expectancy: 6 Remaining Life: 4

Best Cost: \$3,400 Estimate to repair/repaint

Worst Cost: \$3,600

Higher estimate

Source of Information: Research with Client

Observations:

The painted wood siding surfaces are in fair condition. We recommend funding to repair/repaint this component approximately every 4 - 6 years. Remaining life based on current age and condition.





Comp #: 219 Wood Surfaces - Stain





Bridges, Monument Signs & Tunnel Location:

Quantity: See General Notes

Life Expectancy: 4 Remaining Life: 1

Best Cost: \$35,000

Estimate to stain

Worst Cost: \$37,000

Higher estimate

Source of Information: Research with Client

Observations:

Research with the client reveals this component is stained every four years. Remaining life based on current age.

General Notes:

Quantity description:

- (3) Monument Signs
- (4) Ski Bridge (1) Tunnel



Comp #: 390 Stone Veneer - Repairs





Location: Common Area

Quantity: Extensive Sq.ft.

Life Expectancy: 1 Remaining Life: 0

Best Cost: \$20,000

Estimate to repair


Worst Cost: \$22,000

Higher estimate

Source of Information: Research with Client

Observations:

Research with the client reveals this component is partially repaired every year.





Comp #: 401 Asphalt - Banner Court - Major Rehab





Location: Banner Court

Quantity: Approx 8,825 Sq.ft.

Life Expectancy: 16 Remaining Life: 4


Best Cost: \$14,000 Estimate for major rehab

Worst Cost: \$18,000

Higher estimate

Source of Information: CSL Cost Database

Observations:





Comp #: 401 Asphalt - Empire Club Drive - Major Rehab





Location: Empire Club Drive

Quantity: Approx 60,750 Sq.ft.

Life Expectancy: 16 Remaining Life: 18


Best Cost: \$92,000 Estimate for major rehab

Worst Cost: \$122,000

Higher estimate

Source of Information: CSL Cost Database

Observations:





Comp #: 401 Asphalt - Hawkeye Place - Major Rehab





Location: Hawkeye Place

Quantity: Approx 12,300 Sq.ft.

Life Expectancy: 16 Remaining Life: 1


Best Cost: \$19,000 Estimate for major rehab

Worst Cost: \$23,000

Higher estimate

Source of Information: CSL Cost Database

Observations:





Comp #: 401 Asphalt - Northside Court - Major Rehab





Location: Northside Court

Quantity: Approx 10,050 Sq.ft.

Life Expectancy: 16 Remaining Life: 6


Best Cost: \$16,000 Estimate for major rehab

Worst Cost: \$21,000

Higher estimate

Source of Information: CSL Cost Database

Observations:





Comp #: 401 Asphalt - Red Cloud Trail - Major Rehab





Location: Red Cloud Trail

Quantity: Approx 40,425 Sq.ft.

Life Expectancy: 16 Remaining Life: 2

Best Cost: \$61,000


Estimate for overlay

Worst Cost: \$81,000

Higher estimate

Source of Information: CSL Cost Database

Observations:





Comp #: 401 Asphalt - Red Cloud Trail 2016 - Major Rehab





Location: Red Cloud Trail

Quantity: Approx 50,000 Sq.ft.

Life Expectancy: 16 Remaining Life: 11


Best Cost: \$75,000 Estimate for major rehab

Worst Cost: \$100,000

Higher estimate

Source of Information: CSL Cost Database

Observations:





Comp #: 401 Asphalt - Ruby Hollow - Major Rehab





Location: Ruby Hollow

Quantity: Approx 15,300 Sq.ft.

Life Expectancy: 16 Remaining Life: 16

Best Cost: \$22,950


\$1.50/Sq.ft.; Estimate for major rehab

Worst Cost: \$30,600 \$2.00/Sq.ft.; Higher estimate

Source of Information: CSL Cost Database

Observations:

Research with the client reveals this component is scheduled to be replaced in 2021. We recommend funding for a major rehab of this component approximately every 16 - 20 years. Remaining life based on current age.





Comp #: 401 Asphalt - Silver Strike Trail - Major Rehab





Location: Silver Strike Trail

Quantity: Approx 31,300 Sq.ft.

Life Expectancy: 16 Remaining Life: 11

Best Cost: \$46,950


\$1.50/Sq.ft.; Estimate for major rehab

Worst Cost: \$62,600 \$2.00/Sq.ft.; Higher estimate

Source of Information: Research with Client

Observations:


The asphalt surfaces are in good condition. We recommend funding for a major rehab of this component approximately every 16 - 20 years. Remaining life based on current age.





Comp #: 401 Asphalt - Twisted Branch - Major Rehab





Location: Twisted Branch

Quantity: Approx 168,600 Sq.ft.

Life Expectancy: 16 Remaining Life: 3


Best Cost: \$252,900 \$1.50/Sq.ft.; Estimate for overlay

Worst Cost: \$337,200 \$2.00/Sq.ft.; Higher estimate

Source of Information: CSL Cost Database

Observations:

The asphalt surfaces are in good to fair condition. We recommend funding for a major rehab of this component approximately every 16 - 20 years. Remaining life based on current age.





Comp #: 401 Asphalt - Village Way - Major Rehab





Location: Village Way

Quantity: Approx 20,225 Sq.ft.

Life Expectancy: 16 Remaining Life: 15

Best Cost: \$31,000 Estimate for major rehab


Worst Cost: \$41,000

Higher estimate

Source of Information: CSL Cost Database

Observations:

The asphalt surfaces are in good to fair condition. We recommend funding for a major rehab of this component approximately every 16 - 20 years. Remaining life based on current age.





Comp #: 402 Asphalt - 2018 - Slurry Seal





Location: Hawkeye Place

Quantity: Approx 12,300 Sq.ft.

Life Expectancy: 3 Remaining Life: 0

Best Cost: \$2,500 Estimate for seal coat


Worst Cost: \$2,700

Higher estimate

Source of Information: CSL Cost Database

Observations:

The asphalt seal coat is in poor condition. We recommend funding to seal this component approximately every 3 - 5 years. Remaining life based on current condition.





Comp #: 402 Asphalt - 2021 - Slurry Seal





Location: Northside Court & Twisted Branch

Quantity: Approx 178,650 Sq.ft.

Life Expectancy: 3 Remaining Life: 0

Best Cost: \$34,000

Estimate for seal coat

Worst Cost: \$38,000

Higher estimate

Source of Information: CSL Cost Database

General Notes:

Quantity description:

10,050 Sq.ft. - Northside Court 168,600 Sq.ft. - Twisted Branch

178,650 Sq.ft. - Total

Observations:

The asphalt seal coat is in poor condition. We recommend funding to seal this component approximately every 3 - 5 years. Remaining life based on current condition.



Comp #: 402 Asphalt - Slurry Seal





Location: Community Streets

Quantity: Approx 226,825 Sq.ft.

Life Expectancy: 3 Remaining Life: 1

Best Cost: \$44,000

Estimate to seal coat

Worst Cost: \$48,000

Higher estimate

Source of Information: Research with Client

General Notes:

Quantity description:

8,825 Sq.ft. - Banner Court 60,750 Sq.ft. - Empire Club Drive 90,425 Sq.ft. - Red Cloud Trail 15,300 Sq.ft. - Ruby Hollow 31,300 Sq.ft. - Silver Strike 20,225 Sq.ft. - Village Way

226,825 Sq.ft. - Total

Observations:

The asphalt seal coat is in poor condition. We recommend funding to seal this component approximately every 3 - 5 years. Remaining life based on current condition.



Comp #: 403 Asphalt - Crack Seal





Location: Community Streets

Quantity: Approx 417,775 Sq.ft.

Life Expectancy: 1 Remaining Life: 0

Best Cost: \$12,000
Allowance for Crack Seal

Worst Cost: \$14,000

Higher Allowance

Source of Information: CSL Cost Database

General Notes:

Quantity description:

8,825 Sq.ft. - Banner Court 60,750 Sq.ft. - Empire Club Drive 12,300 Sq.ft. - Hawkeye Place 10,050 Sq.ft. - Northside Court 90,425 Sq.ft. - Red Cloud Trail 15,300 Sq.ft. - Ruby Hollow 31,300 Sq.ft. - Silver Strike 168,600 Sq.ft. - Twisted Branch 20,225 Sq.ft. - Village Way

417,775 Sq.ft. - Total

Observations:

Research with the client reveals this component is being sealed every year.



Comp #: 406 Curbing - Partial Replace





Location: Along Community Roads

Quantity: Approx 5,735 Linear ft.

Life Expectancy: 10 Remaining Life: 0

Best Cost: \$18,000 Estimate to patrially replace

Worst Cost: \$22,000

Higher estimate

Source of Information: CSL Cost Database

General Notes:

Quantity description:

5,735 Linear ft. - High Back Curbing

Observations:

Research with the client reveals plans to partially replace this component. We recommend funding to partially replace this component every 10 years. Remaining life based on current age.



Comp #: 490 Asphalt - Ruby Hollow - Replace





Location: Ruby Hollow

Quantity: Approx 15,300 Sq.ft.

Life Expectancy: 99 Remaining Life: 0

Best Cost: \$35,000

Estimate to replace


Worst Cost: \$45,000

Higher estimate

Source of Information: CSL Cost Database

Observations:

Research with the client reveals this component is scheduled to be replaced in 2021. This is a one-time project



Comp #: 801 Monument Signs - Refurbish





Location: Entrances to Community

Quantity: (3) Signs

Life Expectancy: 20 Remaining Life: 4

Best Cost: \$9,000 Estimate to refurbish


Worst Cost: \$10,500

Higher estimate

Source of Information: CSL Cost Database

Observations:

The monument signs are in good to fair condition. We recommend refurbishing this component approximately every 15 - 20 years. Remaining life is based on current age and condition.





Comp #: Sign Posts - Install/Replace 808





Througout Community Location:

Quantity: (52) Sign Posts

Life Expectancy: 1 Remaining Life: 0

Best Cost: \$2,000

Estimate to replace

Worst Cost: \$2,200

Higher estimate

Source of Information: Research with Client

Observations:

Research with the client reveals this component is addressed yearly as needed.

General Notes:

Quantity description:

(18) - Pole Light Posts (24) - Road Sign Posts (10) - Street Sign Posts



Comp #: 903 Camera System - Replace





Location: Corner of Red Cloud Trail & Twisted Branc General Notes:

Quantity: (1) System

Life Expectancy: 8 Remaining Life: 3

Best Cost: \$1,600

Estimate to replace

Worst Cost: \$1,800

Higher estimate

Source of Information: Research with Client

Observations:

The security camera system is in working condition. We recommend funding to replace this component approximately every 8 - 10 years. Remaining life based on current age.



Comp #: 990 Fire Hydrants - Repair/Replace





Location: Common Area

Quantity: (1) System

Life Expectancy: 3 Remaining Life: 2

Best Cost: \$5,000 Estimate to repair/replace


Worst Cost: \$6,000

Higher estimate

Source of Information: CSL Cost Database

Observations:

The fire hydrant system is in working condition. We recommend funding to make repairs/replacements to this component approximately every 3 - 5 years. Remaining life based on current age.





Comp #: 1007 Guard Rails - Repair





Location: Adjacent to Community Streets

Quantity: Approx 4,645 Linear ft.

Life Expectancy: 1 Remaining Life: 0

Best Cost: \$2,000

Estimate to repair

Worst Cost: \$2,200

Higher estimate

Source of Information: Research with Client

Observations:

Research with the client reveals this component is inspected and repaired yearly.

General Notes:

Quantity description:

345 Linear ft. - Village Way 4,300 Linear ft. - Red Cloud

4,645 Linear ft. - Total



Comp #: 1604 Bridge & Pole Lights - Replace





Location: Throughout Community

Quantity: (23) Fixtures

Life Expectancy: 20 Remaining Life: 5

Best Cost: \$161,000

Estimate to replace

Worst Cost: \$184,000

Higher estimate

Source of Information: Research with Client

Observations:

The bridge and pole lights are in good condition. Although this component may reach an extended life, we recommend funding to completely replace this component approximately every 15 - 20 years. Remaining life based on current age and condition.

General Notes:

Quantity description:

(4) - Bridge Light (19) - Pole Light

(23) - Total Lights



Comp #: 1890 Retaining Walls - Repair





Location: Adjacent to Community Roads

Quantity: Extensive Sq.ft.

Life Expectancy: 10 Remaining Life: 0

Best Cost: \$5,000

Allowance to repair


Worst Cost: \$6,000

Higher allowance

Source of Information: Research with Client

Observations:

The retaining walls are generally in good condition. Although this component has an extended useful life, we are funding to make minor repairs every 10 years. Remaining life based on current age.



Comp #: 2090 Water Lines - Repair

Picture Unava	ilable	Picture Unavailable
Location:	Common Area	General Notes:
Quantity:	Extensive Linear ft.	
Life Expectancy:	1 Remaining Life: 0	
Best Cost:	\$5,000	
Allowance to repa		
Worst Cost:	\$6,000	
Higher allowance		
Source of Information: Research with Client		

Observations:

The client has requested we add a yearly component for water line repair.



Comp #: 2302 Bridges Surfaces - Refurbish





Location: Throughout Community

Quantity: (5) Structures

Life Expectancy: 20 Remaining Life: 18

Best Cost: \$145,000

Estimate to refurbish

Worst Cost: \$155,000

Higher estimate

Source of Information: Research with Client

Observations:

The bridge surfaces are generally in good condition. We recommend funding an allowance to refurbish this component approximately every 20 years. Remaining life based on current condition.

General Notes:

Quantity description:

(4) - Ski Bridge

(1) - Tunnel



Comp #: 2302 Metal Bridge - Maintenance





Location: Common Area

Quantity: (1) Bridge

Life Expectancy: 4 Remaining Life: 0

Best Cost: \$10,000

Estimate the maintain


Worst Cost: \$12,000

Higher estimate

Source of Information: Research with Client

Observations:

Research with the client reveals the metal bridge is in good condition. Regular maintenance is performed annually as an operating expense. More significant maintenance is performed approximately every 4 years.





Glossary of Commonly Used Words And Phrases

(Provided by the National Reserve Study Standards of the Community Associations Institute)

Cash Flow Method – A method of developing a reserve funding plan where contributions to the reserve fund are designed to offset the variable annual expenditures from the reserve fund. Different reserve funding plans are tested against the anticipated schedule of reserve expenses until the desired funding goal is achieved.

Component – Also referred to as an "Asset." Individual line items in the Reserve Study developed or updated in the physical analysis. These elements form the building blocks for the Reserve Study. Components typically are: 1) Association responsibility, 2) with limited useful life expectancies, 3) have predictable remaining life expectancies, 4) above a minimum threshold cost, and 5) required by local codes.

Component Full Funding – When the actual (or projected) cumulative reserve balance for all components is equal to the fully funded balance.

Component Inventory – The task of selecting and quantifying reserve components. This task can be accomplished through on-site visual observations, review of association design and organizational documents, a review of established association precedents, and discussion with appropriate association representatives.

Deficit – An actual (or projected reserve balance), which is less than the fully funded balance.

Effective Age – The difference between useful life and remaining useful life (UL - RUL).

Financial Analysis – The portion of the Reserve Study where current status of the reserves (measured as cash or percent funded) and a recommended reserve contribution rate (reserve funding plan) are derived, and the projected reserve income and expenses over time is presented. The financial analysis is one of the two parts of the Reserve Study.

Fully Funded Balance – An indicator against which the actual (or projected) reserve balance can be compared. The reserve balance that is in direct proportion to the fraction of life "used up" of the current repair or replacement cost of a reserve component. This number is calculated for each component, and then summed together for an association total.

FFB = Current Cost * Effective Age / Useful Life

Fund Status – The status of the reserve fund as compared to an established benchmark, such as percent funded.

Funding Goals – Independent of calculation methodology utilized, the following represent the basic categories of funding plan goals:

- Baseline Funding: Establishing a reserve-funding goal of keeping the reserve balance above zero.
- Component Full Funding: Setting a reserve funding goal of attaining and maintaining cumulative reserves at or near 100% funded.
- *Threshold Funding*: Establishing a reserve funding goal of keeping the reserve balance above a specified dollar or percent funded amount.

Funding Plan – An association's plan to provide income to a reserve fund to offset anticipated expenditures from that fund.



Funding Principles -

- Sufficient funds when required
- Stable contributions through the year
- Evenly distributed contributions over the years
- Fiscally responsible

GSF - Gross Square Feet

Life and Valuation Estimates – The task of estimating useful life, remaining useful life, and repair or replacement costs for the reserve components.

LF - Linear Feet

Percent Funded – The ratio, at a particular point in time (typically the beginning of the fiscal year), of the actual (or projected) reserve balance to the ideal fund balance, expressed as a percentage.

Physical Analysis – The portion of the Reserve Study where the component evaluation, condition assessment, and life and valuation estimate tasks are performed. This represents one of the two parts of the Reserve Study.

Remaining Useful Life (RUL) – Also referred to as "remaining life" (RL). The estimated time, in years, that a reserve component can be expected to continue to serve its intended function. Projects anticipated to occur in the current fiscal year have a "0" remaining useful life.

Replacement Cost – The cost of replacing, repairing, or restoring a reserve component to its original functional condition. The current replacement cost would be the cost to replace, repair, or restore the component during that particular year.

Reserve Balance – Actual or projected funds as of a particular point in time (typically the beginning of the fiscal year) that the association has identified for use to defray the future repair or replacement of those major components that the association is obligated to maintain. Also known as "reserves," "reserve accounts," or "cash reserves." In this report the reserve balance is based upon information provided and is not audited.

Reserve Study – A budget-planning tool, which identifies the current status of the reserve fund and a stable and equitable funding plan to offset the anticipated future major common area expenditures. The Reserve Study consists of two parts: The Physical Analysis and the Financial Analysis.

Special Assessment – An assessment levied on the members of an association in addition to regular assessments. Governing documents or local statutes often regulate special assessments.

Surplus – An actual (or projected) reserve balance that is greater than the fully funded balance.

Useful Life (UL) – Also known as "life expectancy." The estimated time, in years, that a reserve component can be expected to serve its intended function if properly constructed and maintained in its present application of installation.

