


Free seam displacement: 717 seams before the fix, 715 after

faulty corrected



Every seam over 100 m disappears under the corrected datum: 189 of them, leaving none.