


GARAGE REPLACEMENT / DESIGN REVIEW

Existing building / floor plan



EXISTING GARAGE / DEMOLITION

Building footprint: 6800 x 3500.
Roof length annotation: 7200.
Approach: 1200 beyond entrance.

Door width is unresolved.
Dashed entrance is schematic only.
1100 source label may describe one leaf.

Side elevations are partly cropped.
Additional openings are not established.
100 mm wall thickness is schematic.

Preliminary - reference dimensions, subject to verification

A3 landscape | 1:50 at 100% print | Dimensions mm | Do not scale JPEG references


Site/address and compass orientation unconfirmed | 14 Sep 2026 | Revision P02



GARAGE REPLACEMENT / DESIGN REVIEW

Existing building / front elevation

All heights relative to provisional ground datum 0.



Door width/position schematic; verify 1100 label.
Door height 2000 from reference.

Photo S5: weathered timber and blue-green doors; roof covering still to be verified.
S2 labels roof corrugated; photograph appears tiled - confirm covering.
Front doors schematic; rear reference indicates no openings.

Preliminary - reference dimensions, subject to verification

A3 landscape | 1:50 at 100% print | Dimensions mm | Do not scale JPEG references

Site/address and compass orientation unconfirmed | 14 Sep 2026 | Revision P02



GARAGE REPLACEMENT / DESIGN REVIEW

Existing building / rear elevation

All heights relative to provisional ground datum 0.




Photo S5: weathered timber and blue-green doors; roof covering still to be verified.
S2 labels roof corrugated; photograph appears tiled - confirm covering.
Front doors schematic; rear reference indicates no openings.

Preliminary - reference dimensions, subject to verification

A3 landscape | 1:50 at 100% print | Dimensions mm | Do not scale JPEG references

Site/address and compass orientation unconfirmed | 14 Sep 2026 | Revision P02



GARAGE REPLACEMENT / DESIGN REVIEW

Existing building / left elevation

All heights relative to provisional ground datum 0.




Photo S5: weathered timber and blue-green doors; roof covering still to be verified.
S2 labels roof corrugated; photograph appears tiled - confirm covering.
Side openings unresolved where original image is cropped.

Preliminary - reference dimensions, subject to verification

A3 landscape | 1:50 at 100% print | Dimensions mm | Do not scale JPEG references

Site/address and compass orientation unconfirmed | 14 Sep 2026 | Revision P02



GARAGE REPLACEMENT / DESIGN REVIEW

Existing building / right elevation

All heights relative to provisional ground datum 0.




Photo S5: weathered timber and blue-green doors; roof covering still to be verified.
S2 labels roof corrugated; photograph appears tiled - confirm covering.
Side openings unresolved where original image is cropped.

Preliminary - reference dimensions, subject to verification

A3 landscape | 1:50 at 100% print | Dimensions mm | Do not scale JPEG references


Site/address and compass orientation unconfirmed | 14 Sep 2026 | Revision P02



GARAGE REPLACEMENT / DESIGN REVIEW

Existing building / schematic roof section

Geometric section | pitch 42.44 deg



DATUM / GEOMETRY NOTES

Ground = provisional 0.

Eaves = roof surface at wall line.

Ridge = highest roof surface.

No roof build-up designed.

No foundations shown.

Section is geometric, not structural.

Verify heights and ground levels.

Reference roof length 7200 versus wall length 6800.

Model assumes 200 mm overhang at each end; distribution unverified.

Eave overhang 100 mm is a visual assumption.

Section cuts across 3500 width; length/approach shown separately on plan.

Preliminary - reference dimensions, subject to verification

A3 landscape | 1:50 at 100% print | Dimensions mm | Do not scale JPEG references

Site/address and compass orientation unconfirmed | 14 Sep 2026 | Revision P02

