Stewardship for McClenny Acres I and II

Lead Steward: Andrew


2023-12-18

Boundary Issues

Channel Issues

OBJECTID	Year	Subtype	Issue	Resolved
550	2021	Channel Stability/Erosion	SlumpingSettling	No
551	2021	Channel Stability/Erosion	SlumpingSettling	No


Channel Issues (lines)



Vegetation Issues

OBJECTID	Year	Issue	Description	Resolved
1088	2023	Low Stem Vigor/Height		No
1164	2023	Low Stem Density		No
830	2022	Bare Areas and Low Stem Density	standing water	No
831	2022	Bare Areas and Low Stem Density	standing water	No
832	2022	Bare Areas and Low Stem Density	standing water	No


Vegetation Issues (polygons)




Weed Issues

OBJECTID	Year	Species1	Species2	Issue	Treatment	Method	TreatDate	Resolved
1535	2023	Climbing Hempvine						No
827	2022	Cattail		Cattails	Cattail treatment (cut stump on	Cut Stump	06/2022	No
826	2022	Cattail		Cattails	western part, spray on central section) Weedeat Cattails	Mow	07/2022	No
					Weedeat Cattails	MOW	07/2022	
828	2022	Cattail		Cattails				No
829	2022	Cattail		Cattails				No
881	2022	Cattail		Cattails				No
882	2022	Cattail		Cattails				No
883	2022	Cattail		Cattail				No
884	2022	Cattail		Cattail				No
885	2022	Cattail		Cattail				No
347	2021	Chinese Privet	Tree Of Heaven	7 Acres of Privet	Cut Stump and Foliar Spray	Cut Stump	03/2023	No


Weed Issues – Climbing Hempvine



Weed Issues - Cattail




Weed Issues - Chinese Privet



Miscellaneous Issues

OBJECTID	Year	Subtype	Description	LocationOrFeature	Resolved
1349	2023	Misc			No
1536	2023	Beaver Dam			No
541	2022	Misc	Wetland outlet draining to UT1	Bank	No

Miscellaneous - Beaver Dam



Miscellaneous Issues

