Stewardship for Rosewood


Lead Steward: Hanna

2023-12-18

Boundary Issues

OBJECTID	Year	Issue	Description	Resolved
1062	2023	Other	Neighbors using CE as backyard/driveway	Yes


Boundary Issues (polygons)



Channel Issues

OBJECTID	Year	Subtype	Issue	Description	Resolved
970	2023	Channel Stability/Erosion	ErosionScour	Bank eroding, needs a couple live stakes	No
971	2023	Channel Stability/Erosion	ErosionScour	Eroding bank, needs 5 live stakes	No


Channel Issues (lines)



Vegetation Issues

OBJECTID	Year	Issue	Description	Resolved
1242	2023	Low Stem Density	Supplemental planting, 3 trees	No
1243	2023	Low Stem Density	Supplemental planting, 12 trees	No
1244	2023	Low Stem Density	Supplemental planting, 30 trees shade/dry tolerant	No
1284	2023	Bare Areas	Cover crop/soil amendment. Sandy!	No


Vegetation Issues (polygons)




Weed Issues

OBJECTID	Year	Species1	Species2	Issue	Resolved
1000	2023	Chinaberry		Treat with basal bark	No
1365	2023	Climbing Hempvine	Callery Pear	Keep an eye on weeds	No
1001	2023	Multiflora Rose	Japanese Honeysuckle	Invasives on bank of ditch	No
969	2023			Cattail in ditch	No
1138	2023			Elephant ears in ditch	No
1139	2023			Elephant ears in ditch	No


Weed Issues - Chinaberry




Weed Issues – Climbing Hempvine



Weed Issues - Multiflora Rose



Weed Issues – NA



Miscellaneous Issues

OBJECTID	Year	Subtype	Description	LocationOrFeature	Resolved
972	2023	Misc	Grading both sides of bank		No
973	2023	Misc	Grading both sides of bank		No
974	2023	Misc	Grading both sides of bank		No
1013	2023	Misc	Trash/old plastic culvert among trees	Floodplain	No
1014	2023	Misc	Rock pile		No
1015	2023	Misc	Large woody debris pile		No

Miscellaneous Issues

