Stewardship for Grantham Branch


Lead Steward: Neil

2023-12-18

Boundary Issues

OBJECTID	Year	Resolved
510	2021	Yes

Boundary Issues (lines)




Channel Issues

Vegetation Issues

OBJECTID	Year	Issue	Description	Treatment	TreatDate	Resolved
924	2022	Low Stem Vigor/Height		Tree boosters applied	05/2023	No
924	2022	Low Stem Vigor/Height		Tree boosters applied	08/2023	No
908	2022	Low Stem Vigor/Height and Density	Low density and diversity.			No
909	2022	Low Stem Vigor/Height and Density	P2 cut area looks good on ground cover now but sparse in tree density.			No

Vegetation Issues (polygons)






Weed Issues

OBJECTID	Year	Species1	Issue	Resolved
754	2022	Marsh Dewflower	Murdannia locally very dense in areas of direct sunshine.	No

Weed Issues - Marsh Dewflower



Miscellaneous Issues

OBJECTID	Year	Subtype	Description	LocationOrFeature	Resolved
1407	2023	Misc	Brush, leaf litter burned, some trees cleared		No
753	2022	Misc	Is sedimentation in pools on T1 an issue? No flow but channel bottom to TOB is maybe 6"	In-Stream	No

Miscellaneous Issues

