# Stewardship for Wyant


Lead Steward: Emily

2023-12-18

### Boundary Issues

OBJECTID	Year	Issue	Description	Treatment	TreatDate	Resolved
654	2022	Other	Off-site gullies inputting sediment into CE	Additional sign and posts installed (need insulators and another sign on one post)	01/2022	No
654	2022	Other	Off-site gullies inputting sediment into CE	3 coir logs installed along boundary line	04/2023	No
553	2021	Herbicide	Herbicide drift			No
554	2021	Herbicide	Herbicide drift			No


## Boundary Issues (lines)




### Channel Issues

OBJECTID	Year	Subtype	Issue	Description	Treatment	${\bf TreatDate}$	Resolved
946	2023	Channel Stability/Erosion	ErosionScour		Machine repair	06/2023	Yes
739	2022	Channel Stability/Erosion	ErosionScour				No
806	2022	Channel Stability/Erosion	AggradationDeposition				No
898	2022	Needs Livestakes					No
919	2022	Needs Livestakes					No
920	2022	Needs Livestakes					No
752	2022	Failed Structure	Piping	Piping under log			No
829	2022	Failed Structure		Repair both banks where sill is tied in.			No
830	2022	Failed Structure					No
831	2022	Failed Structure					No
655	2021	Needs Livestakes					No
656	2021	Channel Stability/Erosion	AggradationDeposition				No
657	2021	Channel Stability/Erosion		Gully from farm road by gate			No
320	2021	Failed Structure	Piping	Piping around log sill where keyed into bank			No

## Channel Issues (points)




## Channel Issues (lines)



### Vegetation Issues

OBJECTID	Year	Issue	Description	Treatment	TreatDate	Resolved
586	2023	Low Stem Density	Replanting 2022 and 2023			Yes
587	2023	Low Stem Density	Replanting 2022 and 2023			Yes
590	2023	Low Stem Density	Replanting 2022 and 2023			Yes
555	2021	Bare Areas	Bare area and gullies (wet area)	Gullies smoothed, seeded, strawed, matted. Dead logs placed at top to deflect water.	04/2022	Yes
444	2021	Bare Areas	Bare areas filling in			No
447	2021	Bare Areas	Bare areas healing			No
552	2021	Bare Areas	Very sandy			No
553	2021	Bare Areas				No
556	2021	Bare Areas and Low Stem Density	Slightly bare, rocky, and very wet. Seed heavy.			No


## Vegetation Issues (polygons)




#### Weed Issues

OBJECTID	Year	Species1	Species2	Issue	Treatment	Method	${\bf TreatDate}$	Resolved
842	2023	Cattail						No
1093	2023				5 pct glyphosate plus surfactant. Need to follow-up.	Backpack Spray	07/2023	No
843	2022	Cattail		Cattails				No
557	2022	Cattail						No
558	2022	Cattail						No
578	2022	Cattail						No
827	2022	Cattail						No
828	2022	Cattail						No
832	2022	Japanese Honeysuckle						No
785	2022	Morning Glory						No
561	2022	Multiflora Rose						No
906	2022	Tree Of Heaven						No
805	2022			Most veg. not rooted in stream	In stream veg spray	Backpack Spray	07/2022	No
805	2022			Most veg. not rooted in stream	5 pct glyphosate plus surfactant. Need to finish. Hard to find channel. Most veg not rooted in stream.	Backpack Spray	07/2023	No
446	2021	Chinese Privet						No
551	2021	Chinese Privet	Multiflora Rose					No
554	2021	Chinese Privet						No
167	2021	Chinese Privet						No
319	2021	Chinese Privet	Japanese Honeysuckle					No
1096	2021			Veg in riffles.	5 pct glyphosate instream veg. treatment		07/2023	No
560	2021				In stream veg spray		07/2022	No
560	2021				5 pct glyphosate instream veg. treatment		08/2023	No
1094	2021			Veg in riffles.	5 pct glyphosate instream treatment		07/2023	No
1095	2021			Veg in riffles.	5 pct glyphosate instream veg. treatment		07/2023	No


### Weed Issues - Cattail




### Weed Issues – NA




## Weed Issues – Japanese Honeysuckle




Weed Issues – Morning Glory




Weed Issues - Multiflora Rose



#### Weed Issues – Tree Of Heaven




### Weed Issues – Chinese Privet



#### Miscellaneous Issues

OBJECTID	Year	Subtype	Description	LocationOrFeature	Treatment	${\bf TreatDate}$	Resolved
947	2023	Beaver Dam			Dam removed by trappers	11/2023	Yes
1681	2023	Beaver Dam			Dam removed by trappers	11/2023	No
1680	2023	Beaver Dam			Dam removed by trappers	11/2023	No
948	2023	Beaver Dam			Dam removed by trappers	11/2023	No
1459	2023	Beaver Dam			Dam removed by trappers	11/2023	No
1169	2023	Beaver Dam			Trapped 2 beaver	07/2023	No
1679	2023	Beaver Dam			Dam removed by trappers	11/2023	No
1678	2023	Beaver Dam			Dam removed by trappers	11/2023	No
1347	2023	Misc	Photo point	Floodplain			No
1348	2023	Misc	Photo description	Floodplain			No
1357	2023	Misc	Cattail photo point				No
1361	2023	Misc	Cattail photo point				No
1362	2023	Misc	Cattail photo point				No
1472	2023	Beaver Dam					No
1819	2023	Misc	Remove tposts and wire	Floodplain			No
1820	2023	Beaver Dam					No
1821	2023	Misc	Remove fence				No
184	2022	Beaver Dam					Yes
577	2022	Beaver Dam					Yes
165	2021	Beaver Dam			Staff raked dam out	09/2021	Yes

### Miscellaneous - Beaver Dam



#### Miscellaneous Issues

