

小磨坊斗六廠辦更新工程



We protect and
beautify the world™
世界塗料領導品牌



 **Seigneurie** 申纽丽漆

廠房更新前



現況評估

ALC版


- 接縫處滲漏水
- 鋼筋鏽蝕裸露
- 防水漆處理無效



建議工法

PPG彈性佩能漆+節能板工法

隔熱漆+節能板 雙倍隔熱效果更佳



SGS
材料暨工程實驗室-台中

試驗報告



報告編號: TV-23-02752

頁數: 1 OF 1

報告日期: 112年07月31日

騰輝企業有限公司

產品名稱: PPG 中紐麗-彈性佩能漆

送驗廠商: 騰輝企業有限公司

收件日期: 112年07月17日

試驗日期: 112年07月17日~112年07月31日

備註:

1.以上資料(會驗廠商、試驗方法、試驗數量、收件日期及試驗日期除外)及

下述報告內容標示#處係由顧客提供

2.除非另有說明,此報告結果僅對測試之樣品負責

未經本公司事先書面同意,此報告不可部分複製

試驗結果:

試驗項目	試驗方法	試驗結果	
		No.1	No.2
熱傳導係數(W/m·K)	CNS 7332: 2014	0.0450	0.0486

註: 1.本試驗報告熱傳導係數試驗委託SGS材料暨工程實驗室-高雄執行(報告編號:KV-23-07152)

2.樣品描述:塗料複合板材

3.導熱係數試驗條件如下:

試片類型:板狀試片

試片厚度(mm): 1.26.94; 2.37.64(量測值)

養護條件: (23±1)°C, (50±10)% R.H.至恆重

養護試片密度(kg/m³): 1.666.0; 2.469.8

養護期間質量改變(g): 1.0; 2.0

量測過程之質量變化(g): 1.0; 2.0

量測過程之厚度變化(mm): 1.0; 2.0

量測過程之體積變化(cm³): 1.0; 2.0

量測過程之平均溫差(°C): 1.20; 2.20

平均溫度(°C): 1.23.01; 2.23.01

通過試片之熱流率密度(W/m²): 1.33.40; 2.25.82

儀器類型:單試片水平型,熱而在試片下方

試驗時環境溫度: (23±2)°C, (50±10)% R.H.

前次熱流計查驗日期: 2023年5月12日

標準片: NIST 1450e (驗證日期 2020年4月28日)

-----oOo-----

本報告若有提供規範值時,該規範值僅供參考,合格之判定以委託單位實際要求為準。

報告簽署人

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <http://www.sgs.com.tw/Terms-and-Conditions> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <http://www.sgs.com.tw/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained herein reflects the Company's findings at the time of its issuance only and within the limits of Client's instructions. If any, the Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this report refer only to the sample(s) tested.

SGS Taiwan Ltd.
台灣檢驗科技股份有限公司

No. 9, 14th Rd, Taichung Industrial Park, Taichung 407271, Taiwan / 407271
t (886-4) 2358-1515

f (886-4) 2358-2557
www.sgs.com.tw


Member of SGS Group

TWD8137860

4004

建議工法

節能板施工圖



規劃設計

3D渲染圖



規劃設計

3D渲染圖



完工照片

現場拍攝



完工照片

現場拍攝




紀錄照片

開工拜拜



紀錄照片


鷹架



紀錄照片


外牆檢測敲除標示

小磨坊斗六廠外牆一期工程-辦公棟外牆檢測敲除修補




紀錄照片

外牆檢測.清洗



紀錄照片

外牆敲除.防鏽.修補



紀錄照片

外牆窗框砂利康割除



紀錄照片

外牆節能版施工



放樣



節能版安裝




挖孔




網片固定

紀錄照片

外牆節能版施工



節能版上泥



抗拉玻纖網安裝



粉光完成

紀錄照片

外牆防汙滴水條施工



放樣



安裝



完成

紀錄照片

PPG彈性佩能漆(隔熱漆)外牆施工



多功能封孔底漆



鑿面底材



PPG彈性佩能漆

施工前後對比照



Before



After

歡迎賜教

Thank You

Q&A



We protect and
beautify the world™

世界塗料領導品牌

 **Seigneurie**® 申紐丽漆



騰輝企業有限公司

電話: 04-26872899 傳真: 04-26864726

地址: 台中市大甲區興安路321巷102號