



Change Assembly Superbolts Hoist Pedestal - CAT 7495

Maintenance and
Repair

Application

Component Life
Management

Component
Renewal (CRC)

MARC
Management

Change Assembly Superbolts Hoist Pedestal - CAT 7495.....	1
1.0 Introduction.....	2
2.0 Best Practice Description.....	4
3.0 Implementation Steps.....	5
4.0 Benefits.....	6
5.0 Resources Required.....	6
6.0 Supporting Attachments / References.....	6
7.0 Related Best Practices.....	6
8.0 Acknowledgements.....	6

DISCLAIMER: The information and potential benefits included in this document are based upon information provided by one or more Cat® dealers, and such dealer(s) opinion of “Best Practices.” Caterpillar makes no representation or warranty about the information contained in this document or the products referenced herein. Caterpillar welcomes additional “Best Practice” recommendations from our dealer network.

February 2023
1.04-230203-1

1.0 Introduction

The models “D” and “E” super bolts that are mounted on the left hoist drum pedestal and rear lugs of the gearcase base after the completion of gearcase assembly become inaccessible for torque checking in maintenance.

Sotreq presented an option for mounting super bolts inversely to CAT that made the super bolts accessible for torque checking without removing the hoist gearcase. This solution was approved and implemented in a machine assembly in Brazil.



Figure 1: Machine 7495

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Change Assembly Superbolts Hoist Pedestal CAT 7495	DATE 2/3/2023	CHG NO 00	NUMBER 1.04-230203-1




Figure 2: Location of super bolts of hoist pedestal

Below is the identification (inside the red rectangles) of the screws that had the assembly in reverse arrangement.




Figure 3: Screws arrangement "C" hoist pedestal

The screws arrangement "C" was kept according to the drawing orientation, even being covered by the reducer, as these have super bolts on both sides and would not bring the advantage of the models mentioned above.

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Change Assembly Superbolts Hoist Pedestal CAT 7495		DATE 2/3/2023	CHG NO 00
			NUMBER 1.04-230203-1

2.0 Best Practice Description

The purpose of this Best Practice is to change the mounting orientation of the hoist pedestal hardware fixture shown in the drawings S006762 and S006970 to facilitates access for the preventative maintenance team performing torque verification on the ERS 7495 hoist pedestal super bolts. This results in less maintenance and inspection time and consequently less overall downtime.



Figure 4: Rear bearing of the reductor hoist



Figure 5: LE pedestal internal screws



Figure 5: LE pedestal external screws

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Change Assembly Superbolts Hoist Pedestal CAT 7495	DATE	CHG NO	NUMBER
	2/3/2023	00	1.04-230203-1




Figure 6: LE pedestal




Figure 7: Super bolts detail

The inversion of the mounting arrangement in the drawings cited was carried out with a total of 12 screws model “D” and 2 screws model “E”.

3.0 Implementation Steps

To implement this best practice, follow the steps below:

1. Assemble the super bolts **PN 443-2362 model “D”** and **PN 467-0893 model “E”** in the position shown in this BP during the equipment assembly process or intervention to replace the super bolts.
2. At the time of installation, use suitable torque equipment and technicians with proper confined space training.

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Change Assembly Superbolts Hoist Pedestal CAT 7495	DATE 2/3/2023	CHG NO 00	NUMBER 1.04-230203-1

4.0 Benefits

- Facilitates the visual inspection process during maintenance
- Improved accessibility for maintenance
- Reduce the labor time to complete torque maintenance by 40%

5.0 Resources References

- Tools
- Super Bolts - PN 443-2362 model "D" and PN 467-0893 model "E"

6.0 Supporting Attachments / References

Figure 03-

<https://sis2.cat.com/?ts=1638882519740#/detail?keyword=82637920&serialNumber=ER6&ieSystemControlNumber=NIS000733536&productStructureId=00001655&tab=parts>

7.0 Related Best Practices

N/A

8.0 Acknowledgements

Anderson Lima
Expanded Mining Products
anderson.lima@sotreq.com.br
Sotreq S/A

Webert Lopes
Expanded Mining Products
webert.lopes@sotreq.com.br
Sotreq S/A

Thiago Rezende
Expanded Mining Products
thiago.rezende@sotreq.com.br
Sotreq S/A

Thiago Dillon
Expanded Mining Products
thiago.dillon@sotreq.com.br
Sotreq S/A

Josian Araújo
Expanded Mining Products
josian.araujo@sotreq.com.br
Sotreq S/A

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Change Assembly Superbolts Hoist Pedestal CAT 7495	DATE 2/3/2023	CHG NO 00	NUMBER 1.04-230203-1